

ROURKELA (R&B) DIVISION.

RESIDENTIAL

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Industries	a) U.G.I.E. Staff Qrs. 5R = 1 No.	Municipality	S.S.	1964	254	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	b) do 4R = 4 nos.	Municipality	D.S	1964	624	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	c) do 2RB = 12 nos.	Municipality	T.S.	1964	529	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	d) -do- 3R = 18 nos.	Municipality	T.S.	1964	1249	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	e) -do- 2R = 24 nos.	Municipality	T.S.	1964	1209	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	f) -do- F type = 13 nos.	Municipality	T.S.	1961	1825	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	a) ITI staff Qrs. 4R = 1 no.	Municipality	S.S	1961	155	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	b) -do- 2RB = 11 nos.	Municipality	S.S.	1961	572	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	c) -do- 2RA = 22 nos.	Municipality	S.S	1961	1721	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	d) -do- 2R = 12 nos.	Municipality	S.S.	1961	662	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	e) -do- F type = 12 nos. (3 block)	Municipality	D.S	1982	484	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	a) SKDAV Poly.tech. Womens staff Qrs. F-type	Municipality	S.S.	1968	2289	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	b) -do- Peon qrs. 2 nos.	Municipality	S.S	1971	41	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Industries	c) -do- 2RA = 1 no.	Municipality	S.S	1961	86	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	d) -do- E/type = 6 nos.	Municipality	T.S.	1988	366	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	e) -do- 5R Principal Qrs. = 5 nos.	Municipality	S.S.	1982	254	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	f) -do- 4 Nos. D/type Qrs.= 4nos.	Municipality	D.S	1990	365	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	a) L.O. Qrs. At Uditnagar.	Municipality	S.S	1956	322	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Industries	b) Store cum choukidar Qr.,Uditnagar	Municipality	S.S	1956	73	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Industries	c) Spl. Officer Res. At Uditnagar.	Municipality	S.S	1956	146	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Industries	d) U.D.C Qrs. At Uditnagar = 4 nos.	Municipality	S.S.	1956	209	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Industries	e) L.D.C. Qrs.at Uditnagar = 8 nos.	Municipality	S.S.	1945	426	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Industries	f) Married person Qrs.at U.nagar=2nos	Municipality	S.S.	1956	113	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Industries	g) Peon Qrs. At Uditnagar = 2 nos.	Municipality	S.S.	1956	113	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Industries	h) Zonal Officer Qrs.U.nagar= 3 nos.	Municipality	S.S.	1955	463	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Industries	l) Peon Qrs.at Uditnagar = 2 nos.	Municipality	S.S.	1956	87	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Industries	j) LDC-cum-Driver Qrs. At Uditnagar.	Municipality	S.S.	1955	40	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Industries	k) UDC Qrs. Uditnagar 4 nos.	Municipality	S.S.	1955	318	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Industries	l) Oversear Qrs. At Uditnagar.	Municipality	S.S.	1958	128	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	m) LDC Qrs.at Uditnagar 4 nos.	Municipality	S.S.	1955	478	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Industries	n) Driver Res.-cum-Motor Garrage.	Municipality	S.S.	1957	182	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Industries	o) Zonal Officer Qr.at Uditnagar.	Municipality	S.S.	1956	165	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Industries	p) RHS Qrs.D/15 near Twin water .	Municipality	D.S	1975	91	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	q) -do- E/23,49,50,51 4 nos.	Municipality	D.S	1979	243	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	r) -do- F/31 1 nos.	Municipality	D.S	1979	40	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	s) -do- G/41,53,66,68, 5 nos.	Municipality	D.S.	1980	186	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	t) -do- at Uditnagar	Municipality	D.S.	1980	91	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	u) -do- E/2	Municipality	D.S.	1980	61	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	v) -do- D/21,23, 2 nos.	Municipality	D.S.	1980	79	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	w) F/type qrs.of DIC at U.nagar 2 nos	Municipality	S.S.	1990	174	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	4 nos. D type qrs. at U.G.I.E	Municipality	D/s	1998	480	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	6 nos. D type qrs. at U.G.I.E.	Municipality	T/s	1998	720	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	6 nos. E-type qrs. at U.G.I.E.	Municipality	T/s	1998	553	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	6 nos. D-type qrs. at SKDAV Pol.Tech.	Municipality	T/s	1997	720	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	12 nos. F-type qrs. at SKDAV Pol.Tech	Municipality	T/s	1997	918	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Industries	4 nos. D-type qrs. at Testing Lab.	Municipality	D/s	1997	480	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Industries	6 nos. E-type qrs. at Testing Lab.	Municipality	D/s	1997	553	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Home	Wireless Inspector Quarter, Bonai	Bonai	S.S	1958	59	BMW	AS flooring	R.C.C.	Panelled & batten	Needs repair
Home	Court S.I. Quarter.	Bonai	S.S	1958	130	BMW	AS flooring	Tile Terraced	Panelled & batten	Needs repair
Home	A.S.I. Qr.	Bonai	S.S	1958	130	BMW	AS flooring	Tile Terraced	Panelled & batten	Needs repair
Home	A.S.I. Qr.	Bonai	S.S	1957	130	BMW	AS flooring	Tile Terraced	Panelled & batten	Needs repair
Home	O.I.C. Qrs.	Bonai	S.S	1957	130	BMW	AS flooring	Tile Terraced	Panelled & batten	Needs repair
Home	W.C. Quarter.	Bonai	S.S	1957	25	BMW	AS flooring	Tile Terraced	Panelled & batten	Needs repair
Home	Habildar quarter.	Bonai	S.S	1957	85	BMW	AS flooring	Tile Terraced	Panelled & batten	Needs repair
Home	A.S.I. Qurs. 2 nos.	Bonai	S.S	1957	123	BMW	AS flooring	Tile Terraced	Panelled & batten	Needs repair
Home	A.S.I. Quarters. 2 nos.	Bonai	S.S	1957	198	BMW	AS flooring	Tile Terraced	Panelled & batten	Needs repair
Home	Constable barrack 7 suite 1 No.	Bonai	S.S	1957	198	BMW	AS flooring	Tile Terraced	Panelled & batten	Needs repair
Home	Constable barrack 6 suite 2 nos.	Bonai	S.S	1957	198	BMW	AS flooring	Tile Terraced	Panelled & batten	Needs repair
Home	Circle Inspector Qrs.	Bonai	S.S	1957	216	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled & batten	Needs repair
Home	A.S.P. Qrs.5R at Uditnagar.	Rourkela	S.S	1962	290	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	S.P. Residence 6 R at Uditnagar.	Rourkela	S.S	1963	560	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	D.S.P. Qrs. 4R 8 nos.	Rourkela	S.S	1961	189	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Inspector Qrs. 3R 3 nos.	Rourkela	S.S	1961	290	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	S.I. Qrs. 3R 4 blocks 8 nos.	Rourkela	S.S	1961	663	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Constable Qrs. 6 nos.	Rourkela	S.S	1961	853	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Clerk qrs. 4 nos.	Rourkela	S.S	1961	251	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	A.S.I. Qrs. 4 nos.	Rourkela	S.S	1961	171	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	A.S.I. Qrs. 2 nos.	Rourkela	S.S	1968	93	BMW	AS flooring	R.C.C.	Pannelled	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Home	Inspector Qrs. At Plant site.	Rourkela	S.S	1968	155	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	S.I. Qrs. 2 nos. Plant site.	Rourkela	D.S	1968	136	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	S.I. Qrs. 8 nos. Plant site.	Rourkela	D.S	1968	409	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Habildar quarters 8 Nos.	Rourkela	D.S	1968	409	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Habildar quarters 8 Nos.	Rourkela	D.S	1967	528	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Constable qrs. 48 nos. at RP line.	Rourkela	D.S	1967	5119	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Constable qrs. 2 nos. at RP line.	Rourkela	D.S	1967	66	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	A.S.I. Qrs at Sectore-19 3 nos.	Rourkela	S.S	1960	129	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Constable Qrs. 34 Nos. at Sectore 19	Rourkela	S.S	1961	3626	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	S.I. Qrs. Sectore-19 2 nos.	Rourkela	S.S	1961	209	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Inspector Qrs. At Sectore-19	Rourkela	S.S	1961	91	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Constable Qrs. At Sectore 7 24 nos.	Rourkela	S.S	1961	2433	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	A.S.I. Qrs. Sectore-3 24 nos.	Rourkela	S.S	1961	2433	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	S.I. Qrs. Sectore-3 4 nos.	Rourkela	S.S	1961	343	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	A.S.I. Qrs. Sectore-7 2 nos.	Rourkela	S.S	1961	179	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	O.S.A.P. Qrs. "O" block 24 nos.	Rourkela	T.S.	1963	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	O.S.A.P. Qrs. "P" block 24 nos.	Rourkela	T.S.	1968	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	O.S.A.P. Qrs. "Q" block 24 nos.	Rourkela	T.S.	1968	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	O.S.A.P. Qrs. "R" block 24 nos.	Rourkela	T.S.	1968	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	O.S.A.P. Qrs. "S" block 24 nos.	Rourkela	T.S.	1968	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	O.S.A.P. Qrs. "D" block 24 nos.	Rourkela	T.S.	1968	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	O.S.A.P. Qrs. "C" block 24 nos.	Rourkela	T.S.	1968	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	O.S.A.P. Qrs. "E" block 24 nos.	Rourkela	T.S.	1968	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Home	O.S.A.P. Qrs. "F" block 24 nos.	Rourkela	T.S.	1968	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	O.S.A.P. Qrs. "G" block 24 nos.	Rourkela	T.S.	1968	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	O.S.A.P. Qrs. 2R qrs.'F" block 24 nos	Rourkela	T.S.	1968	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	O.S.A.P. Qrs. 2R qrs.'K" block 24 nos	Rourkela	T.S.	1968	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	O.S.A.P. Qrs. 2R qrs.'L" block 24 nos	Rourkela	T.S.	1968	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	O.S.A.P. Qrs. 2R qrs.'M" block 24 nos	Rourkela	T.S.	1968	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	O.S.A.P. Qrs. 2R qrs.'N" block 24 nos	Rourkela	T.S.	1968	1108	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	2 R Qrs. 2 block 'TU' block 24 Nos.	Rourkela	T.S.	1968	2215	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	2 RB Qrs. 'VW' block 24 nos.	Rourkela	T.S.	1968	1292	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	2 RB Qrs. 2.5 blocks 30 nos.	Rourkela	T.S.	1968	1737	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	4 R qrs. 1 no.	Rourkela	S.S	1968	293	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	3 R Qrs. 2 blocks 12 nos.	Rourkela	D.S	1968	1040	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	2 R Qrs. 8 blocks 96 nos.	Rourkela	T.S.	1968	7030	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	E type qrs. For O.S.A.P.	Rourkela	D.S	1968	351	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	F type qrs. For O.S.A.P. 5 nos.	Rourkela	D.S	1968	184	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Constable Qrs. At RP line 24 nos.	Rourkela	T.S.	1963	1031	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Constable Qrs. At RP line 24 nos.	Rourkela	T.S.	1963	1032	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	do	Rourkela	T.S.	1963	1033	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Constable Qrs. At R.P. line 48 nos.	Rourkela	T.S.	1972	2062	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Constable Qrs. 13 blocks 24 nos.	Rourkela	S.S	1963	2773	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	A.S.I. Qrs. & 2RB 12 nos.	Rourkela	S.S	1963	514	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	A.S.I. Qrs. 3R 4 nos.	Rourkela	S.S	1963	331	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	A.S.I Qrs. 2 nos.	Rourkela	S.S	1967	90	BMW	AS flooring	R.C.C.	Pannelled	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Home	Surgent Qrs. 2 nos.	Rourkela	S.S	1969	144	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	Reserve Inspector Qrs. 1 no.	Rourkela	S.S	1971	66	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	S.I Qrs. At Raghunathpalli	Rourkela	S.S	1961	296	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannelled	Needs repair
Home	A.S.I Qrs. At Raghunathpalli.	Rourkela	S.S	1961	73	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannelled	Needs repair
Home	Court Inspector Qrs. At Uditnagar.	Rourkela	S.S	1961	410	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannelled	Needs repair
Home	C.I. Reader Qrs. At Uditnagar.	Rourkela	S.S	1961	66	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannelled	Needs repair
Home	Constable Qrs. At Uditnagar.	Rourkela	S.S	1961	302	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannelled	Needs repair
Home	Treasury Guard barrack at Uditnagar	Rourkela	S.S	1989	85	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	R.H.S. Qrs. D-6 at Uditngar.	Rourkela	D.S	1970	91	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	R.H.S. Qrs. E-3 & 4 at Uditnagar.	Rourkela	D.S	1970	122	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	R.H.S. Qrs. G-13,14,15 & 16	Rourkela	D.S	1970	149	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	R.H.S. Qrs. D-22,25,26,28,29 30 & 35	Rourkela	D.S	1970	639	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	R.H.S. Qrs.D-30,31,32,46,55 & 57	Rourkela	D.S	1970	365	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	R.H.S. Qrs.F-28,33,34,35,36 & 45	Rourkela	D.S	1970	236	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	R.H.S. Qrs.G-26,28,35,56 & 65	Rourkela	D.S	1970	186	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	E type Qrs. At Vedveyas Chouk 4 nos.	Rourkela	D.S	1970	334	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	F type Qrs. At Vedveyas chouk 2 nos.	Rourkela	S.S	1972	121	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	F type Qrs. At Vedveyas chouk 8 nos.	Rourkela	D.S	1972	483	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	F type Qrs. At Birmitrapur.	Birmitrapur	D.S	1972	296	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	F type Qrs. At Raghunathpalli	R.N. Palli	D.S	1968	155	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	F type Qrs. At Raghunathpalli	R.N. Palli	S.S	1968	74	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	F type Qrs. At Biramitrapur	Birmitrapur	D.S	1972	283	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	S.I. Qrs. At Biramitrapur	Birmitrapur	S.S	1970	158	BMW	AS flooring	R.C.C.	Pannelled	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Home	A.S.I. Qrs. At Biramitrapur	Birmitrapur	S.S	1970	45	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannelled	Needs repair
Home	Constable Qrs. 7 nos	Birmitrapur	S.S	1970	394	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannelled	Needs repair
Home	F type Qrs at R.P.Line 8 nos	Rourkela	D.S	1991	310	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	F type Qrs At R.P.Line 4 nos	Rourkela	D.S	1990	155	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	F type Qrs At R.P.Line2 nos(Twin)	Rourkela	S.S	1990	74	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	E type Qrs At R.P.Line 3 nos	Rourkela	D.S	1990	217	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	F type Qrs At O.S.A.P. 5 nos	Rourkela	D.S	1991	185	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	E type Qrs At O.S.A.P. 5 nos	Rourkela	D.S	1991	353	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	F type Qrs at Biramitrapur 8 nos	Birmitrapur	S.S	1989	296	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	E type Qrs at Biramitrapur 4 nos	Birmitrapur	S.S	1989	203	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	F type Qrs for Fire Service 5 nos	Rourkela	T.S.	1990	202	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	2 nos. D type Qrs. for Obser. Home	Rourkela	S/s	1997	170	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	4 nos. F type qrs. for Obser. Home	Rourkela	D/s	1997	220	BMW	AS flooring	R.C.C.	Pannelled	Needs repair
Home	12 nos. F-type qrs. at RP line, Rourkela.	Rourkela	T/s	2004	455	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Home	10 nos. F type qrs.	Rourkela	T/s	2004	386	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Home	6 nos. F type qrs.	Rourkela	T/s	2005	232	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Home	Jail Staff Quarter at Bonai	Bonai	S.S.	1913	89	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Home	Sub Assistant Jailer Quarter.	Bonai	S.S.	1988	84	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Home	Assistant Jailer Quarter.	Bonai	S.S.	1988	84	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Home	Head warden quarter.	Bonai	S.S.	1913	37	BMW	AS flooring	Tile Terraced	WP shutter	Needs repair
Home	Sub ordinate staff Qrs. 2 nos.	Bonai	S.S.	1989	74	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Home	do	Bonai	S.S.	1989	74	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Home	Jail warden barrack	Bonai	S.S.	1913	384	BMW	AS flooring	A.C.S. & G.C.I.S.	WP shutter	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Home	do	Bonai	S.S.	1913	217	BMW	AS flooring	Tile Terraced	WP shutter	Needs repair
Home	Sub Jail staff compound wall at Bonai.	Bonai	..	2009				Comp. wall		
Home	3R quarters, 2 nos.	Rourkela	S.S.	1913	184	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Home	2R quarter, 1 no.	Rourkela	S.S.	1913	35	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Home	2RB quarter 1 no.	Rourkela	S.S.	1913	52	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Home	2R quarters, 12 nos.	Rourkela	S.S.	1913	469	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Home	2R quarters, 12 nos. (extension.)	Rourkela	S.S.	2009	124	BMW	AS flooring	A.C.S. & G.C.I.S.	Iron D&W	Needs repair
Home	2R quarters, 6 nos.	Rourkela	S.S.	1913	166	BMW	AS flooring	A.C.S. & G.C.I.S.	Iron D&W	Needs repair
Home	Doctor quarter 3 R 1no	Rourkela	S.S.	1913	107	BMW	AS flooring	A.C.S. & G.C.I.S.	Iron D&W	Needs repair
Home	E-type flat quarter 13 nos.	Rourkela	D.S.	1982	675	BMW	AS flooring	R.C.C.	Iron D&W	Needs repair
Home	D-type quarter -1 no. and F-type 4 nos. for Observation home & spl. School at TISCO	Rourkela	S.S.	1990	258	BMW	AS flooring	R.C.C.	Iron D&W	Needs repair
Home	2 nos. D type Qrs. for Obser. Home at do	Rourkela	S/s	1997	170	BMW	AS flooring	R.C.C.	Iron D&W	Needs repair
Home	4 nos. F type qrs. for Obser. Home at do	Rourkela	D/s	1997	220	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Home	10 Nos. F-type Qrs. for Spl. Jail, Rourkela	Rourkela	T/s	2006	455	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Home	3 nos. E-type qrs. for Spl. Jail, Rourkela.	Rourkela	D/s	2006	191	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	R.H.S. quarter D/8 at Uditnagar.	Rourkela	D.S.	1970	91	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	R.H.S. qrs. E-7,11 & 12 at Uditnagar.	Rourkela	D.S.	1970	183	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do G-17,18,19,20,22 & 24 (6 nos)	Rourkela	D.S.	1970	223	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do at twin water D-10 & 12	Rourkela	D.S.	1972	182	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do at E-37,39 & 48	Rourkela	D.S.	1972	183	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do at G-25	Rourkela	D.S.	1972	37	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do at D-5 at Uditnagar	Rourkela	D.S.	1970	92	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do at E-10 at Uditnagar	Rourkela	D.S.	1970	61	BMW	AS flooring	R.C.C.	WP shutter	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Labour & Empl.	do at G-9 to 10 at Uditnagar	Rourkela	D.S.	1970	74	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do at D-9 to 11 at twin water tower	Rourkela	D.S.	1972	182	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do at E-38 to 40	Rourkela	D.S.	1972	122	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do at F-25	Rourkela	D.S.	1972	139	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do at G-27 & 52	Rourkela	D.S.	1972	74	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	3R & 2RB L.I.C. Uditnagar 5 nos	Rourkela	D.S.	1972	741	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	2RB & 2RA quarter at old L.I.C 5 nos	Rourkela	D.S.	1967	697	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	2 RH-10 nos Old L.I.C	Rourkela	D.S.	1967	576	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do 2 RA -12 nos	Rourkela	D.S.	1967	706	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do F-type 24 nos	Rourkela	D.S.	1967	1382	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do 2RA 1 no	Rourkela	D.S.	1970	37	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do 2RA 2 nos	Rourkela	D.S.	1970	55	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Labour & Empl.	do 1R 2 no	Rourkela	D.S.	1970	51	BMW	AS flooring	R.C.C.	WP shutter	Needs repair
Civil Supply	R.H.S. qrs. At twin water tower E-22, 24, 25 & 47	Rourkela	D.S	1975	243	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Civil Supply	do F-30 & 46	Rourkela	D.S	1975	79	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Civil Supply	do G-37, 50 & 64	Rourkela	D.S	1975	111	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Transport	Staff Qrs.under RHS G-5, Uditnagar.	Rourkela.	S.S	1972	37	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Transport	do E-41, F-41 & 43 at S.T.I.	Rourkela.	D.S	1972	140	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	Sub Treasury Officer Qr. Uditnagar	Rourkela	D.S.	1970	91	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	Staff qrs. For Spl.Treasury G-8 R.H.S.	Rourkela	D.S.	1970	84	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	do at twin water tower D/24	Rourkela	D.S.	1972	91	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	Staff qrs. For Treasury No.E-18,20,59	Rourkela	D.S.	1972	183	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	do G-46 & 58	Rourkela	D.S.	1972	74	BMW	AS flooring	R.C.C.	Pannel	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Finance	Staff qrs for C.T.Deptt. 3 nos	Biramitrapur	S.S	1972	109	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	do Peon qr. 3nos	Biramitrapur	S.S	1972	64	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	D-type Qrs. at Sub Treasury, Bonai.	Bonai.	S/s	2000	98	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	Garrage with 4 R. Qr. 1 No.of CTO, Uditnagar	Rourkela	S.S	1972	175	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	3R Quarters 3 nos. for C.T.O., Uditnagar	Rourkela	S.S	1972	258	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	2R quarters 5 nos. for C.T.O., Uditnagar	Rourkela	D.S.	1972	260	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	2RA quarters 30 nos. for C.T.O., Uditnagar	Rourkela	D.S.	1972	1728	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	E-type 2 nos. for C.T.O. Uditnagar	Rourkela	D.S.	1990	220	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	E-type 15 nos. for C.T.O.(Twin.) (2 block)	Rourkela	T.S.	1990	892	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	C-type duplex qrs. at Unit-39, Rourkela.	Rourkela	D/s	2007	183			Comp. wall		
Finance	C-type qrs. at Unit - 39, Rourkela.	Rourkela	S/s	2008	573			Comp. wall		
Finance	Compound wall around staff qrs. of Treasury deptt.	Rourkela	..	1992				Comp. wall		
Finance	4 nos. E type qrs. at Uditnagar.	Rourkela	D/s	2002	370	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Finance	Compound wall at CTO, Uditnagar	Rourkela	..	2006				Comp. wall		
Finance	Comp. wall at 238 ac. Land unit 39	Rourkela	..	2005				Comp. wall		
Finance	Comp. wall CTO staff Qrs. STI	Rourkela	..	2005				Comp. wall		
Mines	Mining staff Qrs. 4R -1 No.	Rourkela.	S.S	1973	141	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Mines	Mining staff Qrs. 3R 7 nos. & 2R 7 nos	Rourkela.	S.S	1973	418	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Mines	do 1R 10 nos.& 4R 4 nos.	Rourkela.	S.S	1973	399	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Mines	do 2RB 1 no.	Rourkela.	S.S	1973	54	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Mines	do F-54 at Twin water tower.	Rourkela.	S.S	1973	39	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Mines	do G-40 -do-	Rourkela.	S.S	1973	37	BMW	AS flooring	R.C.C.	Pannel	Needs repair
I & P.R.	R.H.S. Qrs.D-27 at Twin water tower.	Rourkela.	D.S.	1975	91	BMW	AS flooring	R.C.C.	Pannel	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
I & P.R.	do E-19 do	Rourkela.	D.S.	1975	61	BMW	AS flooring	R.C.C.	Pannel	Needs repair
I & P.R.	do F-3 do	Rourkela.	D.S.	1975	40	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	Asst. Engineer Qrs. At Bonai.	Bonai.	S.S.	1962	111	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	Junior Engineer Qrs. At Bonai.	Bonai.	S.S.	1962	77	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Works	Sub-Oberseer Qrs. At Bonai.	Bonai.	S.S.	1962	77	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Works	Driver Qrs. At Bonai.	Bonai.	S.S.	1963	39	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Works	SDO Quarter at Bonai.	Bonai.	S.S.	1963	39	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Works	Peon Qrs. At Bonai.	Bonai.	S.S.	1963	26	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Works	do	Bonai.	S.S.	1963	36	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Works	Work shop at Bonai.	Bonai.	S.S.	1963	30	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Works	Roller driver qrs. At Bonai.	Bonai.	S.S.	1967	26	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Works	PWD Clerk Quarter.	Bonai.	S.S.	1967	26	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Works	Jr.Engineer Qrs. At Darjin.	Bonai.	S.S.	1962	86	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	Jr. Enginer Qrs. At Lahunipada.	Bonai.	S.S.	1984	50	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	PWD Jr.Engineer Qrs. At Koira.	Koira	S.S.	1938	77	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Works	Boundary wall of G-type Qrs. at New LIC Colony, Rourkela.	Rourkela.	..	2008				Comp. wall		
Works	Bonday wall of F-type Qrs. at New LIC Colony at Rourkela.	Rourkela.	..	2009				Comp. wall		
Works	E.E. NH Qrs. At Panposh.	Rourkela.	S.S.	1960	238	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	SDO Quarters at Panposh.	Rourkela.	S.S.	1960	83	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	Cashier Qrs. At Panposh.	Rourkela.	S.S.	1960	74	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	Latrine block converted to quarter.	Rourkela.	S.S.	1960	46	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	Kitchen block	Rourkela.	S.S.	1960	127	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	Peon Qrs. At Panposh 6 nos.	Rourkela.	S.S.	1960	133	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Works	E-type 4 nos. & F-type 4 nos.	Rourkela.	D.S.	1976	401	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	S.O. Qrs. At Uditngar.	Rourkela.	S.S.	1954	183	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	Twin qrs. At Uditnagar.	Rourkela.	S.S.	1954	139	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	RHS Qrs. D-1 & D-3 at Uditnagar.	Rourkela.	S.S.	1970	132	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	RHS Qrs. E-5, 6, 8, 13 & 15.	Rourkela.	D.S.	1970	304	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	C-1,2,3,6 & 7 at Uditnagar.	Rourkela.	D.S.	1970	186	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	E-17, 21 & 29	Rourkela.	D.S.	1972	300	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	D-12,17,18 & 21 at Twin water tower	Rourkela.	D.S.	1972	183	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	F-42 and 44	Rourkela.	D.S.	1972	79	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	C-33, 38, 39, 42, 58 and 60	Rourkela.	D.S.	1992	223	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	E.E. Residence at Uditnagar.	Rourkela.	S.S.	1971	339	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	PWD 2RB Qrs. 6 nos. at Uditnagar.	Rourkela.	S.S.	1961	553	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	2R Qrs. I 7 nos. at Uditnagar.	Rourkela.	S.S.	1971	330	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	3R Qrs. 2 nos. at Uditnagar.	Rourkela.	S.S.	1968	290	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	1R Qrs. 6 nos. at Uditnagar.	Rourkela.	S.S.	1965	179	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	1R Qrs. 14 nos. at Uditnagar.	Rourkela.	S.S.	1961	406	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	Kitchen boock converted to S.O. Qr.	Rourkela.	S.S.	1961	127	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	2R Qrs. At Old Bus stand.	Rourkela.	S.S.	1961	451	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	2R Qrs.at old bus stand 5 nos.	Rourkela.	S.S.	1961	648	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	Junior Engineer Qrs. At Bisra.	Rourkela.	S.S.	1954	95	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	Junior Engineer Qrs. At Birmitrapur.	Rourkela.	S.S.	1954	158	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	Junior Engineer Qrs. At Kalulnga.	Rourkela.	S.S.	1954	83	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Works	PWD staff Qrs. At Twin water tower.	Rourkela.	D.S.	1972	228	BMW	AS flooring	R.C.C.	Pannel	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Works	PWD Qrs. E-9	Rourkela.	S.S.	1970	61	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	Compound wall of PWD-1 Panposh.	Rourkela.	..	1971				Comp. wall		
Works	Compound wall of PWD-2 Panposh.	Rourkela.	..	1971				Comp. wall		
Works	Compound wall of PWD-3 Panposh.	Rourkela.	..	1985				Comp. wall		
Works	do PWD-1,5,6 and 9 at Panposh.	Rourkela.	..	1985				Comp. wall		
Works	do PWD-1 at Uditnagar	Rourkela.	..	1989				Comp. wall		
Works	do PWD-2 to 5 at Uditnagar	Rourkela.	..	1989				Comp. wall		
Works	2nos Type -I qr at A.D.B Colony	Rourkela.	S.S.	1993	289	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	2nos Type-II qr at A.D.B Colony	Rourkela.	S.S.	1993	221	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Works	4nos Type-III qr at A.D.B Colony	Rourkela.	S.S.	1993	383	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Education	Head master qrs.at Bonai.	Bonai.	S.S	1938	292	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Education	Asst. Teacher Qrs. At Bonai.	Bonai.	S.S	1956	93	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Education	Hostel Suprintendent Qrs.	Bonai.	S.S	1915	61	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Education	Head Mistress Qrs.of Govt.Girls H.S.	Bonai.	S.S	1957	92	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Education	Asst. Teachers Qrs. 3 nos.	Bonai.	S.S	1964	156	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Education	Clerk room of Govt.Girls High School	Bonai.	S.S	1964	26	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Education	Craft hall (Now 2 nos. Peon Qrs.)	Bonai.	S.S	1956	36	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Education	Kitchen block(Now 2 nos.Teacher Qrs)	Bonai.	S.S	1964	54	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Education	D.I. Of School Qrs.	Bonai.	S.S	1938	90	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Education	R.S. Hostel No.1.	Bonai.	S.S	1963	511	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Education	RDD High School Hostel No.1.	Bonai.	S.S	1963	361	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
Education	-do- No.2	Bonai.	S.S	1967	279	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
Education	TRW hostel(Govt. High School.)	Bonai.	S.S	1967	172	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Education	Principal Qrs. At Panpoh.	Rourkela	D.S.	1980	275	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Education	D-type Qrs.10 nos. at Twin water tower	Rourkela	D.S.	1975	912	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Education	Teachers Qrs. 10 nos.at Birmitrapur.	Birmitrapur.	S.S	1973	390	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Education	2RB Qrs. 7 nos. at Uditnagar.	Rourkela	D.S.	1975	462	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Education	2RA Qrs. 4 nos. at Uditnagar.	Rourkela	D.S.	1975	243	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Education	C-type Qrs. at Twin water tower- 1 No	Rourkela	D.S.	1975	93	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Education	D-type Qrs. 4 nos.(D.19,20,23 & 28)	Rourkela	D.S.	1978	300	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Education	E-type Qrs. 6 nos. (E-42, 43, 56, 58, 16, 19)	Rourkela	D.S.	1970	365	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Education	F-type Qrs. 4 nos.(F-37 to 40)	Rourkela	D.S.	1978	158	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Education	D-type Qrs. 4 nos.(D.4,11,34 & 35)	Rourkela	D.S.	1978	249	BMW	AS flooring	R.C.C.	Pannel	Needs repair
Education	Compouond wall of Principal Qrs.	Rourkela	..	1980				Comp. wall		
Education	Staff. Qrs. of S.G. Womens College	Rourkela.	S/s	1957	147	BMW	AS flooring	R.C.C.	Pannel	Needs repair
H. & T.W.	A.D.W.O Qrs. At Bonai.	Bonai.	S.S	1967	56	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
H. & T.W.	Attendant Qrs. At Bonai.	Bonai.	S.S	1967	20	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
H. & T.W.	A.D.W.O Qrs. At Uditnagar.	Rourkela	S.S	1975	58	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. H & V. S.	S.D.V.O Qr at Bonai	Bonai	S.S	1957	104	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. H & V. S.	Peon qr at do	Bonai	S.S	1957	20	BMW	AS flooring	A.C.S. & G.C.I.S.	Pannel	Needs repair
A. H & V. S.	V.A.S staff qr at Panposh	Rourkela	D.S	1975	37	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. H & V. S.	D-36 near Twin Water Tower	Rourkela	D.S	1975	91	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. H & V. S.	V.A.S qr at STI Chouk	Rourkela	S.S	1973	156	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. H & V. S.	L . I . Qr 1no at STI	Rourkela	S.S	1973	128	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. H & V. S.	Double Mineral Qr at STI	Rourkela	S.S	1973	94	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. H & V. S.	E-type 3nos F-type 3nos & G-type-6nos	Rourkela	S.S	1973	913	BMW	AS flooring	R.C.C.	Pannel	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
A. J.	Asst. Dewan bunglow occupied by SDJM, Bonai (now functioning as Library bldg.)	Bonai.	S.S	1913	227	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
A. J.	L.D.C. Qrs. At Bonai.	Bonai.	S.S	1913	114	BMW	AS flooring	Tile Terraced	Pannel	Needs repair
A. J.	Sub Judge Qrs. At Bonai.	Bonai.	S.S	1913	213	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. J.	do	Bonai.	S.S	1988	85	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. J.	Sub Judge Qrs. At Twin water tower	Rourkela	D.S.	1988	93	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. J.	Qr.No.D-14 and D-32 do	Rourkela	D.S.	1972	182	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. J.	Qr.No.E-33,34,35and 36 do	Rourkela	D.S.	1972	243	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. J.	Qr.No.F-49, 50,51 and 52 do	Rourkela	D.S.	1972	158	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. J.	Qr.No.G-29,30,31,32 and 57 do	Rourkela	D.S.	1972	186	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. J.	D-type Qrs.for J.M.F.C. at Rourkela.	Rourkela	S.S	1996	102	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. J.	Addl.to Asst.Session Judge Qrs.,Bonai	Bonai.	S.S	1996	55	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. J.	Compound wall of SDJM Qr.,Uditnagar	Rourkela	..	1972				Comp. wall		
A. J.	Compound wall of JMFC at Rouorkela	Rourkela	..	1990				Comp. wall		
A. J.	B-type Qrs. For A.D.J. at Uditnagar.	Rourkela	D.S.	2001	216	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. J.	D-type Qrs. For JMFC at Rourkela	Rourkela	S.S	2001	90	BMW	AS flooring	R.C.C.	Pannel	Needs repair
A. J.	Civil & session Court bldg. At Rourkela.	Rourkela	D.S.	2006	3498	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
H. & U.D.	PHD Staff Qrs. 4R - 1 No.at Panposh	Rourkela	S.S.	1966	141	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
H. & U.D.	do 3R 2 nos. at Panposh.	Rourkela	S.S.	1966	193	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
H. & U.D.	do 2RB - 11 nos. at Panposh.	Rourkela	S.S.	1966	597	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
H. & U.D.	do 2RA - 15 nos. at Panposh.	Rourkela	S.S.	1966	590	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
H. & U.D.	do 2R - 3 nos. at Panposh.	Rourkela	S.S.	1966	100	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
H. & U.D.	Garrage - 1 no. at Panposh.	Rourkela	S.S.	1966	20	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Health	S.D.M.O. Qrs. At Bonai.	Bonai	S.S	1920	292	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Health	Staff Nurse Qrs. At Bonai.	Bonai	S.S	1961	68	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Health	do	Bonai	S.S	1961	61	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Health	Doctors Qrs. At Bonai.	Bonai	S.S	1963	85	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Health	Attendant Qrs. At Bonai.	Bonai	S.S	1920	26	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Health	do	Bonai	S.S	1920	26	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Health	Compounder & Servent Qrs.at Bonai	Bonai	S.S	1920	86	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Health	do	Bonai	S.S	1920	86	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Health	Compounder & Dressers Qrs.	Bonai	S.S	1920	64	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Health	do	Bonai	S.S	1920	64	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Health	Mid-wife Qrs. At Bonai.	Bonai	S.S	1920	64	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Health	Asst. Surgeion Qrs. At Bonai.	Bonai	S.S	1920	317	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Health	do	Bonai	S.S	1920	317	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Health	Pharmasist Qrs. At Bonai.	Bonai	S.S	1920	64	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Health	Sanitary Inspector Qrs. At Bonai	Bonai	S.S	1920	50	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Health	Sweeper Qrs. At Bonai.	Bonai	S.S	1920	13	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Health	D-type qrs. for SDH at Bonai.	Bonai	S.S	1994	170	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Health	E-type qrs. for SDH at Bonai.	Bonai	S.S	1994	90	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Health	F-type qrs. for SDH at Bonai	Bonai	S.S	1994	76	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Health	E-type qrs. for SDH at Bonai.	Bonai	S.S	2008	121	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Health	F-type qrs. for SDH at Bonai	Bonai	S.S	2008	79	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Health	Doctors Qrs. At Raghunathpalli	Rourkela.	S.S	1920	192	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Health	Compounder Qrs. At do	Rourkela.	S.S	1920	99	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Health	Dressers Qrs. At do	Rourkela.	S.S	1920	24	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Health	Nurse & Dhai Qrs. At do	Rourkela.	S.S	1920	93	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Health	RHS Qrs. D-33 at Twin water Tower.	Rourkela.	D.S.	1972	91	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Health	do Qrs. No.D-52 at do	Rourkela.	D.S.	1972	60	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Health	do Qrs. No.G-55 at do	Rourkela.	D.S.	1972	37	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Health	Health Inspector Qrs. Do	Rourkela.	D.S.	1972	120	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Health	D-type staff qrs. for R.G.H.	Rourkela	S/s	2005	284	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Health	E-type staff qrs. for R.G.H.	Rourkela	S/s	2005	214	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Health	Staff qrs. C.H.C. bldg.	Birmitrapur	S/s	2003	112	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Agriculture	V.A.W. Qrs. At Bonai.	Bonai	S.S	1978	28	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Agriculture	S.M.S. P.P.quarter at Bonai.	Bonai	S.S	1992	85	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Agriculture	S.M.S.(Agro.) Qrs. At Bonai.	Bonai	S.S	1992	85	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Agriculture	D.A.O. Qrs. At Bonai.	Bonai	S.S	1992	85	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Agriculture	A.D.A.O. Qrs. At Bonai.	Bonai	S.S	1985	86	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Agriculture	V.A.W. Qrs. At Raghunathpalli	Rourkela.	S.S	1989	32	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Agriculture	do at Brahamanitaranga	Rourkela.	S.S	1979	32	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Agriculture	Qr.No.D-1,F-2 and E-6 of Soil Conservation	Rourkela.	S.S	1991	366	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Agriculture	A.C.O. Qrs. At Birmitrapur.	Birmitrapur	S.S	1989	56	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Agriculture	D.A.O. Qrs. At Panposh	Rourkela.	S.S	1993	87	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Agriculture	D-type Qrs. 2 nos. at Panposh.	Rourkela.	D.S	1992	174	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Agriculture	do do	Rourkela.	D.S	1992	174	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Agriculture	Staff Qrs. At Twin water Tower.	Rourkela.	D.S	1972	144	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Sub Collector Qrs. At Uditnagar.	Rourkela	S.S	1960	390	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	2nd Officer Qrs. At Uditnagar.	Rourkela	S.S	1960	183	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Revenue	Head clerk Qrs. At Uditnagar.	Rourkela	S.S	1960	152	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	C.S.I. Qrs. At Uditnagar.	Rourkela	S.S	1960	150	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	Health Inspector Qrs. At Uditnagar.	Rourkela	S.S	1960	102	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	Clerk Qrs. 3 Blocks at Uditnagar.	Rourkela	S.S	1960	686	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	Peon Qrs. 6 block at Uditnagar.	Rourkela	S.S	1960	820	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	Clerk Qrs. 2 block at Uditnagar.	Rourkela	S.S	1960	924	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	Sweeper Qrs. 2 blocks at Uditnagar.	Rourkela	S.S	1964	321	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	Staff Qrs. Of Excise Deptt. 13 Qrs.	Rourkela	S.S	1964	521	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	Qr.No.D-1 & 2 near Twin water tower.	Rourkela	D.S	1964	152	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Qr. No.D-13, 31, 7,37 do	Rourkela	D.S	1964	274	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Qr. No.E-25,27,28,42 & 45	Rourkela	D.S	1980	304	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Qr. No.E-26, 42, 47, 48 & 53	Rourkela	D.S	1980	197	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Qr. No.G-44, 45, 47, 49,61 & 63	Rourkela	D.S	1980	223	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	D-type Qrs. For Tahasil Office, B.Pur	Birmitrapur.	S.S	1980	98	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	F-type Qrs. Do	Birmitrapur.	S.S	1980	70	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	S.I. Of Excise Qrs. At Birmitrapur.	Birmitrapur.	S.S	1980	186	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	Excise Peon Qrs. At Birmitrapur.	Birmitrapur.	S.S	1980	99	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	NT type Qrs. 5 nos.	Rourkela	S.S	1980	371	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	NT.J.E. Qrs. 1 no.	Rourkela	S.S	1980	78	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	LDC Qrs. 4 nos.	Rourkela	S.S	1980	258	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	LDC Qrs. 3 nos.	Rourkela	S.S	1980	90	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	Double Municipal Qrs.	Rourkela	S.S	1980	58	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	Garrage cum Driver Qrs.	Rourkela	S.S	1980	59	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Revenue	Asst. D.W.O. Qrs.	Rourkela	S.S	1980	60	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	A.D.M. Qrs. At Uditnagar.	Rourkela	S.S	1965	333	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	B-type Qrs. 1 No. for S.R.O.	Rourkela	S.S	1980	60	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	R.I. Office Cum. Res.	Rourkela	S.S	1980	60	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	E-type Qrs. 10 nos.	Rourkela	S.S	1980	669	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Dewan bungalow at Bonai	Bonai.	S.S	1980	708	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Office supdt. Qrs. At Bonai.	Bonai.	S.S	1980	170	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Office-cum.-Res. Of C.R.I. At Bonai.	Bonai.	S.S	1976	79	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	Sr. Clerk Qrs. At Bonai.	Bonai.	S.S	1938	75	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	Jr. Clerk Qrs. At Bonai.	Bonai.	S.S	1938	75	BMW	AS flooring	A.C.S. & G.C.I.S.	Panelled iron glazed	Needs repair
Revenue	Jr. Clerks Qrs. 1 No. at Bonai.	Bonai.	S.S	1938	75	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Jr. Clerks Qrs. 2 nos. at Bonai.	Bonai.	S.S	1938	75	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Jr. Clerks Qrs. 3 nos. at Bonai.	Bonai.	S.S	1938	75	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Asst. Teachers Qrs at Bonai.	Bonai.	S.S	1938	75	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Sr. Clerks Qrs. At Bonai.	Bonai.	S.S	1938	75	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	S.H.O.W. qrs. (3rd Officer) at Bonai.	Bonai.	S.S	1938	84	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Tahasildar Qrs.(Addl.Tahasildar)	Bonai.	S.S	1940	84	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Tahasildar Qrs. 1 no. at Bonai.	Bonai.	S.S	1940	984	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Nizarat Qrs. At Bonai.	Bonai.	S.S	1940	984	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Jr. Clerks Qrs. At Bonai.	Bonai.	S.S	1940	65	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	do	Bonai.	S.S	1938	74	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Sr. Clerk Qrs.F-type At Bonai.	Bonai.	S.S	1977	56	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Jr. Clerk Qrs. F-type 2 nos. at Bonai	Bonai.	S.S	1988	135	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Revenue	E-type Qrs. 2 nos. at Bonai.	Bonai.	S.S	1989	135	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Jr. Clerk Qrs. E-type 2 nos. at Bonai.	Bonai.	S.S	1989	135	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Jr. Clerk Qrs. E-type 2 nos. at Bonai.	Bonai.	S.S	1989	135	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Jr. Clerk Qrs. E-type 2 nos. at Bonai.	Bonai.	S.S	1989	135	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Jr. Clerk Qrs. E-type 2 nos. at Bonai.	Bonai.	S.S	1989	135	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Jr. Clerk Qrs. E-type 2 nos. at Bonai.	Bonai.	S.S	1989	135	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Jr. Clerk Qrs. E-type 2 nos. at Bonai.	Bonai.	S.S	1989	135	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Jr. Clerk Qrs. E-type 2 nos. at Bonai.	Bonai.	S.S	1989	135	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Jr. Clerk Qrs. E-type 2 nos. at Bonai.	Bonai.	S.S	1989	135	BMW	AS flooring	R.C.C.	Panelled iron glazed	Needs repair
Revenue	Jr. Clerk Qrs. E-type 2 nos. at Bonai.	Bonai.	S.S	1938	80	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Jr. Clerk Qrs. E-type 2 nos. at Bonai.	Bonai.	S.S	1938	59	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Peons Qrs. At Bonai.	Bonai.	S.S	1938	59	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Jr. Clerk Barrack 4 nos. at Bonai.	Bonai.	S.S	1938	180	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	do do	Bonai.	S.S	1938	545	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	do do	Bonai.	S.S	1938	85	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Amala Barrack 8 nos. at Bonai.	Bonai.	S.S	1913	114	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Garrage cum Driver Qrs. At Bonai.	Bonai.	S.S	1913	21	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Tauzi Qrs. At Bonai.	Bonai.	S.S	1940	90	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Kitchen block at Bonai.	Bonai.	S.S	1940	90	BMW	AS flooring	Tile Terraced	Panelled iron glazed	Needs repair
Revenue	Revenue Supervisor Office-cum-Res. At Bonai.	Bonai.	S.S	2009	58	BMW	AS flooring	R.C.C.	Iron D&W	Needs repair
Revenue	2RB Qrs. At twin water Tower	Rourkela	S.S	1968	55	BMW	AS flooring	R.C.C.	Iron D&W	Needs repair
Revenue	do	Rourkela	S.S	1968	190	BMW	AS flooring	R.C.C.	Iron D&W	Needs repair
Revenue	2RA Qrs. 1 No.	Rourkela	D.S	1968	85	BMW	AS flooring	R.C.C.	Iron D&W	Needs repair
Revenue	2RB Qrs. 4 nos.	Rourkela	D.S	1968	90	BMW	AS flooring	R.C.C.	Iron D&W	Needs repair

Dept. Name	Name of the building	Location	Single/ Double/ multi storied	Year of construct ruction	Total plinth area(Sq m)	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Revenue	Office cum Res. Of Excise S.I.	Rourkela	S.S	1993	55	BMW	AS flooring	R.C.C.	Iron D&W	Needs repair
Revenue	do at Bonai D-type.	Bonai.	S.S	1993	190	BMW	AS flooring	R.C.C.	Iron D&W	Needs repair
Revenue	do A.S.I. Qrs.(New)	Bonai.	S.S	1992	85	BMW	AS flooring	Tile Terraced	Iron D&W	Needs repair
Revenue	Revenue Qrs.E-type 12 nos.,Uditnagar	Rourkela	S.S	1993	879	BMW	AS flooring	R.C.C.	Iron D&W	Needs repair
Revenue	Compound wall of ADM Qrs. Rourkela	Rourkela	..	1966				Comp. wall		
Revenue	Compouond wall of Sub Collector Res.	Rourkela	..	1962				Comp. wall		
Revenue	Compound wall of Rev. Officer Qrs.	Rourkela	..	1962				Comp. wall		
Revenue	Revenue Staff Qrs. 6 Nos., Uditnagar.	Rourkela	T.S.	1992	366	BMW	AS flooring	R.C.C.	Iron D&W	Needs repair

ROURKELA (R&B) DIVISION.
NON RESIDENTIAL

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Industries	UGIE, Rourkela a) Main School building	Municipality	SS/ DS & TS	1964	1964	3400		BMW	A.S. flooring	R.C.C.	Pannel wooden & glazed.	Needs repair
Industries	UGIE, Rourkela b) Work shop building UGIE (4 block)	Municipality	S.S.	1964	do	2898		BMW	A.S. flooring	A.C.S. & G.C.I.S.	Pannel wooden & glazed.	Needs repair
Industries	UGIE, Rourkela c) Hostel bldg. Single storied.	Municipality	S.S.	1964	do	254		BMW	A.S. flooring	R.C.C.	Pannel wooden & glazed.	Needs repair
Industries	UGIE, Rourkela d) Hostel bldg. Double storied	Municipality	D.S.	1964	do	1612		BMW	A.S. flooring	R.C.C.	Pannel wooden & glazed.	Needs repair
Industries	UGIE, Rourkela e) Hostel bldg. Triple storied.	Municipality	T.S.	1964	do	1945		BMW	A.S. flooring	R.C.C.	Pannel wooden & glazed.	Needs repair
Industries	UGIE, Rourkela f) Extension block 2 nos. of Workshop building.	Municipality	S.S.	1973	1973	318		BMW	A.S. flooring	R.C.C.	H.S.grill	Needs repair
Industries	UGIE, Rourkela g) Compound wall of UGIE and	Municipality	..	1985	1985		2546	B.W.M. 9" & 4.5"		Comp. wall		
Industries	UGIE, Rourkela h) Insttitutional building of UGIE, Rourkela.	Municipality	T/s	1996	1996	3600		Brick masonary.	A.S. flooring	R.C.C.	Iron frame with glass pannel door.	Needs repair
Industries	UGIE, Rourkela i) Girls hostel bldg. at UGIE, Rourkela.	Municipality	D/s	1998	1998	839		B.M.	A.S. flooring	R.C.C.	Pannel shutter & window	Needs repair
Industries	UGIE, Rourkela j) Workshop bldg. of UGIE, Rourkela.	Municipality	S/s	1996	1996	134		B.M.	A.S. flooring	R.C.C.	Iron window & door	Needs repair
Industries	I.T.I., Rourkela,									Comp. wall		
Industries	I.T.I., Rourkela, a) Main school building, I.T.I.	Municipality	T.S.	1960	1960	2317		BMW 9' & 13.5"	A.S. flooring	R.C.C.	Pannel & glazed grill	Needs repair
Industries	I.T.I., Rourkela, b) Workshop bldg. 4 nos. of I.T.I.	Municipality	S.S.	1960	do	2941		BMW 9' & 13.5"	A.S. flooring	A.C.S. & G.C.I.S.	Pannel & glazed grill	Needs repair
Industries	I.T.I., Rourkela, c) Dining hall of I.T.I.	Municipality	S.S.	1960	do	2195		BMW 9' & 13.5"	A.S. flooring	A.C.S. & G.C.I.S.	Pannel & glazed grill	Needs repair
Industries	I.T.I., Rourkela, d) I.T.I Hostel bldg. Singl storied 1 No	Municipality	S.S.	1961	1961	666		BMW 9' & 13.5"	A.S. flooring	R.C.C.	Pannel & glazed grill	Needs repair
Industries	I.T.I., Rourkela, e) -do- triplid storied.	Municipality	T.S.	1962	1962	2265		BMW 9' & 13.5"	A.S. flooring	R.C.C.	Pannel & glazed grill	Needs repair
Industries	I.T.I., Rourkela, f) Extention block of I.T.I.	Municipality	S.S.	1973	1973	280		BMW 9' & 13.5"	A.S. flooring	R.C.C.	Pannel & glazed grill	Needs repair

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Industries	I.T.I., Rourkela, g) Cycle & Motor cycle shed of ITI	Municipality	S.S	1972	1972	79		BMW 9' & 13.5"	A.S. flooring	A.C.S. & G.C.I.S.	Pannel & glazed grill	Needs repair
Industries	I.T.I., Rourkela, h) 50 seated apprentice hostel, ITI	Municipality	S.S.	1973	1973	1008		BMW 9' & 13.5"	A.S. flooring	R.C.C.	Pannel & glazed grill	Needs repair
Industries	I.T.I., Rourkela, I) Workshop bldg.(Plastic trade) ITI	Municipality	S.S.	1992	1992	140		BMW 9' & 13.5"	A.S. flooring	R.C.C.	Pannel & glazed grill	Needs repair
Industries	I.T.I., Rourkela, j) Compound wall of I.T.I.	Municipality	..	1995	1995, 2007 & 2008		1185	BMW 9'		Comp. wall		
Industries	I.T.I., Rourkela, k) Class room of I.T.I.	Municipality	S.S.	1992	1992	50		BMW 9'	A.S. flooring	R.C.C.	Panneled door & windows.	Needs repair
Industries	I.T.I., Rourkela, l) Basic Training Centre at Rourkela	Municipality	S.S.	1996	1996	1080		BMW 9'	A.S. flooring	R.C.C.	Iron door & window	Needs repair
Industries	I.T.I., Rourkela, m) Institution building (COE)	Municipality	T/s	2008	2009	864	..	BMW 9'	Kota stone	R.C.C.	Iron door & window	Good
Industries	Testing Laborarory, Rourkela,									Comp. wall		
Industries	a) Administrative Block of Testing Testing Laboratory, Rourkela, Laboratory, Rourkela	Municipality	D.S.	1972	1972	3902		B.W.M.	A.S. flooring	R.C.C.	Pannel glazed.	Good
Industries	Testing Laborarory, Rourkela, b) Compound wall	Municipality	..	1980	1980		300	BMW		Comp. wall		
Industries	Testing Laborarory, Rourkela, c) Laborary building, Rourkela.	Municipality	D.S	1972	1972	3193		B.M.W.	A.S. flooring	R.C.C.	Pannel glazed.	Good
Industries	D.I.C., Rourkela,									Comp. wall		
Industries	D.I.C., Rourkela, a) Administrative building of Jt. Director of Industries, Rourkela.	Municipality	S.S	1954	1954	594		B.M.W.	A.S. flooring	R.C.C.	Pannel glazed.	Good
Industries	D.I.C., Rourkela, b) Canteen building of -do-	Municipality	S.S	1967	1967	119		B.M.W.	A.S. flooring	R.C.C.	Pannel glazed.	Good
Industries	D.I.C., Rourkela, c) Extention block of DIC Office.Rkl.	Municipality	S.S	1982	1982	100		B.M.W.	A.S. flooring	R.C.C.	Pannel glazed.	Good
Industries	D.I.C., Rourkela, d) Compound wall of DIC Office bldg.	Municipality	..	2001	2001		98	B.M.W.		Comp. wall		
Industries	a) S.K.D.A.V. Polytechnic Institute building.	Municipality	SS+ DS	1989	1989	3767		B.M.W.	A.S. flooring	R.C.C.	Pannel glazed.	Good
Industries	b) S.K.D.A.V. Poly.tech. Workshop.	Municipality	S.S.	1989	1989	1881		B.M.W.	A.S. flooring	A.C.S. & G.C.I.S.	Pannel glazed.	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Industries	c) S.K.D.A.V. Poly. Tech. Womens hostel	Municipality	D.S	1989	1989	5655		B.M.W.	A.S. flooring	R.C.C.	Pannel glazed.	Good
Industries	d) Class room workshop & Pump house of SKDAV Ploy. Tech.	Municipality	S.S.	1968	1968	392		B.M.W.	A.S. flooring	A.C.S. & G.C.I.S.	Pannel glazed.	Good
Industries	e) Compound wall of SKDAV Poly. Tech. Institutie & hostel	Municipality	..	1989	1989		572	do 2 M.		Comp. wall		
Industries	f) Institutional bldg. of SKDAV Poly tech. for Women, Rourkela.	Municipality	T/s	1994	1994	2231		B.M.	A.S. flooring	A.C.S. & G.C.I.S.	Pannel window & glazed.	Good
Industries	a) Office of the Deputy Chief Inspector of Factories & Boilers.	Municipality	S.S.	1968	1968	279		B.M.	A.S. flooring	R.C.C.	Pannel window & glazed.	Good
Home	Circle Inspector Office at Bonai.	Bonai	S.S.	1956	..	245		Brick	AS flooring	A.C.S. & G.C.I.S.	Batten	Good
Home	Police Club building	Bonai	S.S.	1988	..	84		Brick	AS flooring	A.C.S. & G.C.I.S.	Batten	Good
Home	Pigeon loft at Bonai.	Bonai	S.S.	1964	..	23		Brick	AS flooring	A.C.S. & G.C.I.S.	Batten	Good
Home	Police station building.	Bonai	S.S.	1963	..	247		Brick	AS flooring	A.C.S. & G.C.I.S.	Pannel shutter	Good
Home	Circle transmission.	Bonai	S.S.	1975	..	172		Brick	AS flooring	R.C.C.	Pannel shutter	Good
Home	Out Post building, Raghunathpalli	R.N.Palli.	S.S.	1961	..	235		Brick	AS flooring	A.C.S. & G.C.I.S.	Batten	Good
Home	Constable barrack.	R.N.Palli.	S.S.	1961	..	358		Brick	AS flooring	A.C.S. & G.C.I.S.	Batten	Good
Home	Treasury guard barrack.	R.N.Palli.	S.S.	1961	..	116		Brick	AS flooring	A.C.S. & G.C.I.S.	Batten	Good
Home	Sub Jail building.	R.N.Palli.	S.S.	1960	..	183		Brick	AS flooring	A.C.S. & G.C.I.S.	Batten	Good
Home	Thana building.	R.N.Palli.	S.S.	1969	..	238		Brick	AS flooring	A.C.S. & G.C.I.S.	Batten	Good
Home	S.P. Office building.	R.N.Palli.	S.S.	1965	..	1762		Brick	AS flooring	R.C.C.	Batten	Good
Home	Temporary garrage at Plantsite P.S.	R.N.Palli.	S.S.	1967	..	144		Brick	AS flooring	R.C.C.	Batten	Good
Home	Motor garrage at A.S.P. Qr.	R.N.Palli.	S.S.	1966	..	25		Brick	AS flooring	A.C.S. & G.C.I.S.	Batten	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Home	Main P.S. bldg. At Plant site.	R.N.Palli.	D.S.	1967	..	1177		Brick	AS flooring	R.C.C.	Batten	Good
Home	Police Out post building.	R.N.Palli.	S.S.	1967	..	245		Brick	AS flooring	R.C.C.	Batten	Good
Home	Rest room cum-class room,Plantsite	R.N.Palli.	S.S.	1967	..	236		Brick	AS flooring	R.C.C.	Batten	Good
Home	A.P.R.Barrack at Birmitrapur.	Birmitrapur	S.S.	1962	..	452		Brick	AS flooring	A.C.S. & G.C.I.S.	Batten	Good
Home	P.S. building at Birmitrapur	Birmitrapur	S.S.	1962	..	104		Brick	AS flooring	A.C.S. & G.C.I.S.	Batten	Good
Home	Permanent garrage at Plantsite 2 nos	Rourkela	S.S.	1968	..	100		Brick	AS flooring	A.C.S. & G.C.I.S.	Batten	Good
Home	-do- 4 rooms.	Rourkela	S.S.	1968	..	224		Brick	AS flooring	A.C.S. & G.C.I.S.	Batten	Good
Home	Pressure filter house Plant site.	Rourkela	S.S.	1968	..	37		Brick	AS flooring	A.C.S. & G.C.I.S.	Batten	Good
Home	Pump chamber at Plant site.	Rourkela	S.S.	1968	..	10		Brick	AS flooring	R.C.C.	Pannel	Good
Home	-do- 2 nos.	Rourkela	S.S.	1968	..	58		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Chlorine house,Plant site.	Rourkela	S.S.	1968	..	15		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Out Post building at Plant site.	Rourkela	S.S.	1969	..	118		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Filter & APR barrack at Plant site	Rourkela	S.S.	1968	..	8		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Weigh bridge building 1 no.	Rourkela	S.S.	1964	..	13		Brick	AS flooring	R.C.C.	Pannel	Good
Home	P.S. building at Sactore 19	Rourkela	S.S.	1961	..	591		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Out post building Sactore-7	Rourkela	S.S.	1961	..	118		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Out post building at Sactore-3	Rourkela	S.S.	1961	..	118		Brick	AS flooring	R.C.C.	Pannel	Good
Home	UP school building at OSAP Barrack	Rourkela	S.S.	1966	..	896		Brick	AS flooring	R.C.C.	Pannel	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Home	Market bldg. Of OSAP	Rourkela	S.S.	1966	..	513		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Garrage bldg. O.S.A.P.	Rourkela	D.S.	1968	..	4726		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Club canteen of OSAP.	Rourkela	SS/DS/TS	1968	..	1651		Brick	AS flooring	R.C.C.	Pannel	Good
Home	PWD Store at OSAP..	Rourkela	S.S.	1968	..	2287		Brick	AS flooring	A.C.S. & G.C.I.S.	Pannel	Good
Home	Hospital building OSAP	Rourkela	S.S.	1968	..	1890		Brick	AS flooring	R.C.C.	Pannel	Good
Home	100 seated barrack of OSAP 2 nos.	Rourkela	D.S.	1970	..	4298		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Company Office bldg. O.S.A.P.	Rourkela	T.S.	1970	..	1598		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Guard room O.S.A.P. 2 nos.	Rourkela	S.S.	1970	..	111		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Tear smoke dump proof room OSAP	Rourkela	S.S.	1968	..	244		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Store cum petrol & lubricant OSAP	Rourkela	S.S.	1970	..	51		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Refilid shed, cycle shed OSAP	Rourkela	S.S.	1970	..	264		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Open urinal guard rom for OSAP	Rourkela	S.S.	1970	..	93		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Saluting base for O.S.A.P.,.	Rourkela	S.S.	1970	..	93		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Police barrack at Sectore-19	Rourkela	S.S.	1961	..	261		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Reserve Police Office at RP line.	Rourkela	D.S.	1961	..	519		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Motor vehicle shed RP line.	Rourkela	S.S.	1968	..	35		Brick	AS flooring	R.C.C.	Iron shutt.	Good
Home	Wireless office, R.P. Line.	Rourkela	S.S.	1968	..	78		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Generating Office, RP line 1 no.	Rourkela	S.S.	1968	..	61		Brick	AS flooring	R.C.C.	Pannel	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Home	Magazine & armoury R.P.line.	Rourkela	S.S.	1968	..	1570		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Petrol Pump of R.P Line.	Rourkela	S.S.	1968	..	15		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Constable barrack - 40 nos. RP line	Rourkela	S.S.	1968	..	5749		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Police hospital, R.P. Line.	Rourkela	S.S.	1968	..	1291		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Motor garrage R.P. Line - 5 nos.	Rourkela	S.S.	1968	..	210		Brick	AS flooring	R.C.C.	Iron shutt.	Good
Home	Motor garrage R.P. Line - 3 nos.	Rourkela	S.S.	1968	..	91		Brick	AS flooring	R.C.C.	Iron shutt.	Good
Home	Dog Kennel of R.P. line.	Rourkela	S.S.	1965	..	103		Brick	AS flooring	R.C.C.	Iron shutt.	Good
Home	Ramp for motor Garrage, RP Line.	Rourkela	..	1967	..	74		Brick	AS flooring	R.C.C.	Iron shutt.	Good
Home	Temporary garrage RP line 4 nos.	Rourkela	S.S.	1967	..	59		Brick	AS flooring	A.C.S. & G.C.I.S.	Iron shutt.	Good
Home	Dining hall, R.P. Line	Rourkela	S.S.	1966	..	126		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Latrine room, R.P. line.	Rourkela	S.S.	1966	..	66		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Obstacle of course wall,R.P.line	Rourkela	..	1966	..	5		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Asst. Fire Office, Plant site.	Rourkela	S.S.	1969	..	808		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Tin shed barrack O.S.A.P	Rourkela	S.S.	1969	..	3293		Brick	AS flooring	A.C.S. & G.C.I.S.	Pannel	Good
Home	P.S. building Bondamunda	Rourkela	S.S.	1991	..	210		Brick	AS flooring	R.C.C.	Pannel	Good
Home	P.S. building Raghunathpalli	Rourkela	S.S.	1992	..	211		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Cooperative store, R.P. line.	Rourkela	S.S.	1992	..	93		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Constable barrack R.P.line.	Rourkela	S.S.	1993	..	112		Brick	AS flooring	R.C.C.	Pannel	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Home	Compouond wall to S.P. Office bldg.	Rourkela	..	1995	..		60	Brick	AS flooring	R.C.C.	Pannel	Good
Home	Compound wall of P.S. bldg. Sector-7	Rourkela	..	1976	..		320	Brick		Comp. wall		
Home	Compund wall P.S. bldg. Sector-3	Rourkela	..	1976	..		320	Brick	AS flooring	R.C.C.	Pannel	Good
Home	High school bldg. Of O.S.A.P	Rourkela	S.S.	1988	..	312		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Vigilance D.S.P Office bldg.	Rourkela	S.S.	1992	..	144		Brick	AS flooring	R.C.C.	Pannel	Good
Home	Compund wall DSP(Vig.) Office bldg.	Rourkela	..	1992	..		90	Brick	AS flooring	R.C.C.	Pannel	Good
Home	P.S. bldg. At Brahamanitarang. (B.type)	Rourkela	S.S.	1988	2003	169		Brick	AS flooring	R.C.C.	Pannel	Good
Home	P.S. bldg. At Sectore-3(B-type)	Rourkela	S.S.	1988	2001	169		Brick	AS flooring	R.C.C.	Pannel	Good
Home	P.S. bldg. Sector-15 (B-type)	Rourkela	S.S.	1988	2001	169		Brick	AS flooring	R.C.C.	Pannel	Good
Home	P.S. bldg. Raghunathpalli (A-type)	Rourkela	S.S.	1989	2001	221		Brick	AS flooring	R.C.C.	Pannel	Good
Home	P.S. bldg. Bondamunda (A-type)	B.munda	S.S.	1990	2001	220		Brick	AS flooring	R.C.C.	Pannel	Good
Home	P.S. bldg. Bondamunda (Old)	B.munda	S.S.	1974	..	575	350	Brick	AS flooring	A.C.S. & G.C.I.S.	Pannel	Good
Home	M.S. school bldg. R.P. Line.	Rourkela	S.S.	1985	2001	380		Brick	AS flooring	A.C.S. & G.C.I.S.	Pannel	Good
Home	D.F.S.L. bldg. R.P. Line.	Rourkela	S.S.	1984	2001	79		Brick	AS flooring	A.C.S. & G.C.I.S.	Pannel	Good
Home	P.M.C. at Bonai.	Bonai	S.S.	1993	2003	18		Brick	AS flooring	A.C.S. & G.C.I.S.	Pannel	Good
Home	Fire station building at Bonai.	Bonai	D/s	2001		203		Brick	AS flooring	R.C.C.	Iron	Good
Home	Fire station bldg. At Rourkela 4 Units	Rourkela	D.S.	1999	2001	443		Brick	AS flooring	R.C.C.	Iron	Good
Home	Addl. Hall 120 capacity at spl. Jail	Rourkela	S/s	2005	2005	415.3		Brick	AS flooring	R.C.C.	Iron	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Home	Observation home building.	Rourkela	S/s	1997	1997	523		Brick	AS flooring	R.C.C.	Iron	Good
Home	Comp. wall for obser. Home TISCO	Rourkela	..	1996	1997		866	Brick	..	R.C.C.	Iron	Good
Home	Compound wall at R.P. Line.	Rourkela	..	2006	2007		1060	Brick		Comp. wall		
Home	Compound wall at P.S. bldg.	Bondamunda	..	2005	2005		425	Brick		Comp. wall		
Home	Conference hall at S.Ps Office	Rourkela	D/s	2007	2009	211	..	Brick	Kota stone	R.C.C.	Aluminium	Good
Home	Raghunathpalli P.S. bldg.	Rourkela	S/s	2008	2009	29	..	Brick	Kota stone	A.C.S. & G.C.I.S.	Aluminium	Good
Home	Female & Male ward in Spl-Jail 4 nos	Rourkela	S.S	1961	..	487		Brick	Kota stone	R.C.C.	Iron Shutter	Good
Home	Kitchen Block Spl-Jail 2 nos	Rourkela	S.S	1961	..	447		Brick	Kota stone	A.C.S. & G.C.I.S.	Iron Shutter	Good
Home	Segrage Room Spl-Jail 2 nos	Rourkela	S.S	1961	..	1210		Brick	Kota stone	R.C.C.	Iron Shutter	Good
Home	Hospital with latrine 1 No.	Rourkela	S.S	1961	..	1429		Brick	Kota stone	R.C.C.	Iron Shutter	Good
Home	Bath and Latrine 25 nos.	Rourkela	S.S	1961	..	101		Brick	Kota stone	R.C.C.	Iron Shutter	Good
Home	Office building 1 no.	Rourkela	S.S/ D.S	1961	..	496		Brick	Kota stone	R.C.C.	Iron Shutter	Good
Home	Dining & Work shop 2 nos.	Rourkela	S.S	1961	..	1217		Brick	Kota stone	R.C.C.	Iron Shutter	Good
Home	Out house, bath room 2 nos.	Rourkela	S.S	1976	..	297		Brick	Kota stone	R.C.C.	Iron Shutter	Good
Home	Kitchen room 1 No.	Rourkela	S.S	1976	..	27		Brick	Kota stone	A.C.S. & G.C.I.S.	Iron Shutter	Good
Home	Visitor room, Perimeter wall 2 nos. Obstacle wall 2 nos., Wall and crimpal room.	Rourkela	S.S	1991	..	348		Brick	Kota stone	R.C.C.	Iron Shutter	Good
Home	Jail with subsidiary bldgs. At Bonai.	Bonai.	S.S	1964	..	1757		Brick	Kota stone	R.C.C.	Iron Shutter	Good
Home	52 male ward of Spl.Jail, Rourkela 4 nos	Rourkela	D.S.	1961	..	1880		Brick	Kota stone	R.C.C.	Iron Shutter	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Home	32 male ward of Spl.Jail Rourkela 1 No	Rourkela	D.S	1964	..	302		Brick	Kota stone	R.C.C.	Iron Shutter	Good
Home	Male ward of Spl.Jail, Rourkela 36 nos	Rourkela	S.S	1961	..	438		Brick	Kota stone	R.C.C.	Iron Shutter	Good
Home	Compound wall to Spl. Jail, Rourkela	Rourkela	..	1961	..		120	Brick		Comp. wall		
Home	Compound wall to spl. Jail, Bonai.	Bonai.	..	1964	..		900	Brick		Comp. wall		
Home	Dining hall	Bonai.	S/s	2009	..	77		Brick	Kota stone	R.C.C.	Iron Shutter	Good
Home	Observation Home & Spl. School Block 3 Workshop building.	Rourkela	S.S	1989	2003	343		Brick wall	Kota stone	R.C.C.	Iron Shutter	Good
Home	do block 2 School building.	Rourkela	S.S	1989	2003	279		Brick wall	Kota stone	R.C.C.	Iron Shutter	Good
Home	do block 1 Hostel building.	Rourkela	S.S	1989	2003	802		Brick wall	Kota stone	R.C.C.	Iron Shutter	Good
Home	Administrative building.	Rourkela	S.S	1991	2003	159		Brick wall	Kota stone	R.C.C.	Iron Shutter	Good
Home	Compound wall around -do-	Rourkela	..	1991	2003		533	Brick wall		Comp. wall		
Home	Addl. Hall 120 capacity at spl. Jail	Rourkela	S/s	2005	2005	415.3		Brick wall	Kota stone	R.C.C.	Iron Shutter	Good
Home	Observation home building.	Rourkela	S/s	1997	1997	523		Brick wall	Kota stone	R.C.C.	Iron Shutter	Good
Home	Comp. wall for obser. Home TISCO	Rourkela	..	1996	1997		866	Brick wall	Kota stone	R.C.C.	Iron Shutter	Good
Home	Addl. Hall 120 capacity at spl. Jail	Rourkela	S/s	2005	2005	415.3		Brick wall	Kota stone	R.C.C.	Iron Shutter	Good
Home	Observation home building.	Rourkela	S/s	1997	1997	523		Brick wall	Kota stone	R.C.C.	Iron Shutter	Good
Home	120 capacity ward at Spl. Jail, Rkl	Rourkela	S/s	2005	2009	415		Brick wall	A.S.	R.C.C.	Iron Shutter	Good
Home	300 capacity ward at Spl. Jail, Rkl.	Rourkela	T/s	2006	..	367	81	Brick wall	A.S.	R.C.C.	Iron Shutter	Good
Home	Perimeter wall at Spl. Jail, Rourkela	Rourkela	S/s	2006	2009	..	393	Brick wall	A.S.	R.C.C.	Iron Shutter	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Labour & Empl.	Zonal Labour Office at Uditnagar.	Rourkela.	S.S	1964	..	264		Brick wall	A.S.	R.C.C.	Iron Shutter	Good
Labour & Empl.	Extention of do	Rourkela.	S.S	1976	..	279		Brick wall	A.S.	R.C.C.	Iron Shutter	Good
Labour & Empl.	Employment Exchange office bldg.	Rourkela.	S.S	1960	..	881		Brick wall	A.S.	R.C.C.	Iron Shutter	Good
Labour & Empl.	Compound wall to labour office.	Rourkela.	..	1964	..		100	Brick wall		Comp. wall		
Labour & Empl.	do to Employment Exchange office.	Rourkela.	..	1964	..		200	Brick wall	A.S.	R.C.C.	Iron Shutter	Good
Labour & Empl.	Industrial Tribunal bldg.Rourkela.	Rourkela.	S.S	1962	1997	260		Brick wall	A.S.	R.C.C.	Iron Shutter	Good
Labour & Empl.	Garrage do	Rourkela.	S.S	1962	1997	25		Brick wall	A.S.	R.C.C.	Iron Shutter	Good
Labour & Empl.	Compound wall do	Rourkela.	..	1962	1997		37	Brick wall		Comp. wall		
Civil Supply	Civil Supply Office Building at Uditnagar	Rourkela	S.S	1960	..	883	0	Brick wall	A.S.	R.C.C.	Iron Shutter	Good
Civil Supply	Storage Goodown at S.T.I. 4 nos	Rourkela	S.S	1962	..	1466	0	Brick wall	A.S.	A.C.S. & G.C.I.S.	Iron Shutter	Good
Transport	R.T.O Office building at Rourkela.	Rourkela.	D.S	1960	..	449		Brick wall	A.S.	A.C.S. & G.C.I.S.	Iron Shutter	Good
Transport	Com. Wall at R.T.O. Office,	Rourkela	..	2005	2005		560	Brick wall	A.S.	A.C.S. & G.C.I.S.	Iron Shutter	Good
Finance	Sub Treasury Office bldg. Bonai.	Bonai.	S.S	1991	..	172		Brick wall	A.S.	A.C.S. & G.C.I.S.	Iron Shutter	Good
Finance	D-type Qrs. at Sub Treasiru, Bonai	Bonai.	S.S	2000	..	1055		Brick wall	A.S.	A.C.S. & G.C.I.S.	Iron Shutter	Good
Finance	Spl. Treasury Office bldg., Uditnagar	Rourkela.	S.S	1963	..	902		Brick wall	A.S.	A.C.S. & G.C.I.S.	Iron Shutter	Good
Finance	Office building for C.T.O.	Birmitrapur.	S.S	1963	..	23		Brick wall	A.S.	A.C.S. & G.C.I.S.	Iron Shutter	Good
Finance	C.T.O. godown	Birmitrapur.	S.S	1966	..	23		Brick wall	A.S.	A.C.S. & G.C.I.S.	Iron Shutter	Good
Finance	Office building for C.T.O.	Rourkela.	S.S	1963	..	753		Brick wall	A.S.	A.C.S. & G.C.I.S.	Iron Shutter	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Finance	Compound wall for C.T.O. Office	Rourkela.	S.S	1963	..		392	Brick wall		Comp. wall		
Finance	C.T.O Office building (New)	Rourkela.	T.S	1998	1999	365		Brick wall	A.S.	A.C.S. & G.C.I.S.	Iron Shutter	Good
Finance	Compound Wall & Cycle Shed	Rourkela.	..	1999	2000		135	Brick wall		Comp. wall		
Finance	Computer Room Spl. Treasure Panposh	Rourkela.	S.S	2002	2002	40		Brick wall	A.S.	A.C.S. & G.C.I.S.	Iron Shutter	Good
Finance	Conference hall for C.T.O. at Rourkela.	Rourkela.	D/s	2009	2009	207		Brick wall	Kota stone	R.C.C.	Alluminium	Good
Mines	Mining Office at Uditnagar.	Rourkela.	S.S.	1985	..	424	0	Brick wall	A.S.	R.C.C.	Alluminium	Good
I & P.R.	D.I.P.R.O.Office building at Panposh	Rourkela	S.S	1992	..	536		Brick wall	A.S.	R.C.C.	Alluminium	Good
I & P.R.	Compound wall of DIPRO Office.	Rourkela	..	1993	..		260	Brick wall		Comp. wall		
I & P.R.	Garrage & Choukidar shed -do-	Rourkela	S.S	1993	..	35		Brick wall	A.S.	R.C.C.	Alluminium	Good
Works	PWD Sub division Office, Bonai.	Bonai	S.S.	1968	..	389		Brick wall	A.S.	R.C.C.	Alluminium	Good
Works	PWD Store no.1 at Bonai.	Bonai	S.S.	1968	..	80		Brick wall	A.S.	R.C.C.	Alluminium	Good
Works	PWD Store No.2 at Bonai.	Bonai	S.S.	1968	..	75		Brick wall	A.S.	R.C.C.	Alluminium	Good
Works	PWD Store no.1 at Bonai.	Bonai	S.S.	1971	..	117		Brick wall	A.S.	A.C.S. & G.C.I.S.	Alluminium	Good
Works	PWD Store No.2 at Bonai.	Bonai	S.S.	1971	..	95		Brick wall	A.S.	A.C.S. & G.C.I.S.	Alluminium	Good
Works	Compuound wall of Sub divn.Office.	Bonai	S.S.	1970	..		150	Brick wall	A.S.	A.C.S. & G.C.I.S.	Alluminium	Good
Works	PWD IB at Bonai.	Bonai	S.S.	2008	..	102		Brick wall	A.S.	A.C.S. & G.C.I.S.	Alluminium	Good
Works	PWD IB at Bonai, Kitchen block	Bonai	S.S.	2008	..	102		Brick wall	A.S.	A.C.S. & G.C.I.S.	Alluminium	Good
Works	PWD IB, Bonai Compound wall	Bonai	..	2008	..		244	Brick wall		Comp. wall		

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Works	Bonai (R&B) Sub division Office	Bonai	S.S	2009	..	65		Brick wall	AS & Kota	R.C.C.	Alluminium	Good
Works	PWD store at Koira.	Koira	S.S.	1968	..	130		Brick wall	AS & Kota	R.C.C.	Alluminium	Good
Works	PWD sub division Office at Panposh.	Rourkela.	S.S.	1951	..	202		Brick wall	AS & Kota	R.C.C.	Alluminium	Good
Works	Store godown at Panposh.	Rourkela.	S.S.	1965	..	37		Brick wall	AS & Kota	R.C.C.	Alluminium	Good
Works	C.T. sub division Office, Rourkela.	Rourkela.	S.S.	1938	..	249		Brick wall	AS & Kota	Tile Terraced	Alluminium	Good
Works	PWD Store 3 nos. at Rourkela.	Rourkela.	S.S.	1970	..	889		Brick wall	AS & Kota	A.C.S. & G.C.I.S.	Alluminium	Good
Works	PWD Store 2 nos. (T&P)	Rourkela.	S.S.	1970	..	695		Brick wall	AS & Kota	A.C.S. & G.C.I.S.	Alluminium	Good
Works	PWD Store and Section Office.	Rourkela.	S.S.	1970	..	43		Brick wall	AS & Kota	A.C.S. & G.C.I.S.	Alluminium	Good
Works	C.T. Section No.1 Office.	Rourkela.	S.S.	1970	..	21		Brick wall	AS & Kota	A.C.S. & G.C.I.S.	Alluminium	Good
Works	R.C. Sub division Office.	Rourkela.	S.S.	1970	..	193		Brick wall	AS & Kota	A.C.S. & G.C.I.S.	Alluminium	Good
Works	Division Office building, Rourkela.	Rourkela.	D.S.	1962	..	1302		Brick wall	AS & Kota	R.C.C.	Alluminium	Good
Works	PWD C.T. Section Office.	Rourkela.	S.S.	1972	..	71		Brick wall	AS & Kota	R.C.C.	Alluminium	Good
Works	PWD Store at OSAP Campus.	Rourkela.	S.S.	1967	..	898		Brick wall	AS & Kota	A.C.S. & G.C.I.S.	Alluminium	Good
Works	Investigation Sub division Office.	Rourkela.	S.S.	1975	..	279		Brick wall	AS & Kota	R.C.C.	Alluminium	Good
Works	Compound wall of C.T. Sub divn.	Rourkela.	..	1976	..		200	Brick wall		Comp. wall		
Works	Inner compound wall of Central Store.	Rourkela.	..	1980	..		150	Brick wall		Comp. wall		
Works	Compound wall of Panposh Sub divn.	Rourkela.	..	1988	..		50	Brick wall		Comp. wall		
Works	do of Investigation Sub divn. Office.	Rourkela.	..	1983	..		60	Brick wall	AS & Kota	R.C.C.	Alluminium	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Works	ADB Office bldg. At Panposh.	Rourkela.	S.S.	1993	1999	696		Brick wall	Mosaic	R.C.C.	Alluminium	Good
Works	Generator room -do-	Rourkela.	S.S.	1993	1999	33		Brick wall	AS flooring	R.C.C.	Alluminium	Good
Works	Pumphper room -do-	Rourkela.	S.S.	1993	1999	17		Brick wall	AS flooring	R.C.C.	Alluminium	Good
Works	Guest house -do-	Rourkela.	S.S.	1993	1999	120		Brick wall	AS flooring	R.C.C.	Alluminium	Good
Works	Cycle stand of Bonai Sub divn.	Bonai	S.S.	1990	..	43		Brick wall	AS flooring	R.C.C.	Alluminium	Good
Works	Compound Wall at P.W.D. I.B. Bonai	Bonai	..	1999	..		282	Brick wall		Comp. wall		
Works	Compound Wall Sub Division Office	Bonai	..	1998	..		160	Brick wall		Comp. wall		
Education	RDD high school at Bonai.	Bonai.	S.S.	1938	..	288		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Alluminium	Good
Education	Old high school at Bonai.	Bonai.	S.S.	1938	..	226		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Alluminium	Good
Education	do	Bonai.	S.S.	1938	..	211		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Alluminium	Good
Education	Compound wall & Urinal at Bonai.	Bonai.	..	1976	..		200	Brick wall		Comp. wall		
Education	Vocational Training College, Rourkela	Rourkela.	S.S.	1982	..	160		Brick wall	AS flooring	R.C.C.	Alluminium	Good
Education	High School hostel No.1 at Bonai.	Bonai.	S.S.	1938	..	810		Brick wall	AS flooring	Tile Terraced	Alluminium	Good
Education	High School hostel No.2 at Bonai.	Bonai.	S.S.	1938	..	273		Brick wall	AS flooring	Tile Terraced	Alluminium	Good
Education	D.I. Of School office building	Bonai.	S.S.	1940	..	88		Brick wall	AS flooring	Tile Terraced	Alluminium	Good
Education	RDD high School (New block)	Bonai.	S.S.	1963	..	602		Brick wall	AS flooring	Tile Terraced	Alluminium	Good
Education	do (Old block.)	Bonai.	S.S.	1950	..	1692		Brick wall	AS flooring	Tile Terraced	Alluminium	Good
Education	do (Science laboratory)	Bonai.	S.S.	1959	..	92		Brick wall	AS flooring	R.C.C.	Alluminium	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Education	do (Craft shed.)	Bonai.	S.S.	1952	..	49		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Alluminium	Good
Education	do (Kitchen block)	Bonai.	S.S.	1988	..	150		Brick wall	AS flooring	Tile Terraced	Alluminium	Good
Education	Gopinathpur M.E.School.	Bonai.	S.S.	1988	..	229		Brick wall	AS flooring	Tile Terraced	Alluminium	Good
Education	do (Craft hall)	Bonai.	S.S.	1940	..	96		Brick wall	AS flooring	Tile Terraced	Alluminium	Good
Education	do (DAC room)	Bonai.	S.S.	1940	..	24		Brick wall	AS flooring	Tile Terraced	Alluminium	Good
Education	do (Hostel building.)	Bonai.	S.S.	1938	..	226		Brick wall	AS flooring	Tile Terraced	Alluminium	Good
Education	D.H.E. School West block.	Bonai.	S.S.	1948	..	226		Brick wall	AS flooring	R.C.C.	Alluminium	Good
Education	do (East block.)	Bonai.	S.S.	1948	..	211		Brick wall	AS flooring	R.C.C.	Alluminium	Good
Education	Govt. High School at Bonai.	Bonai.	S.S.	1948	..	1600		Brick wall	AS flooring	R.C.C.	Alluminium	Good
Education	do (Kitchn block)	Bonai.	S.S.	1980	..	50		Brick wall	AS flooring	Tile Terraced	Alluminium	Good
Education	RDD High School (Kitchen block)	Bonai.	S.S.	1948	..	50		Brick wall	AS flooring	Tile Terraced	Alluminium	Good
Education	Compound wall Govt. High School.	Bonai.	..	1980	..		111	Brick wall	AS flooring	Tile Terraced	Alluminium	Good
Education	Compound wall RDD high Schoo	Bonai.	..	2008	..		488	Brick wall		Comp. wall		
Education	Nehru block compound wall	Bonai.	..	2009	..		98	Brick wall		Comp. wall		
Education	Vocational bldg. Of RDD high school	Bonai.	S.S	1997	..	100		Brick wall	AS flooring	R.C.C.	Alluminium	Good
Education	Kitchen block RDD high school	Bonai.	S.S	2009	..	37		Brick wall	AS flooring	R.C.C.	Alluminium	Good
Education	Girls high school hostel bldg., Bonai	Bonai.	S.S.	2009	..	56		Brick wall	AS flooring	R.C.C.	Alluminium	Good
Education	Cycle stand of Girls high School	Bonai.	S.S.	2003	..	73		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Alluminium	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Education	Gopinathpur M.E.School at Bonai	Bonai.	S.S.	2000	..	149		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Govt. College at Rourkela (B Block.)	Rourkela.	D.S.	1976	..	1914		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	do (C Block.)	Rourkela.	D.S.	1976	..	2378		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	do (D Block.)	Rourkela.	D.S.	1976	..	3261		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	do (E Block.)	Rourkela.	D.S.	1976	..	3261		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Plus 2 Class room of Govt. College.	Rourkela.	D.S.	1976	..	66		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Boy's hostel do	Rourkela.	D.S.	1976	..	2621		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Lady's hostel do	Rourkela.	D.S.	1976	..	3407		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	High School building at Birmitrapur.	Birmitrapur.	S.S.	1976	..	930		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Hostel bldg. Of do	Birmitrapur.	S.S.	1976	..	930		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	M.E. School bldg.& Science Lab.	Birmitrapur.	S.S.	1976	..	259		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	High School extension portion.	Birmitrapur.	S.S.	1976	..	100		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	M.E. School hostel No.1.	Birmitrapur.	S.S.	1976	..	105		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Iron door	Good
Education	M.E. School hostel No.2	Birmitrapur.	S.S.	1976	..	188		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Iron door	Good
Education	Govt. High School at Uditnagar.	Rourkela.	D.S.	1962	..	2735		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Govt. Girls High School, Uditnagar.	Rourkela.	S.S.	1962	..	2657		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	S.I. Office building at Uditnagar.	Rourkela.	S.S.	1963	..	48		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	D.I Office building at Uditnagar.	Rourkela.	S.S.	1971	..	136		Brick wall	AS flooring	R.C.C.	Iron door	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Education	B.E.D. College, Nayabazar, Rourkela.	Rourkela.	S.S.	1975	..	5598		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Open air Auditorium of Govt. College.	Rourkela.	..	1988	..	196		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Compound wall of Girls High School.	Rourkela.	..	1984	..		180	Brick wall		Comp. wall		
Education	do Ladies hostel of Govt. College.	Rourkela.	..	1994	..		160	Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Vocational Shed at RDD High School.	Rourkela.	S.S.	2001	..	160		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Library bldg. at Govt. College (GF)	Rourkela	S/s	1999	1999	247		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Extension room at Govt. College	Rourkela	S/s	2006	2006	21		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Comp. wall around Govt. College	Rourkela		2001	2001		1009	Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	SG womens College, Sector-2							Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	SG womens College, Sector-2 a) Administrative block.	Rourkela	S/s	1957	1957	110		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	SG womens College, Sector-2 b) Class room & lab. Block.	Rourkela	S/s	1980	1980	475		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	SG womens College, Sector-2 c) Student common room.	Rourkela	S/s	2001	2001	56		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	SG womens College, Sector-2 d) Library & Phy. Hsc. Block	Rourkela	S/s	1957	1957	516		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	SG womens College, Sector-2 e) Class room 2 nos.	Rourkela	S/s	2003	2003	84		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	SG womens College, Sector-2 f) Sub-station.	Rourkela	S/s	1957	1957	20		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	SG womens College, Sector-2 g) Boundary wall	Rourkela	..	2006	2006		345	Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Rourkela College, Sector.-4							Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Rourkela College, Sector.-4 a) Administrative block.	Rourkela	S/s	1957	1957	641		Brick wall	AS flooring	R.C.C.	Iron door	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Education	Rourkela College, Sector.-4 b) Auditorium block.	Rourkela	S/s	1957	1957	614		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Rourkela College, Sector.-4 c) Unit - 1 Class room 1 to 15	Rourkela	S/s	1957	1957	1961		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Rourkela College, Sector.-4 d) Girls common room.	Rourkela	S/s	2005	2005	56		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Rourkela College, Sector.-4 e) Boys common room.	Rourkela	S/s	2001	2001	37		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Rourkela College, Sector.-4 f) Class room 2 nos.	Rourkela	S/s	1957	1957	93		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Rourkela College, Sector.-4 g) Cycle stand 2 nos.	Rourkela	S/s	1957	1957	218		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Rourkela College, Sector.-4 h) Lab. Hall Phy, Che., Zool.	Rourkela	S/s	1957	1957	322		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Rourkela College, Sector.-4 i) Lab. Hall Bot., & Phy.	Rourkela	S/s	1957	1957	243		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Rourkela College, Sector.-4 j) Boundary wall	Rourkela		1998	1998		300	Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Municipal. College, Rourkela,							Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Municipal. College, Rourkela. a) Main building.	Rourkela	D/s	1984	1984	1050		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Municipal. College, Rourkela, b) Lecturer Theature 2 nos.	Rourkela	S/s	1984	1984	217		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Municipal. College, Rourkela, c) Library building	Rourkela	D/s	2001	2001	302		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Municipal. College, Rourkela, d) Chemistry block.	Rourkela	S/s	1984	1984	263		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Municipal. College, Rourkela, e) Gallery Lt. 2 and 3	Rourkela	D/s	1984	1984	705		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Municipal. College, Rourkela, f) Cycle & M. Cycle stand.	Rourkela	S/s	2002	2002	154		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Municipal. College, Rourkela, g) Canteen building.	Rourkela	S/s	2001	2001	53		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Municipal. College, Rourkela, h) Boundary wall.	Rourkela		1984	1984		116	Brick wall	AS flooring	R.C.C.	Iron door	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compund wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Education	Girls high school building	Birmitrapur	S/s	2004	2004	325		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Compound wall for -do-	Birmitrapur		2002	2002		550	Brick wall		Comp. wall		
Education	Govt. High school	Birmitrapur	S/s	1999	1999	170		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Comp. wall for Boys high school bldg.	Birmitrapur		2002	2002		500	Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	- do- Hostel building for -do-	Birmitrapur		2001	2001		200	Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	-do- M.E. School building	Birmitrapur		2002	2002		430	Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Pendal of Girls high school, Uditnagar	Rourkela.	S/s	2009	2009	62		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Cycle stand at -do-	Rourkela.	S/s	2007	2009	90		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Pendal of Govt. high school, Uditnagar.	Rourkela.	S/s	2008	2009	72		Brick wall	AS flooring	R.C.C.	Iron door	Good
Education	Cycle stand at -do-	Rourkela.	S/s	2008	2009	95	430	Brick wall	AS flooring	R.C.C.	Iron door	Good
H & T.W.	ITDA Office at Uditnagar.	Rourkela.	S.S	1964	..	95		Brick wall	AS flooring	R.C.C.	Iron door	Good
H & T.W.	Kamla Neheru Adivasi hostel	Rourkela.	D.S	1964	..	6205		Brick wall	AS flooring	R.C.C.	Iron door	Good
H & T.W.	Compound wall of do	Rourkela.	..	1964	..		180	Brick wall		Comp. wall		
H & T.W.	Hostel building for Birmitrapur	Birmitrapur.	S.S	1980	..	334		Brick wall	AS flooring	R.C.C.	Iron door	Good
H & T.W.	S.S. High School at Birmitrapur.	Birmitrapur.	S.S	1980	..	513		Brick wall	AS flooring	R.C.C.	Iron door	Good
H & T.W.	100 seated ST girls hostel at Govt. College, Rourkela.	Rourkela.	D.S	2007	..	1167	..	Brick wall	AS flooring	R.C.C.	Irron door	Good
A. & H.	Border Cum Range House at Bonai	Bonai	S.S	1966	..	58		Brick wall	AS flooring	Tile Terraced	Irron door	Good
A. & H.	Poultry Shed at do	Bonai	S.S	1966	..	58		Brick wall	AS flooring	Tile Terraced	Irron door	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
A. & H.	Treatment Shed do	Bonai	S.S	1957	..	35		Brick wall	AS flooring	Tile Terraced	Irron door	Good
A. & H.	Annimal Room at do	Bonai	S.S	1957	..	35		Brick wall	AS flooring	Tile Terraced	Irron door	Good
A. & H.	Bull Shed at do	Bonai	S.S	1957	..	35		Brick wall	AS flooring	Tile Terraced	Irron door	Good
A. & H.	Vetertenary Office bldg. At Bonai.	Bonai	S.S	1957	..	43		Brick wall	AS flooring	R.C.C.	Irron door	Good
A. & H.	S.D.V.O office building at Bonai.	Bonai	S.S	1960	..	43		Brick wall	AS flooring	Tile Terraced	Irron door	Good
A. & H.	Additional & alteration to Vet.Office.	Bonai	S.S	1991	..	58		Brick wall	AS flooring	R.C.C.	Irron door	Good
A. & H.	Compound wall of SDVO Office at Bonai.	Bonai	..	2008	..		146	Brick wall		Comp. wall		
A. & H.	Live Stock Centre at Birmitrapur.	Birmitrapur.	S.S	1960	..	143		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Irron door	Good
A. & H.	Bull shed and attendant Qrs.	Birmitrapur.	S.S	1960	..	49		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Irron door	Good
A. & H.	Intensive egg and Marketing Centre	Rourkela	S.S	1979	..	716		Brick wall	AS flooring	R.C.C.	Irron door	Good
A. & H.	Poultry Farm Market Centre.	Rourkela	S.S	1980	..	486		Brick wall	AS flooring	R.C.C.	Irron door	Good
A. & H.	Garrage bldg. At Sectore-14	Rourkela	S.S	1980	..	39		Brick wall	AS flooring	R.C.C.	Irron door	Good
A. & H.	Treatment shed at -do-	Rourkela	S.S	1981	..	207		Brick wall	AS flooring	R.C.C.	Irron door	Good
A. & H.	Veternary dispensary bldg. At S.T.I.	Rourkela	S.S	1970	..	62		Brick wall	AS flooring	R.C.C.	Irron door	Good
A. & H.	Treatment shed at S.T.I.	Rourkela	S.S	1970	..	206		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Irron door	Good
A. & H.	Bull shed indoor at S.T.I.	Rourkela	S.S	1970	..	49		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Irron door	Good
A. & H.	Compound wall of Veternary Office.	Rourkela	..	1970	..		310	Brick wall	AS flooring	A.C.S. & G.C.I.S.	Irron door	Good
A. & H.	Large & small animal operation theater of Vety hospital at Rourkela.	Rourkela	S.S	2009	2009	107	..	Brick wall	AS flooring	A.C.S. & G.C.I.S.	Irron door	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
A.J.	A.C.J.M. building at Rourkela.	Rourkela.	S.S	1992	..	250		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Irron door	Good
A.J.	Civil Judge (S.D) at Uditnagar.	Rourkela.	S.S	1982	1998	354		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Irron door	Good
A.J.	First track court bldg.	Rourkela	S/s	2005	2005	75		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Irron door	Good
A.J.	First track court building	Bonai	S/s	2005	2005	78		Brick wall	AS flooring	A.C.S. & G.C.I.S.	Irron door	Good
A.J.	Compound wall of Court bldg.	Birjapalli		1999	1999		350	Brick wall		Comp. wall		
Health	Dispensary bldg. At Bonai.	Bonai.	S.S	1920	..	992		Brick wall	AS flooring	Tile Terraced	Irron door	Good
Health	Maternity ward at Bonai.	Bonai.	S.S	1920	..	95		Brick wall	AS flooring	Tile Terraced	Irron door	Good
Health	Segregation Ward (Old) at Bonai	Bonai.	S.S	1962	..	104		Brick wall	AS flooring	R.C.C.	Irron door	Good
Health	do (New)	Bonai.	S.S	1971	..	104		Brick wall	AS flooring	R.C.C.	Irron door	Good
Health	Compound Wall of Health Deptt.	Bonai.	..	1973	..		391	Brick wall		Comp. wall		
Health	O&G, OT at SD hospital, Bonai	Bonai.	S.S	1996	..	290		Brick wall	Mosaic	R.C.C.	Wooden & Aluminium	Good
Health	10 beded Eye ward at SD hospital, Bonai	Bonai.	S.S	2000	..	260		Brick wall	Mosaic	R.C.C.	Wooden	Good
Health	Hostel bldg. At SD hospital, Bonai	Bonai.	S.S	2000	..	114		Brick wall	AS flooring	R.C.C.	Wooden	Good
Health	X-ray bldg. At SD hospital, Bonai	Bonai.	S.S	2000	..	80		Brick wall	AS flooring	R.C.C.	Wooden	Good
Health	Upgradation of Labour room & OT at SD hospital, Bonai	Bonai.	S.S	2009	..	52		Brick wall	AS flooring	R.C.C.	Wooden	Good
Health	Cabin at S.D. hospital, Bonai	Bonai.	S.S	2006	..	47		Brick wall	AS flooring	R.C.C.	Wooden	Good
Health	Store room at SD hospital Bonai.	Bonai.	S.S	2007	..	43		Brick wall	AS flooring	R.C.C.	Wooden	Good
Health	Extension of hospital & 3 nos. of toilet at SD hospital, Bonai.	Bonai.	S.S	2000	..	158		Brick wall	AS flooring	R.C.C.	Wooden	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Health	R.G.H. building at Rourkela	Rourkela	D.S	1978	..	2911		Brick wall	AS flooring	R.C.C.	Wooden	Good
Health	Latrine block of RGH do	Rourkela	S.S	1978	..	130		Brick wall	AS flooring	R.C.C.	Wooden	Good
Health	Strilisation Ward do	Rourkela	S.S	1978	..	176		Brick wall	AS flooring	R.C.C.	Wooden	Good
Health	Labour Room & Store Room do	Rourkela	S.S	1978	..	27		Brick wall	AS flooring	R.C.C.	Wooden	Good
Health	Hospital Building at Raghunathpalli	Rourkela	S.S	1956	..	824		Brick wall	AS flooring	Tile Terraced	Wooden	Good
Health	Patient Ward at do	Rourkela	S.S	1956	..	412		Brick wall	AS flooring	Tile Terraced	Wooden	Good
Health	Postmortum Shed at do	Rourkela	S.S	1956	..	28		Brick wall	AS flooring	Tile Terraced	Wooden	Good
Health	Utkalmani Homeopathic Medical College & Hospital bldg. at Nayabazar	Rourkela	D.S	1996	2003	850		Brick wall	AS flooring	Tile Terraced	Wooden	Good
Health	do Administrative block.	Rourkela	S.S	1990	2003	491		Brick wall	AS flooring	Tile Terraced	Wooden	Good
Health	do Departmental building.	Rourkela	S.S	1989	2003	373		Brick wall	AS flooring	Tile Terraced	Wooden	Good
Health	do Guest house.	Rourkela	S.S	1994	2003	47		Brick wall	AS flooring	Tile Terraced	Wooden	Good
Health	Neunetal Care Unit at R.G.H.	Rourkela	S/s	2007	2007	192		Brick wall	AS flooring	Tile Terraced	Wooden	Good
Health	I.P.D., O.T., Labour room at -do-	Rourkela	S/s	2003	2003	1537		Brick wall	AS flooring	Tile Terraced	Wooden	Good
Health	Washing & cleaning building -do-.	Rourkela	S/s	2003	2003	49		Brick wall	AS flooring	Tile Terraced	Wooden	Good
Health	Generator room at -do-	Rourkela	S/s	2003	2003	33		Brick wall	AS flooring	Tile Terraced	Wooden	Good
Health	Special cabin bldg. At RGH, Rourkela	Rourkela	S/s	1990		175		Brick wall	AS flooring	R.C.C.	Wooden D/W	Good
Health	Paedriatic bldg. At RGH, Rourkela.	Rourkela	D/s	1990		310		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Health	Infection bldg. At RGH, Rourkela	Rourkela	S/s	2001		305		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Health	Postmurtum & extention room for SDH	Panposh	S/s	2007	2007	136		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Health	C.H.C. building	Birmirapur	S/s	2003	2003	421		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Health	Ten beded eye ward at S.D.B.	Bonai	S/s	2000	2000	260		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Health	Major O.T. complex -do-	Bonai	S/s	2000	2000	158		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Health	Ten beded New block general -do-	Bonai	S/s	1997	1997	300		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Health	Hostel bldg. for S.D.H.	Bonai	S/s	2000	2000	114		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Agriculture	D.A.O. Office bldg. At Bonai.	Bonai	S.S	1988	..	259		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Agriculture	Training Hall of D.A.O. at Bonai.	Bonai	S.S	1991	..	120		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Agriculture	Garrage for D.A.O. Office at Bonai.	Bonai	S.S	1989	..	9		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Agriculture	Compound wall of do	Bonai	..	1992	..		100	Brick wall		Comp. wall		
Agriculture	Compound wall of do	Bonai	..	1992	..		50	Brick wall		Comp. wall		
Agriculture	Asst.Soil Conservation Office,Panposh	Rourkela.	S.S	1985	..	300		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Agriculture	do Godown at Panposh.	Rourkela.	S.S	1985	..	98		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Agriculture	D.A.O. Office bldg. At Panposh.	Rourkela.	S.S	1992	..	218		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Agriculture	Garrage of D.A.O. at Panposh.	Rourkela.	S.S	1992	..	25		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Agriculture	Horticulturist Office bldg. At Panposh.	Rourkela.	S.S	2002	2002	98		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Agriculture	Horticultural Office bldg. at Panposh	Rourkela	S/s	1972	1972	86		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Court building at Bonai.	Bonai	S.S	1913	..	735		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Revenue	Sub-Judge Office at Bonai	Bonai	S.S	1959	..	80		Brick wall	AS & Mosaic	A.C.S. & G.C.I.S.	MS & Wooden shutter	Good
Revenue	M.I.Office Building at Bonai	Bonai	S.S	1954	..	68		Brick wall	AS & Mosaic	A.C.S. & G.C.I.S.	MS & Wooden shutter	Good
Revenue	Revenue I.B.at Bonai	Bonai	S.S	1955	..	293		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Court building at Bonai.	Bonai	S.S	1988	..	360		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	do of SDO Chamber at Bonai	Bonai	S.S	1988	..	68		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	do of Urinal block	Bonai	S.S	1988	..	9		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Tahasil Office Building at Bonai	Bonai	S.S	1975	..	259		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	R.I.Waiting Hall at Bonai	Bonai	S.S	1988	..	9		Brick wall	AS & Mosaic	A.C.S. & G.C.I.S.	MS & Wooden shutter	Good
Revenue	Rest sged at Tahasil Office, Bonai	Bonai	S.S	2008	..	79		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Facilation Center at Tahasil Office, Bonai	Bonai	S.S	2009	..	33		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Facilation center at Sub Collector Office, Bonai.	Bonai	S.S	2009	..	33		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Tahasil Office at Biramitrapur	Biramitrapur	S.S	1988	..	446		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Office cum Excise S.I qr at Biramitrapur	Biramitrapur	S.S	1988	..	225		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	S.D.O. Court building at Uditnagar	Rourkela	S.S	1965	..	1454		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Sub-Register Office at Uditnagar	Rourkela	S.S	1970	..	348		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Malkhana building at Uditnagar.	Rourkela	S.S	1996	..	46		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Circuit House at Panposh.	Rourkela	S.S & D.S	1995	..	1034		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Office of the Officer on Spl. Duty.	Rourkela	S.S	1992	..	74		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good

Deptt. Name	Name of the Building	Location	Single/ Double/multi storied	Year of construct ruction	If taken over/pur chased	Total plinth area(Sqm)	Compound wall	Type of wall	Type of floor	Type of roof	Door window	Present condition on note the year
Revenue	Civil defence Office	Rourkela	S.S	1967	..	617		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	A.D.M. Office at Uditnagar.	Rourkela	S.S	1965	..	500		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Compound wall of Circuit House.	Rourkela	..	1967	..		180	Brick wall		Comp. wall		
Revenue	Compound wall of Court building.	Rourkela	..	1991	..		150	Brick wall		Comp. wall		
Revenue	Excise Office building at Uditnagar.	Rourkela	D.S	1998	1998	628		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Malkhana of Excise Inspector, Panposh	Rourkela	S.S	1996	1996	87		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Cycle stand at ADM Office, Rourkela	Rourkela	S.S	2009	2009	53		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Record room of Tahasil Office, B.Pur.	Biramitrapur	S.S	1994	1996	79		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	do at Bonai.	Bonai	S.S	1994	1997	79		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	RI office-cum- Residence	Bondamunda	S/s	1990	1990	70		Brick wall	AS & Mosaic	R.C.C.	MS & Wooden shutter	Good
Revenue	Bar Association bldg. (situated at Sub Collector's Office campus.	Rourkela	S/s D/s	1984	2008	437		Brick wall	AS & Mosaic	R.C.C.	Panneled D&W	Good