

JAGATSINGHPUR [R&B] DIVISION. JAGATSINGHPUR**PLINTH AREA OF RESIDENTIAL BUILDING**

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Works	Executive Engineer qtr at Jagatsinghpur	Municipality	one block	single	1972	202.70	173.22	Brick	brick	Tile	R.C.C.	Sal/Piasal	Damaged
Works	D.A.O qtr at jspur	Municipality	one block	single	1986	117.85		Brick	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	A.E qtr at jspur	Municipality	one block	single	1976	152.38		Brick	brick	Tile	R.C.C.	Sal/Piasal	Damaged
Works	J.E qtr at jspur	Municipality	one block	single	1976	108.25		Brick	brick	Tile	R.C.C.	Sal/Piasal	Damaged
Works	3/R qtr at jspur	Municipality	one block	single	1986	71.44	29.10	Brick	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	2/R qtr at jspur	Municipality	one block	single	1976	75.48	6.00	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	2/R qtr at jspur	Municipality	one block	single	1976	64.75	3.00	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	2/R qtr at jspur	Municipality	one block	single	1976	87.62	6.00	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	2/R qtr at jspur	Municipality	one block	single	1976	40.2	5.00	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	3/R qtr at jspur	Municipality	one block	single	1976	81.81	12.00	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	D' type qtr at jspur [G/F]	Municipality	one block	D/S	1996	92.03		Brick	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	E' type qtr at jspur [G/F]	Municipality	one block	D/S	1996	66.75		Brick	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	D' type qtr at jspur [F/F]	Municipality	one block	D/S	1996	92.03		Brick	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	E' type qtr at jspur [F/F]	Municipality	one block	D/S	1996	66.75		Brick	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	2/R qtr at jspur	Municipality	one block	single	1983	53.85		Brick /Col.	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	2/R qtr at jspur	Municipality	one block	single	1983	53.85		Brick /Col.	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	2/R qtr at jspur	Municipality	one block	single	1983	38.87		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	2/R qtr at jspur	Municipality	one block	single	1983	38.87		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	3/R qtr at jspur	Municipality	one block	single	1974	79.16	10.87	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	2/R qtr at Jspur	Municipality	one block	single	1974	25.77		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Works	2/R qtr at jspur	Municipality	one block	single	1974	64.56	5.79	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	2/R qtr at jspur	Municipality	one block	single	1974	54.36		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	2/R qtr at jspur	Municipality	one block	single	1974	33.84		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	2/R qtr at jspur	Municipality	one block	single	1976	90.1	14.85	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	2/R qtr at jspur	Municipality	one block	single	1976	65.9		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	2/R qtr at jspur	Municipality	one block	single	1976	68.35		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	2/R qtr at jspur	Municipality	one block	single	1976	74.5	6.40	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	3/R qtr at jspur	Municipality	one block	single	1975	104.07	22.92	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	3/R qtr at jspur	Municipality	one block	single	1975	97.02	9.14	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	2R qtr. at jspur	Municipality	one block	single	1975	74.12	7.32	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	2R qtr. at jspur	Municipality	one block	single	1975	62.82	9.45	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Works	"D" type qtr. for A.E. (R&B)Sub-divn. At Manijanga	Tirtol Block	one block	single	1985	120.00	100.00	Brick	brick	Tile	R.C.C.	Sal/Piasal	Damaged
Works	"D" type qtr. for J.E. (R&B)Section at Manijanga	Tirtol Block	one block	single	1986	110.00	30.00	Brick	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	"E" type qtr. for Cashier. (R&B)Sub-Divn at Manijanga	Tirtol Block	one block	single	1986	56.00	0.00	Brick	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	J.E.Qtr. at Taladanda	Block	one block	single	1982	102.00	20.00		brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	J.E.Qtr. at Fakirpada	Block	one block	single	1982	89.18	40.00		brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	J.E.Qtr. at Manpur	Block	one block	single	1982	83.61	0.00		brick	A.S.F	R.C.C.	Sal/Piasal	good
Works	J.E.Qtr. at Jaipur	Tirtol Block	one block	single	1982	92.90	20.00		brick	A.S.F	R.C.C.	Sal/Piasal	good
Works	J.E.Qtr. at Kantapada	Kantapada Block	one block	single	1983	61.31	0.00		brick	A.S.F	R.C.C.	Sal/Piasal	good
Works	J.E.Qtr. at Balikuda Jspur	Block	one block	single	1984	98.00	0.00		brick	A.S.F	R.C.C.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Works	F' type 2/R qtr R.H.S near S.K.Academy at jspur	Municipality	one block	single	1978	56.33	7.00	Brick	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	F' type 2/R qtr R.H.S near S.K.Academy at jspur	Municipality	one block	single	1978	56.33	7.00	Brick	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	F' type 2/R qtr R.H.S near S.K.Academy at jspur	Municipality	one block	single	1978	56.33	7.00	Brick	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Works	F' type 2/R qtr R.H.S near S.K.Academy at jspur	Municipality	one block	single	1979	56.34	8.00	Brick	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	Collector residence at jspur	Municipality	one block	single	1998	326.5	293.67	Brick /Col.	brick	A.S.F/tile	R.C.C.	Sal/Piasal	Damaged
Revenue	P.D D.R.D.A qtr at jspur jaipur road	Municipality	one block	single	1960	296.88	140.15	Brick	brick	A.S.F/tile	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Revenue	A.D.M qtr at Jspur	Municipality	one block	single	1980	208.77	53.03	Brick /col.	brick	A.S.F/tile	R.C.C.	Sal/Piasal	Damaged
Revenue	Sub-Collector qtr atr Jspur	Municipality	one block	single	1980	174.15	137.71	Brick work	brick	A.S.F/tile	R.C.C.	Sal/Piasal	Damaged
Revenue	Tahasildar qtr at jspur[3/R]	Municipality	one block	single	1960	192.41	109.42	Brick work	brick	A.S.F	Tile terraced	Sal/Piasal	Damaged
Revenue	Colectoriate staff qtr attach to kherasa R.I at jspur [2/R]	Municipality	one block		1975	95.14	52	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Revenue	D.P.O qtr at jspur jaipur road	Municipality	one block	single	1977	75.66	47.92	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	Colector driver & cook qtrs at jspur	Municipality	one block	single	1998	166.66		Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Revenue	'F' type qtr [2/R]at jspur for collectoriate staff at Jaipur road line [G/F]	Municipality	one block	D/S	1982	34.40		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	F' type qtr[2/R] at jspur for collectoriate staff at Jaipur road line [G/F]	Municipality	one block	D/S	1982	34.40		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	'F' type qtr [2/R]at jspur for collectoriate staff at Jaipur road line [F/F]	Municipality	one block	D/S	1982	34.40	39.16 RMT	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	'F' type qtr [2/R]at jspur for collectoriate staff at Jaipur road line [F/F]	Municipality	one block	D/S	1982	34.40		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	Sub- Register qtr at jspur	Municipality	one block	single	1960	129.00	149.04	Brick work	brick	A.S.F	Tile terraced	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Revenue	Sub- register staff qtr at jspur [2/R qtr]	Municipality	one block	single	1984	49.03	13.36	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	Sub- register staff qtr at jspur [2/R qtr]	Municipality	one block	single	1984	42.3	10.23	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	Sub register staff qtr at jspur [2/R qtr]	Municipality	one block	single	1984	61.04	22.65	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	3/R qtr near Tahasil colony	Municipality	one block	single	1984	89.59	13.71	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Revenue	Twin qtr at jspur near Tahsil colony [2/R]	Municipality	one block	single	1976	57.22	8.00	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Revenue	Twin qtr at jspur near Tahsil colony [2/R]	Municipality	one block	single	1976	54.89	8.00	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Do	Damaged
Revenue	Twin qtr at jspur near Tahsil colony [2/R]	Municipality	one block	single	1976	56.91	6.00	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Do	Damaged
Revenue	Twin qtr at jspur near Tahsil colony [2/R]	Municipality	one block	single	1976	57.09	6.00	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Do	Damaged
Revenue	Twin qtr at jspur near Tahsil colony [2/R]	Municipality	one block	single	1976	57.00	9.00	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Do	Damaged
Revenue	Twin qtr at jspur near Tahsil colony [2/R]	Municipality	one block	single	1976	57.00	9.00	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Do	Damaged
Revenue	3/R qtr at jspur near Tahasil colony.	Municipality	one block	single	1976	84.52	14.00	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Do	Damaged
Revenue	3/R qtr at jspur near Tahasil colony.[Ramesh ch .panda]	Municipality	one block	single	1976	80.80	14.00	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Do	Damaged
Revenue	'F' type qtr [D/S] at jspur near Tahasil colony[2/R] [G/F]	Municipality	one block	double	1982	45.00		Brick work	brick	A.S.F	R.C.C.	Do	Damaged
Revenue	'F' type qtr [D/S] at jspur near Tahasil colony[2/R] [G/F]	Municipality	one block	double	1982	45.00		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	'F' type qtr [D/S] at jspur near Tahasil colony[2/R] [F/F]	Municipality	one block	double	1982	45.00		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	'F' type qtr [D/S] at jspur near Tahasil colony[2/R] [F/F]	Municipality	one block	double	1982	45.00		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	2/R qtr in Tahasil campus []	Municipality	one block	single	1988	57.72	24.84	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	2/R qtr in Tahasil campus []	Municipality	one block	single	1988	57.42		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	E' type flat [M/S] near tahasil colony at jspur[G/F]	Municipality	one block	M/S	2009	67.16		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Good

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Revenue	E' type flat [M/S] near tahasil colony at jspur[G/F]	Municipality	one block	M/S	2009	67.16		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Good
Revenue	E' type flat [M/S] near tahasil colony at jspur[F/F]	Municipality	one block	M/S	2009	67.16		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Good
Revenue	E' type flat [M/S] near tahasil colony at jspur[F/F]	Municipality	one block	M/S	2009	67.16		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Good
Revenue	E' type flat [M/S] near tahasil colony at jspur[S/F]	Municipality	one block	M/S	2009	67.16		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Good
Revenue	E' type flat [M/S] near tahasil colony at jspur[S/F]	Municipality	one block	M/S	2009	67.16		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Good
Revenue	F' type flat [M/S] near tahasil colony at jspur[G/F]	Municipality	one block	M/S	2009	76.10		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Good
Revenue	F' type flat [M/S] near tahasil colony at jspur[G/F]	Municipality	one block	M/S	2009	76.10		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Good
Revenue	F' type flat [M/S] near tahasil colony at jspur[F/F]	Municipality	one block	M/S	2009	76.10		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Good
Revenue	F' type flat [M/S] near tahasil colony at jspur[F/F]	Municipality	one block	M/S	2009	76.10		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Good
Revenue	F' type flat [M/S] near tahasil colony at jspur[S/F]	Municipality	one block	M/S	2009	76.10		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Good
Revenue	F' type flat [M/S] near tahasil colony at jspur[S/F]	Municipality	one block	M/S	2009	76.10		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Good
Revenue	E type qtr in Tahasil campus	Municipality	one block	single	1982	61.73		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	2/R qtr in Tahasil campus	Municipality	one block	single	1982	45.00		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	2/R qtr in Tahasil campus	Municipality	one block	single	1982	45.00		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	'F' type qtr [D/S] at jspur near Tahasil colony[2/R] [G/F]	Municipality	one block	double	1982	45.00		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	'F' type qtr [D/S] at jspur near Tahasil colony[2/R] [F/F]	Municipality	one block	double	1982	45.00		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Revenue	'F' type qtr [D/S] at jspur near Tahasil colony[2/R] [G/F]	Municipality	one block	D/S	1982	45.00		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	'F' type qtr [D/S] at jspur near Tahasil colony[2/R] [F/F]	Municipality	one block	D/S	1982	45.00		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	D' type twin qtr at jspur near S.K.Academy	Municipality	one block	single	1982	91.00	25.00	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	D' type twin qtr at jspur near S.K.Academy	Municipality	one block	single	1982	91.00	25.00	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	Small savings officer qtr at jspur near sipi	Municipality	one block	single	1997	93.26	5.48	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	F type[2/R] qtr R.H.S near S.K.Academy at jspur	Municipality	one block	single	1978	75.84	5.28	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Revenue	F type[2/R] qtr R.H.S near S.K.Academy at jspur	Municipality	one block	single	1978	56.33	5.28	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Commerce	F' type [2/R]qtr for A.C.TO Staff at jspur	Municipality	One block	D/S	1984	34.28	33.52	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Commerce	F' type qtr[2/R] for A.C.TO Staff at jspur	Municipality		D/S	1984	34.28		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Commerce	F' type qtr[2/R] for A.C.TO Staff at jspur	Municipality	One block	D/S	1984	34.28		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Commerce	F' type[2/R] qtr for A.C.TO Staff at jspur	Municipality		D/S	1984	34.28		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Commerce	F' type [2/R]qtr for A.C.TO Staff at jspur	Municipality	one block	single	1984	36.00	33.52	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Commerce	D' type qtr for A.C.TO Staff at jspur	Municipality	one block	single	1984	120.30	18.28	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Commerce	E' type qtr for A.C.TO Staff at jspur	Municipality	one block	single	1984	98.70	17.67	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Cooperative	F type[2/R] qtr R.H.S near S.K.Academy at jspur	Municipality	one block	single	1978	56.33	7.00	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Agricultre	D.A.O qtr at jspur	Municipality	one block	single	1987	72.77		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Agricultre	J.A.O qtr at jspur	Municipality	one block	single	1987	55.09	8.55	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Agricultre	F type[2/R] qtr R.H.S near S.K.Academy at jspur	Municipality	one block	single	1978	56.33	5.28	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Education	D.I qtr at Jagatsinghpur near court bld.	Municipality	one block	single	1978	148.64	28.00	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Education	Headmaster qtr of S.K.Academy at jspur	Municipality	one block	single	1978	36.25	30.50	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Education	Staff qtr of Govt.Girls high school at jspur	Municipality	one block	single	1974	60.98	15.00	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Education	Staff qtr of Govt.Girls high school at jspur	Municipality	one block	single	1974	60.98	15.00	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Education	Staff qtr of Govt.Girls high school at jspur	Municipality	one block	single	1974	60.98	15.00	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Education	Staff qtr of Govt.Girls high school at jspur	Municipality	one block	single	1974	60.98	15.00	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Education	2R qtr of D.I of school jagatsinghpur near court campous	Municipality	one block	single	1973	102.00	8.00	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Education	2R qtr of D.I of school jagatsinghpur near court campous	Municipality	one block	single	1973	130.00	10.00	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Education	F type[2/R] qtr R.H.S near S.K.Academy at jspur	Municipality	one block	single	1978	56.33	5.28	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Finance	Treasure officer qtr at jspur near Tahasil coly.	Municipality	one block	single	2006	95.54		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Finance	F type[2/R] qtr R.H.S near S.K.Academy at jspur	Municipality	one block	single	1978	56.33	7.00	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	ADJ residence at jspur,Sipi [G/F& F/F]	Municipality	one block	single	1998	167.21	60.95	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	Sub-judge residence at jspur,Sipi [G/F& F/F]	Municipality	one block	single	1998	167.21	259.91	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	CJM qtr at jspur near sipi.	Municipality	one block	single	1998	114.81	65.53	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	JMFC residence at sipi	Municipality	one block	single	1998	139.19	55.77	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	SDJM qr at jspur near court campous	Municipality	one block	single	1998	102.00	150.00	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Home	Munsuf qtr at block colony jspur	Municipality	one block	single	1973	157.93	16.76	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Home	S.P residence cum office at jspur	Municipality	one block	single	1998	462.85	223.72	Brick work/COL.	brick	A.S.F/TILE	R.C.C.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Home	P.S staff qtr at Jspur inside p.s campous. [DSP]	Municipality	one block	single		161.19	78.48	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	3/R qtr for I.IC at jspur p.s campous	Municipality	one block	single		124.18	7	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	2/R qtr for A.S.I at jspur p.s campous	Municipality	one block	single		111.4	15.89	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Home	2/R qtr for Steno at jspur p.s campous	Municipality	one block	single		88.90	21.18	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Home	2/R qtr for Inispector at jspur p.s campous	Municipality	one block	single		84.42	12.64	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Home	2/R qtr for S.I at jspur p.s campous	Municipality	one block	single		85.96	5.94	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Home	'F' type qtr P.S premises at jspur[G/F]	Municipality	one block	D/S	2006	38.54		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr P.S premises at jspur[G/F]	Municipality	one block	D/S	2006	38.54		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr P.S premises at jspur[F/F]	Municipality	one block	D/S	2006	38.54		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr P.S premises at jspur[G/F]	Municipality	one block	D/S	2004	38.54		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr P.S premises at jspur[G/F]	Municipality	one block	D/S	2004	38.54		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr P.S premises at jspur[F/F]	Municipality	one block	D/S	2004	38.54		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr P.S premises at jspur	Municipality	one block	single	1990	38.54		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr P.S premises at jspur	Municipality	one block	single	1990	38.54		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr P.S premises at jspur	Municipality	one block	single	1990	38.54		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	P.S staff qtr at Jspur inside p.s campous. Occupied by C.Mohapatra S.D.P.O	Municipality	one block	single		130.02	42.36	Brick work	brick	A.S.F	Tile terraced	Sal/Piasal	Damaged
Home	P.S staff qtr at Jspur inside p.s campous. Occupied by R.k.Jena Dsp	Municipality	one block	single		98.58	7.30	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Home	P.S staff qtr at Jspur inside p.s campous. Occupied by Samal S.I	Municipality	one block	single		95.23	7.30	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Home	P.S staff qtr at Jspur inside p.s campous. [VACANT]	Municipality	one block	single		64.17	9.14	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr P.S permises at jspur	Municipality	one block	single		38.54		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr P.S permises at jspur	Municipality	one block	single		38.54		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'E' type qtr.at District Head qtr. Jagatsinghpur[1 block M/S] [G/F] E/1	Block	one block	M/S	2006	72.27		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'E' type qtr.at District Head qtr. Jagatsinghpur[1 block M/S] [G/F] E/2	Block	one block	M/S	2006	72.27		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'E' type qtr.at District Head qtr. Jagatsinghpur[1 block M/S][F/F]-E/3	Block	one block	M/S	2006	72.27		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'E' type qtr.at District Head qtr. Jagatsinghpur[1 block M/S] [F/F]E/4	Block	one block	M/S	2006	72.27		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'E' type qtr.at District Head qtr. Jagatsinghpur[1 block M/S] [S/F]-E/5	Block	one block	M/S	2006	72.27		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'E' type qtr.at District Head qtr. Jagatsinghpur[1 block M/S] [S/F]-E/6	Block	one block	M/S	2006	72.27		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'E' type qtr.at District Head qtr. Jagatsinghpur[1 block M/S] [G/F] E/1	Block	one block	M/S	2006	72.27		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'E' type qtr.at District Head qtr. Jagatsinghpur[1 block M/S] [G/F] E/2	Block	one block	M/S	2006	72.27		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'E' type qtr.at District Head qtr. Jagatsinghpur[1 block M/S][F/F]-E/3	Block	one block	M/S	2006	72.27		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Home	'E' type qtr.at District Head qtr. Jagatsinghpur[1 block M/S] [F/F]E/4	Block	one block	M/S	2006	72.27		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'E' type qtr.at District Head qtr. Jagatsinghpur[1 block M/S] [S/F]-E/5	Block	one block	M/S	2006	72.27		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'E' type qtr.at District Head qtr. Jagatsinghpur[1 block M/S] [S/F]-E/6	Block	one block	M/S	2006	72.27		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.1 G/F-F/1	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.1 G/F -F/2	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.1 S/F -F/3	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.1 F/F-F/4	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.1 S/F-F/5	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.1 S/F-F/6	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.2 G/F-F/7	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.2 G/F -F/8	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.2 S/F-F/9	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.2 F/F-F/10	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.2 S/F-F/11	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.2S/F-F/12	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. –Jagatsinghpur[6 block M/S] BLOCK.3G/F-F/13	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.3 G/F –F/14	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.3S/F –F/15	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.3 F/F-F/16	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.3S/F-F/17	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.3S/F –F/18	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.4G/F-F/19	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.4 G/F -F/20	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.4 S/F-F/21	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.4 F/F-F/22	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.4 S/F-F/23	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.5 G/F-F/24	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.5 G/F -F/25	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.5 S/F-F/26	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.5 F/F-F/27	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.5S/F-F/28	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.5 S/F -F/29	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.6 G/F-F/30	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.6 G/F -F/31	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.6 F/F -F/32	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.6 F/F-F/33	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.6 S/F-F/34	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.6 S/F -F/35	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur[6 block M/S] BLOCK.6 S/F -F/36	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur F/1	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur F/2	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur F/3	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur F/4	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur F/5	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	'F' type qtr.at District Head qtr. Jagatsinghpur -F/6	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [G/F] -F/1	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur[G/F] –F/2	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur[F/F] –F/3	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [F/F] –F/4	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur[S/F] –F/5	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/6	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/7	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/8	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/9	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/10	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/11	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/12	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [G/F] –F/13	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur[G/F] –F/14	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur[F/F] –F/15	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [F/F] –F/16	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur[S/F] –F/17	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/18	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/19	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/20	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/21	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/22	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/23	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/24	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [G/F] –F/25	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur[G/F] –F/26	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur[F/F] –F/27	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [F/F] –F/28	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/29	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Home	30 Nos 'F' type qtr.at District Head qtr. Jagatsinghpur [S/F] –F/30	Block	one block	M/S	2006	38.55		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
A.H. & V.S.	V.A.S qtr at jspur behind S.P office [2/R]	Municipality	one block	single	1972	113.32	7.82	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
A.H. & V.S.	peon and chaukidar qtr near tretment shed at jspur[1/R]	Municipality	one block	single	1973	40.75	9.8	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
A.H. & V.S.	peon and chaukidar qtr near tretment shed at jspur[1/R]	Municipality	one block	single	1972	40.75	9.8	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
A.H. & V.S.	2/R staff qtr at jspur for the staff of vetenary near S.D.V.O office	Municipality	one block	single	1972	129.00	7.82	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Health	2/R qtr under D.H.H at jspur[G/F]	Municipality	one block	D/S	1983	16.46	32.92	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	2/R qtr under D.H.H at jspur[G/F]	Municipality	one block	D/S	1983	16.46	32.92	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	2/R qtr under D.H.H at jspur[F/F]	Municipality	one block	D/S	1983	16.46	32.92	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	2/R qtr under D.H.H at jspur[F/F]	Municipality	one block	D/S	1983	16.46	32.92	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	3/R qtr under D.H.H at jspur	Municipality	one block	single	1974	173.99	38.00	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	3/R qtr under D.H.H at jspur[Dr. N.Sahoo]	Municipality	one block	single	1973	176.43	60.00	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	2/R qtr under D.H.H at jspur[G/F]	Municipality	one block	D/S	1983	71.94		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Health	2/R qtr under D.H.H at jspur[F/F]	Municipality	one block	D/S	1983	71.94		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	. F type qtr for DHH at jspur[G/F]	Municipality	one block	D/S	1983	57.03		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	F type qtr for DHH at jspur[F/F]	Municipality	one block	D/S	1983	44.77	40.70	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	F type qtr for DHH at jspur[G/F]	Municipality	one block	D/S	1983	44.77		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	4 Nos. F type qtr for DHH at jspur[F/F]	Municipality	one block	D/S	1983	44.77		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	2/R qtr for the staff of DHH at jspur	Municipality	one block	single	1976	50.45	51.35	Brick work	brick	A.S.F	A.C.S. & G.C.I.S.	Sal/Piasal	Damaged
Health	2/R qtr for the staff of DHH at jspur	Municipality	one block	single	1976	95.79	33.5	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	2/R qtr for the staff of DHH at jspur	Municipality	one block	single	1976	70.50	33.5	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	'E' type qtr for DHH at jspur[G/F]	Municipality	one block	single	1976	171.32		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	'E' type qtr for DHH at jspur[F/F]	Municipality	one block	D/S	1983	99.32	68.75	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	'E' type qtr for DHH at jspur[G/F]	Municipality	one block	D/S	1983	171.32		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	2 Nos.[D/S] 'E' type qtr for DHH at jspur[F/F]	Municipality	one block	D/S	1983	99.32		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	'E' type qtr for DHH at jspur[G/F]	Municipality	one block	D/S	1983	105.78		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	'E' type qtr for DHH at jspur[F/F]	Municipality	one block	D/S	1983	105.78		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	2/R qtr for the staff of DHH at jspur	Municipality	one block	D/S	1983	63.96	58.92				R.C.C.	Sal/Piasal	Damaged
Health	'E' type qtr for DHH at jspur[G/F]	Municipality	one block	D/S	1983	111.93	172.00	Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	'E' type qtr for DHH at jspur[F/F]	Municipality	one block	D/S	1983	74.50		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	'E' type qtr for DHH at jspur[G/F]	Municipality	one block	D/S	1983	74.50		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	'E' type qtr for DHH at jspur[F/F]	Municipality	one block	D/S	1983	74.50		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	'E' type qtr for DHH at jspur[G/F]	Municipality	one block	D/S	1983	74.50		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/Double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Health	'E' type qtr for DHH at jspur[F/F]	Municipality	one block	D/S	1983	74.50		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	'E' type qtr for DHH at jspur[G/F]	Municipality	one block	D/S	2007	74.50		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged
Health	'E' type qtr for DHH at jspur[F/F]	Municipality	one block	D/S	2007	74.50		Brick work	brick	A.S.F	R.C.C.	Sal/Piasal	Damaged

JAGAT SinghPUR [R&B] DIVISION. JAGAT SinghPUR**PLINTH AREA OF NON-RESIDENTIAL BUILDING**

Dept. Name	Name of the Building	Location	Number of Residential	Single/double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Works	Division office at jspur	Municipality	one block	D/S	G/F-1974 F/F-1995	1038.44	194.34	brick	brick	A.S.F Mosaic & Tile	R.C.C.	sal/Piasal	Roof slab , flooring,plastering damaged
Works	Division office cycle stand at jspur	Municipality	one block	single	2005	34.37		brick	brick	A.S.F	A.C.S. & G.C.I.S.		Flooring damaged
Works	[R&B] section office at jspur	Municipality	one block	single	1978	204.53	49.68	brick	brick	A.S.F	R.C.C.	sal/Piasal	Door & window damaged
Works	Stoarge go-down at jspur	Municipality	one block	single	1980	242.42	52.73	brick	brick	A.S.F	R.C.C.	G.C.I	Roof slab damaged
Works	P.W.D I.B at JSPUR	Municipality	one block	single	1955	379.27	213.56	brick	brick	TILE	R.C.C.	sal/Piasal	Door and window of store room damaged.
Works	P.W.D ANNEX at jspur	Municipality	one block	single	1980	172.96	91.83	brick	brick	Mosic	R.C.C.	sal/Piasal	Plastering flooring damaged.
Works	P.W.D Garrage-1 at jspur	Municipality	one block	single	1980	69.96		brick	brick	Mosic	A.C.S. & G.C.I.S.	G.C.I	Plastering flooring damaged.
Works	P.W.D Garrage-2 at jspur	Municipality	one block	single	1982	50.11		brick	brick	ASF	R.C.C.	m.s grill	flooring damaged.
Works	Tirtol (R&B) Sub-Divn at Manijanga	Tirtol Block	one block	D/S	1982 & 2008	340.00	90.00	brick	brick	ASF	R.C.C.	sal/Piasal	good
Works	(R&B) Section at Manijanga	Tirtol Block	one block	Single	2008	30.00		brick	brick	ASF	R.C.C.	sal/Piasal	good
Works	Storage godown of Tirtol (R&B) Sub-Divn at Manijanga	Tirtol Block	one block	Single	1982	129.00		brick	brick	ASF	R.C.C.	sal/Piasal	Plastering flooring damaged.
Works	JE office building at Taladanda	Block	one block	Single	1985	79.67		brick	brick	ASF	R.C.C.	sal/Piasal	Door and window of store room ,Plastering flooring damaged.
Works	P.W.D I.B at Taladanda	Municipality	one block	single	1955	60.00	102.00	brick	brick	A.S.F	R.C.C.	sal/Piasal	Door and window of store room damaged.
Works	R&B Store at Taladanda	Block	one block	Single	1956	90.48		brick	brick	ASF	A.C.S. & G.C.I.S.	sal/Piasal	Door and window of store room ,Plastering flooring damaged.
Works	R&B Store at Balikuda R&B Section	Block	one block	Single	1982	150.31	266.30	brick	brick	ASF	R.C.C.	sal/Piasal	Plastering flooring damaged.
Works	JE office building at Balikuda (R&B)Section	Block	one block	Single	1982	90.85	15.00	brick	brick	ASF	R.C.C.	sal/Piasal	good
Works	I.B.Cum Sub-Division office at Fakirpada	Block	one block	Single	1982	111.48	150.00	brick	brick	ASF	R.C.C.	sal/Piasal	good
Works	J.E. office at Fakirpada	Block	one block	Single	1982	42.73		brick	brick	ASF	R.C.C.	sal/Piasal	good
Works	Storage godown at Fakirpada	Block	one block	Single	1950	30.66		brick	brick	ASF	R.C.C.	sal/Piasal	Door and window of store room ,Plastering flooring damaged.
Works	Storage godown at Fakirpada (A)	Block	one block	Single	1994	37.16		brick	brick	ASF	R.C.C.	sal/Piasal	Door and window of store room ,Plastering flooring damaged.
Works	Storage godown at Fakirpada (B)	Block	one block	Single	1994	53.88		brick	brick	ASF	R.C.C.	sal/Piasal	good
Works	Storage godown at Manpur	Block	one block	Single	1982	42.63		brick	brick	ASF	R.C.C.	sal/Piasal	good
Works	J.E. office at Manpur	Block	one block	Single	1982	27.87		brick	brick	ASF	R.C.C.	sal/Piasal	good
Works	Storage godown at Jaipur	Block	one block	Single	1982	55.74		brick	brick	ASF	R.C.C.	sal/Piasal	Plastering flooring damaged.

Dept. Name	Name of the Building	Location	Number of Residential	Single/double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Works	J.E. office at Niali	Block	one block	Single	1976	69.67		brick	brick	ASF	R.C.C.	sal/Piasal	Plastering flooring damaged.
Works	J.E. office at Kantapada	Block	one block	Single	1976	69.67		brick	brick	ASF	R.C.C.	sal/Piasal	Plastering flooring damaged.
Works	Storage godown at Kantapada	Block	one block	Single	1978	74.32		brick	brick	ASF	A.C.S. & G.C.I.S.	sal/Piasal	AC Sheet roofing, Plastering flooring damaged.
Works	Storage godown at Central Store, Balikuda,Cuttack	Block	one block	Single	1982	1105.13		brick	brick	ASF	A.C.S. & G.C.I.S.	sal/Piasal	AC Sheet roofing, Plastering flooring damaged.
Works	Section office Cum godown at Balikuda,	Block	one block	Single	1983	69.67		brick	brick	ASF	A.C.S. & G.C.I.S.	sal/Piasal	AC Sheet roofing, Plastering flooring damaged.
Works	Watchman shed at Balikuda	Block	one block	Single	1982	138.98		brick	brick	ASF	A.C.S. & G.C.I.S.	sal/Piasal	AC Sheet roofing, Plastering flooring damaged.
Works	Constn. Academy site office of JE at Balikuda,Ctc	Block	one block	Single	2008	69.54		brick	brick	ASF	R.C.C.	Al. door	good
Revenue	Collectoriate building at jspur [G/F]	Municipality	one block	M/S	1995	1734.66	400.00	column	brick	A.S.F, Mosaic,Tile	R.C.C.	sal/Piasal	Door &window choukath ,shuter and plastering, grading damaged
Revenue	Collectoriate building at jspur [F/F]	Municipality	one block	M/S	1995	1688.40		column	brick	A.S.F, Mosaic,Tile	R.C.C.	sal/Piasal	
Revenue	Collectoriate building at jspur [S/F]	Municipality	one block	M/S	1995	260.97		column	brick	A.S.F, Mosaic,Tile	R.C.C.	sal/Piasal	
Revenue	C omposite office building at jspur [G/F]	Municipality	one block	M/S	1974	891.73		column	brick	A.S.F, Mosaic,Tile	R.C.C.	sal/Piasal	Door &window choukath ,shuter and plastering, grading damaged
Revenue	C omposite office building at jspur F/F]	Municipality	one block	M/S	1974	857.60		column	brick	A.S.F, Mosaic,Tile	R.C.C.	sal/Piasal	
Revenue	C omposite office building at jspur [S/F]	Municipality	one block	M/S	1974	848.77		column	brick	A.S.F, Mosaic,Tile	R.C.C.	sal/Piasal	
Revenue	Red cross building at Jspur [collectrate]	Municipality	one block	single	1993	82.07		column	brick	A.S.F	R.C.C.	sal/Piasal	Door &window choukath ,shuter and plastering damaged
Revenue	Rail way Ticket booking counter at jspur[collectrate]	Municipality	one block	single	1990	74.45		column	brick	A.S.F/TILE	R.C.C.	sal/Piasal	Door &window choukath ,shuter and plastering damaged
Revenue	Cycle shed for the collector office staff.	Municipality	one block	single	1995	136.19		Brick	brick	A.S.F	A.C.S. & G.C.I.S.		Flooring damaged
Revenue	Cycle shed for the sub- collector office staff.	Municipality	one block	single	1974	148.87		column	brick	A.S.F	R.C.C.		Rainforcement of roof slab exposed severely and building is un safe.
Revenue	Staff canteen for staff of collector office at jspur	Municipality	one block	single	1974	133.3		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Door &window choukath ,shuter and plastering, flooring damaged
Revenue	District Emergency office .	Municipality	one block	single	1997	91.04		column	brick	A.S.F	R.C.C.	sal/Piasal	Door and window partly damaged.
Revenue	Facilitation center attached to composite office building [G/F]	Municipality	one block	D/S	2009	41.26		column	brick	tile	R.C.C.	Al. Shutter	Good
Revenue	Facilitation center attached to composite office building [F/F]	Municipality	one block	D/S	2009	11.38		column	brick	tile	R.C.C.	Al. Shutter	Good
Revenue	Tahasil office building at jspur [G/F]	Municipality	one block	D/S	1953	477.41		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Good
Revenue	Tahasil office building at jspur [F/F]	Municipality	one block	D/S	1953 & 2009	148.91		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Roof leaking, door and window damaged of old block

Dept. Name	Name of the Building	Location	Number of Residential	Single/double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Revenue	Touze section of Tahasil jagatsinghpur .	Municipality	one block	single	1981	5.34		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Door & window choukath ,shuter and plastering, flooring damaged
Revenue	Cerificate section at jagatsinghpur Tahasil.	Municipality	one block	single	1959	55.27		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	Door & window choukath ,shuter and plastering, flooring damaged and leakage of roof.
Revenue	Sub- Registrar office building at jspur	Municipality	one block	single	1978	367.36	116.43	Brick	brick	A.S.F	R.C.C.	sal/Piasal	Plastering flooring damaged
Revenue	R.I Office at Galupada at jspur	Municipality	one block	single	1959	89.87	18.28	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	A.C.Sheet roof leaking Door & window choukath ,shuter and plastering, flooring damaged .
Revenue	R.I Office kherasa at jspur	Municipality	one block	single	1960	80.54	27.53	Brick	brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	A.C.Sheet roof leaking Door & window choukath ,shuter and plastering, flooring damaged .
Revenue	Officer's club at jspur near circuit house.	Municipality	one block	single	1997	121.8	132.28	column	brick	A.S.F	R.C.C.	sal/Piasal	Roof leaking, Door & window choukath ,shutter and plastering, flooring damaged .
Revenue	Circuit house at jspur [G/F]	Municipality	one block	D/S	1998	450.8	501.39	column	brick	Mosaic,Tile	R.C.C.	sal/Piasal	Out side plaster and grading damaged
Revenue	Circuit house at jspur [F/F]	Municipality	one block	D/S	1998	314.46		column	brick	Mosaic,Tile	R.C.C.	sal/Piasal	Out side plaster and grading damaged
Agriculture	D.A.O office building at jspur	Municipality	one block	single	1982 & 2008	618.88	271.44	Brick	brick	A.S.F	R.C.C.	sal/Piasal	Roof leaking, Door & window choukath ,shutter and plastering, flooring of old block damaged .
Finance	Pensioners rest shed at jspur [G/F]	Municipality	one block	D/S	2007	86.43	271.44	Brick	brick	A.S.F	R.C.C.	sal/Piasal	Good
Finance	Treasury rest shed at jspur [F/F]	Municipality	one block	D/S	2007	36.63	271.44	Brick	brick	A.S.F	R.C.C.	sal/Piasal	Good
Education	Head master office of S.K.Academy	Municipality	One block	single	1960	112.4		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	A.C.Sheet roof leaking , door and window damaged.
Education	Office of S.K. Academy at jspur [C.I OFFICE]	Municipality	One block	single	1982	46.74		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Platering flooring damaged
Education	Class room of S.K.Academy at jspur-BLOCK-1	Municipality	One block	single	1960	358.82		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Repair and Renovation work taken up under 12th F.C.A during 2008/09
Education	Class room of S.K.Academy at jspur-BLOCK-2	Municipality	One block	single	1967	395.49		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	Door and windows flooring damaged,A.C.Sheet roof damaged.
Education	Class room of S.K.Academy at jspur-BLOCK-3	Municipality	One block	single	1972	130.43		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Door and windows flooring damaged,A.C.Sheet roof damaged.
Education	Class room of S.K.Academy at jspur-BLOCK-4	Municipality	One block	single	1972	222.68		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Door and windows flooring damaged,A.C.Sheet roof damaged.
Education	Class room of S.K.Academy at jspur[SCIENCE BLOCK]	Municipality	One block	single	1982	68.28		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Good
Education	Cyclone shellter cum class rooms of S.K.A cademy at jspur. G/F]	Municipality	One block	single	2003	150.00		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Door and windows partly damaged.

Dept. Name	Name of the Building	Location	Number of Residential	Single/double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Education	Cyclone shelter cum class rooms of S.K.Academy at jspur. [F/F]	Municipality	One block	single	2003	150.00		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Door and windows partly damaged.
Education	Cycle stand of S.K.Academy at jspur	Municipality	One block	single	2005	57.80		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	Flooring damaged and roofing partly damaged
Education	Vocational bldg. of S.K.Academy at jspur	Municipality	One block	single	2000	89.05		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Roof leaking, Door & window choukath ,shutter and plastering, flooring damaged .
Education	Compound wall of S.K.Academy at jspur	Municipality	One block	single	1980		320.95	Brick	brick		Comp. wall		partly damaged.
Education	Class room of S.K.Academy at jspur [now functioning of C.I Office]	Municipality	One block	single	1970	314.39		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	Partly damage of A.C.Sheet door window choukath shutter damaged.
Education	D.I of school at jspur	Municipality	One block	single	1960	455.95		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Door and windows damaged
Education	Cycle stand of D.I of school at jspur	Municipality	One block	single	2008	38.55		Brick	brick	A.S.F	A.C.S. & G.C.I.S.		Good
Education	Govt,Girls High school at jspur [G/F]	Municipality	One block	D/S	1958	509.26	483.1	Brick	brick	A.S.F	R.C.C.	sal/Piasal	Door,window choukath, shutter ,plastering flooring damaged.
Education	Govt,Girls High school at jspur [F/F]	Municipality	One block	D/S	1965	509.26		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Door,window choukath, shutter ,plastering flooring damaged and roof leaking.
Education	Watch man shed at govt. girls high school at jspur	Municipality	One block	single	1960	38.85		Brick	brick	A.S.F	A.C.S. & G.C.I.S.		Partly damage of A.C.Sheet door window choukath shutter damaged.
Education	Govt.Girls highschool at jspur [class room] BLOCK-1	Municipality	One block	single	1962	91.00		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Door,window choukath, shutter ,plastering flooring damaged and roof leaking.
Education	Govt.Girls highschool at jspur [class room] BLOCK-2	Municipality	One block	single	1962	182.35		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Door,window choukath, shutter ,plastering flooring damaged and roof leaking.
Education	Govt.Girls highschool at jspur [class room] BLOCK-3	Municipality	One block	single	1962	138.52		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	Partly damage of A.C.Sheet door window choukath shutter damaged.
Education	Govt.Girls high school hostel bldg at jspur [C.T]	Municipality	One block	single	1968	419.67		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	Partly damage of A.C.Sheet door window choukath shutter damaged.
Education	Govt.Girls high school hostel lartine & urinal block at jspur	Municipality	One block	single	1977	30.19		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Door,window choukath, shutter ,plastering flooring damaged and roof leaking.
Education	Govt.Girls highschool hostel bldg at jspur	Municipality	One block	single	1979	427.43		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Door,window choukath, shutter ,plastering flooring damaged and roof leaking.

Dept. Name	Name of the Building	Location	Number of Residential	Single/double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Education	Auditorium of Govt.Girls high school at jspur	Municipality	One block	single	2006	289.08		Brick	brick	A.S.F	R.C.C.	sal/Piasal	Good
Education	Cycle stand of Govt.Girls high school at jspur	Municipality	One block	single	2006	52.95		Brick	brick		A.C.S. & G.C.I.S.		A.C.Sheet roof leaking , Flooring damaged.
Home	ADJ court building at jspur Near collectarate]	Municipality	One block	D/S	1994 & 1997	562.08		column	brick	A.S.F	R.C.C.	sal/Piasal	Good
Home	S.D.J.M court building at jspur near collectarate.	Municipality	One block	single	1972	112.31		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	A.C.Sheet roof leaking , door and window damaged.
Home	JMFC court building at jspur	Municipality	One block	single	1974	296.35		Brick	brick	A.S.F	R.C.C.	sal/Piasal	old A.C.Sheet building demolished and new building taken up under 12th F.C.A during 2008-09.
Home	CJM court building at jspur	Municipality	One block	single	1976	207.03		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	A.C.Sheet roof leaking , door and window damaged.
Home	Court Hazat at jspur [SDJM] at jspur	Municipality	One block	single	1972	87.53		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	A.C.Sheet roof leaking , door and window damaged.
Home	Malkhana of SDJM court building at jspur	Municipality	One block	single	1972	184.87		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	A.C.Sheet roof leaking , door and window damaged.
Home	Bar association building at jspur[sdjm court permises]	Municipality	One block	single	1988	58.85		Brick	brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	A.C.Sheet roof leaking , door and window damaged.
Home	S.P office building at jspur	Municipality	One block	D/S	2005	580.7	228.00	COLUMN	brick	A.S.F	R.C.C.	sal/Piasal	Good
Home	New P.S building at jspur	Municipality	One block	single	1993	257.80		COLUMN	brick	A.S.F	R.C.C.	sal/Piasal	Good
Home	Police Barrack at Jspur inside p.s campas.at jspur	Municipality	One block	single	1950	174.47		Brick	Brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	A.C.Sheet roof leaking , door and window damaged.
Home	Police Barrack at Jspur inside p.s campas at jspur .	Municipality	One block	single	1998	227.00		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Door and window damaged.
Home	Police Barrack at Jspur inside p.s campas at jspur.	Municipality	One block	single	1977	127.73		Brick	Brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	A.C.Sheet roof leaking , door and window damaged.
Home	Toilet block at Jspur inside p.s campas.	Municipality	One block	single	2002	14.75		Brick	Brick	A.S.F	Comp. wall		Door damaged.
Home	Pump house of P.S at Jspur inside p.s campas.	Municipality	One block	single	1998	133.69		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Good
Home	Old P.S building at jspur	Municipality	One block	single	1930	392.19		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Roof leaking and Door,window chokath, shutter ,plastering flooring damaged.

Dept. Name	Name of the Building	Location	Number of Residential	Single/double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Home	D.F.S.L building at jagatsinghpur.	Municipality	One block	single	2002	106.00		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Roof leaking and Door,window choukath, shutter ,plastering flooring damaged.
Home	Reserve office building at punanga jagatsinghpur.	Punaga	One block	single	2005	777.41	357.72	Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Good
Home	Rest room cum toilet building at Jagatsinghpur P.S premises	Municipality	One block	single	2003	15.5		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Good
Home	40 seated police barack at punanga[G/F]	punanga	One block	D/S	1998	322.85		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Door,window choukath, shutter ,plastering flooring damaged.
Home	40 seated police barack at punanga	punanga	One block	D/S	1998	201.16		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Door,window choukath, shutter ,plastering flooring damaged.
Home	constable barack and Dhobi shed at jspur	Municipality	One block	single	1962	80.26		Brick	Brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	Roof leaking and Door,window choukath, shutter ,plastering flooring damaged.
Home	Town out post at college chhack at jspur	Municipality	One block	single	1998	50.16		Brick	Brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	A.CS heet roof leaking and Door,window choukath, shutter ,plastering flooring damaged.
Excise	Excise office bldg at jspur near Galupada	Municipality	One block	single	2001	130.06		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Roof leaking and Door,window choukath, shutter ,plastering flooring damaged.
Home	Fire station building at jspur near sipi[G/F]	Municipality	One block	D/S	1998	276.97		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Door,window choukath, shutter ,plastering flooring damaged.
Home	Fire station building at jspur near sipi[F/F]	Municipality	One block	D/S	1998	98.09		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Roof leaking and Door,window choukath, shutter ,plastering flooring damaged.
Statistical	Statistical office building at jspur near Porohitpur	Municipality	One block	single	1998	338.92	65.30	Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Door,window choukath, shutter ,plastering flooring damaged.
Sports	N.KC.Stadium at jspur North gally-	Municipality	One block	single	2007	664.65	831.05	Column	R.C.C	A.S.F	R.C.C.		Good
Sports	N.KC.Stadium at jspur South gally	Municipality	One block	single	2007	664.65	832.05	Column	R.C.C	A.S.F	R.C.C.		Good
Sports	N.KC.Stadium at jspur Gate-1	Municipality	One block	single	2009	22.15		Column	R.C.C	A.S.F	R.C.C.		Door & window damaged
Sports	N.KC.Stadium at jspur Gate-2	Municipality	One block	single	2009	22.15		Column	R.C.C	A.S.F	R.C.C.		Door & window damaged
Sports	N.KC.Stadium at jspur Ticket counter-1	Municipality	One block	single	2006	22.05		Column	Brick	A.S.F	R.C.C.		Door & window damaged
Sports	N.KC.Stadium at jspur Ticket counter-2	Municipality	One block	single	2006	22.05		Column	Brick	A.S.F	R.C.C.		Door & window damaged

Dept. Name	Name of the Building	Location	Number of Residential	Single/double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Sports	N.KC.Stadium at jspur Guard room-1	Municipality	One block	single	2006	11.73		Column	Brick	A.S.F	R.C.C.		Door & window damaged
Sports	N.KC.Stadium at jspur Guard room-2	Municipality	One block	single	2008	11.73		Column	Brick	A.S.F	R.C.C.		Door & window damaged
A & H. U.	C.D.V.O building at jspur	Municipality	One block	single	2008	340.25	128.62	Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Old block roofing ,and Door,window choukath, shutter ,plastering flooring damaged.
A & H. U.	Dispensary building of Veterinary at jspur [Office and Store]	Municipality	One block	single	1970	72.01		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Partly damaged door & window
A & H. U.	Out door and treatment shed at jspur	Municipality	One block	single	2005	97.57		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Good
A & H. U.	Poultry shed at jspur	Municipality	One block	single	1970	27.59		Brick	Brick	A.S.F	A.C.S. & G.C.I.S.		A.C.S heet leaking and Door,window choukath, shutter ,plastering flooring damaged.
A & H. U.	store at jspur	Municipality	One block	single	1970	60.12		Brick	Brick	A.S.F	A.C.S. & G.C.I.S.	sal/Piasal	A.C.S heet leaking and Door,window choukath, shutter ,plastering flooring damaged.
A & H. U.	Garrage and store for Veterinary at jspur	Municipality	One block	single	1970	73.59		Brick	Brick	A.S.F	A.C.S. & G.C.I.S.		Partly damaged door & window-2009
A & H. U.	compound wall of Veterinary at jspur	Municipality	One block	single	1970	0.00	68.58	Brick	Brick	A.S.F	Comp. wall		Partly damaged -2009
Health	R.H.C Ladies hostel building of D.H.H at jspur[G/F]	Municipality	One block	D/S	1982	352.54		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Door,window choukath, shutter ,plastering flooring partly damaged.
Health	R.H.C Ladies hostel building of D.H.H at jspur[F/F]	Municipality	One block	D/S	1982	352.54		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Door,window choukath, shutter ,plastering flooring partly damaged.
Health	R.H.C Boy's hostel building of D.H.H at jspur[G/F]	Municipality	One block	D/S	1980	383.59		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Door,window choukath, shutter ,plastering flooring partly damaged.
Health	R.H.C Boy's hostel building of D.H.H at jspur[F/F]	Municipality	One block	D/S	1980	293.60		Brick	Brick	A.S.F	R.C.C.	sal/Piasal	Door,window choukath, shutter ,plastering flooring partly damaged.
Health	X-Ray & Ultra sound room at D.H.H at jspur	Municipality	One block	single	1982 & 2003	332.17		Brick	Brick	A.S.F	R.C.C.		Door,window choukath, shutter ,plastering flooring partly damaged.
Health	D.H.H Administrative block at jspur [G/F]	Municipality	One block	M/S	2004	400.10		Column	Brick	A.S.F	R.C.C.		Good
Health	D.H.H Administrative block at jspur[F/F]	Municipality	One block	M/S	2004	400.10		Column	Brick	A.S.F	R.C.C.		Good
Health	D.H.H Administrative block at jspur[S/F]	Municipality	One block	M/S	2004	400.10		Column	Brick	A.S.F	R.C.C.		Good
Health	D.H.H Administrative block at jspur [T/F]	Municipality	One block	M/S	2004	400.10		Column	Brick	A.S.F	R.C.C.		Grading plaster damaged
Health	20 beded eye hospital building at jspur	Municipality	One block	D/S	2005	465.83		Column	Brick	A.S.F	R.C.C.		Door,window choukath, shutter partly damaged.

Dept. Name	Name of the Building	Location	Number of Residential	Single/double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Health	Garrage and store of Eye hospital[G/F]	Municipality	One block	D/S	2005	84.81	47.03	Brick	Brick	A.S.F	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	Garrage and store of Eye hospital[F/F]	Municipality	One block	D/S	2005	84.81		Brick	Brick	A.S.F	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	Garrage for D.H.H at jspur	Municipality	One block	single	2005	60.18		Brick	Brick	A.S.F	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	Staff canteen for D.H.H staff at jspur	Municipality	One block	single	2005	61.68	10.00	Brick	Brick	A.S.F	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	Generator room for D.H.H at jspur	Municipality	One block	single	2005	38.50		Brick	Brick	A.S.F	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	Medicine store room & T.B Center for D.H.H at jspur[G/F]	Municipality	One block	D/S	2004	171.53		Brick	Brick	A.S.F	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	Medicine store room & T.B Center for D.H.H at jspur[F/F]	Municipality	One block	D/S	2005	92.90		Brick	Brick	A.S.F	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	3nos garrage for D.H.H at jspur	Municipality	One block	D/S	1985	135.35		Brick	Brick	A.S.F	R.C.C.		Door and flooring damaged.
Health	Red cross blood bank & pump house at jspur	Municipality	One block	D/S	2005	144.00		Brick	Brick	A.S.F	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	IPD/OT/Labour room for D.H.H at jspur[G/F]	Municipality	One block	D/S	2005	486.88		Brick	Brick	A.S.F/Tile	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	IPD/OT/Labour room for D.H.H at jspur[F/F]	Municipality	One block	D/S	2005	486.88		Brick	Brick	A.S.F/Tile	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	IPD/OT/Labour room for D.H.H at jspur[S/F]	Municipality	One block	D/S	2009	486.88		Brick	Brick	A.S.F/Tile	R.C.C.		Good
Health	D.H.H & R.HC building at jspur [ground floor][Gopabandhu sebasadan]	Municipality	One block	D/S	1970	565.92		Brick	Brick	A.S.F/Tile	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	D.H.H & R.HC building at jspur [First floor][Gopabandhu sebasadan]	Municipality	One block	D/S	1970	459.77		Brick	Brick	A.S.F/Tile	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	D.H.H & R.HC building at jspur [Ground floor][out door]	Municipality	One block	D/S	1982	285.90		Brick	Brick	A.S.F/Tile	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	D.H.H & R.HC building at jspur [First floor][ward]	Municipality	One block	D/S	1982	285.9		Brick	Brick	A.S.F/Tile	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	D.H.H building at jspur [Dental]	Municipality	One block	single	2005	184.06		Brick	Brick	A.S.F	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	D.H.H building at jspur [Dressing room]	Municipality	One block	single	2005	80.04		Brick	Brick	A.S.F	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Health	Postmortem center for D.H.H at jspur	Municipality	One block	single	1970	60.00		Brick	Brick	A.S.F	A.C.S. & G.C.I.S.		Unsafe
Commerce	A.C.T.O office building at jspur [G/F]	Municipality	One block	D/S	1984	188.95	96.92	Brick	Brick	A.S.F	R.C.C.		Door,window choukath, shutter ,plastering flooring damaged.
Commerce	A.C.T.O office building at jspur[F/F]	Municipality	One block	D/S	1984	188.95		Brick	Brick	A.S.F	R.C.C.		Roof leaking & Door,window choukath, shutter ,plastering flooring damaged.
Cooperative	A.R.C.S office building at jspur	Municipality	One block	single	1982	315.07	120.09	Brick	Brick	A.S.F	R.C.C.		Roof leaking & Door,window choukath, shutter ,plastering flooring damaged.
Cooperative	1 no garage for A.R.C.S office at jspur	Municipality	One block	single	1983	44.96		Brick	Brick	A.S.F	R.C.C.		Roof leaking & Door,window choukath, shutter ,plastering flooring damaged.

Dept. Name	Name of the Building	Location	Number of Residential	Single/double	Years of const	Total Plinth area	Compound wall length in Rm.	Type of foundation	Type of Wall	Type of Floor	Type of Roof	Type of Door Window	Present condition on with the year
Cooperative	Cycle stand for A.R.C.S office at ispur	Municipality	One block	single	1983 & 2008	27.81		Brick	Brick	A.S.F	R.C.C.		Flooring damaged