

**Residential building of Puri (R&B) Division,Puri**

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Home	Jailer Qr.in the campus of District Jail at Puri	181.90	Tile Terraced	1946	Renovation required
Home	C.Wall of Jailer Qr.in the campus of District Jail at Puri		Comp. wall	1950	
Home	Assistant Jailer Qr.in the campus of District Jail at Puri	176.88	Tile Terraced	1952	Renovation required
Home	C.Wall of Assistant Jailer Qr.in the campus of District Jail at Puri		Comp. wall		
Home	Assistant Surgeon Qr.in the campus of District Jail at Puri	109.06	R.C.C.	1952	Renovation required
Home	2Nos.Havildar Qr.in the campus of District Jail at Puri	146.03	Tile Terraced	1918	Renovation required
Home	Female Warder Qr.in the campus of District Jail at Puri	89.45	Tile Terraced	1918	Renovation required
Home	C.Wall of Female Warder Qr.in the campus of District Jail at Puri		Comp. wall		
Home	4Nos.of Warder Qr.in the campus of District Jail at Puri	306.02	Tile Terraced	1918	Renovation required
Home	C.Wall of 4Nos.of Warder Qr.in the campus of District Jail at Puri		Comp. wall		
Home	52Nos. Constable Barrack in R.P.Line at Puri	3138.80	R.C.C.	1929	Repair required
Home	40Nos. Constable Qr. in R.P.Line at Puri	3487.27	A.C.S. & G.C.I.S.	1929	Repair required
Home	3 sets of Constable Qr.in R.P.Line at Puri	732.42	R.C.C.	1922	Repair required
Home	Compounder Qr.in R.P.line at Puri	132.38	Tile Terraced	1922	Repair required

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Home	Reserve S.I.Qr.in R.P.line at Puri	270.8	A.C.S. & G.C.I.S.	1922	Repair required
Home	Surjent Major Qr.in R.P.line at Puri	433.28	Tile Terraced	1922	Repair required
Home	Surjent Major Qr.in R.P.line at Puri	250.00	A.C.S. & G.C.I.S.	1949	Repair required
Home	16 Nos.of A.S.I. & Havildar Qr.in R.P.Line at Puri.	2918.28	A.C.S. & G.C.I.S.	1949	Repair required
Home	S.P.Residence at Puri	1670.8	Tile Terraced	1903	Renovation required
Home	Addl.S.P.Residence at Puri	460.3	Tile Terraced	1929	Renovation required
Home	Asst. Surjent Qr.in R.P.line at Puri	348.18	A.C.S. & G.C.I.S.	1949	Renovation required
Home	4Nos.S.I.Qr.near SCS College at Puri	280.98	Tile Terraced	1929	Renovation required
Home	Police Inspector Qr.inside Town P.S.at Puri	260.80	R.C.C.	1925	Renovation required
Home	2Nos. S.I.Qr.inside town P.S.at Puri	2041.38	Tile Terraced	1925	Repair required
Home	16Nos. Fireman Qr.in fire station at Puri	338.89	A.C.S. & G.C.I.S.	1940	Repair required
Home	2Nos.S.I.Qr.near SCS College at Puri	184.48	A.C.S. & G.C.I.S.	1929	Repair required
Home	D.I.B. S.I.Qr.in R.P.line at Puri	185.95	R.C.C.	1960	Repair required
Home	5Nos. Havildar Qr.inside fire station at Puri	520.88	A.C.S. & G.C.I.S.	1940	Repair required
Home	S.I.Qr.inside fire station at Puri	260.86	R.C.C.	1945	Repair required

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Home	Major Surjent Qr.used as sadar P.S.Office at Puri	280.55	R.C.C.	1945	Repair required
Home	S.I.Qr.at Puri	243.10	A.C.S. & G.C.I.S.	1924	Repair required
Home	2Nos.Qrs.for writer and havildar at Puri	167.22	Tile Terraced	1940	Repair required
Home	2Nos.Qrs.of Court S.I.near SCS College at Puri	708.13	Tile Terraced	1940	Repair required
Home	D.I.B.Inspector Qr.in R.P.line at Puri	185.88	R.C.C.	1972	Repair required
Home	D.S.P.Qr.near SadarP.S.at Puri	692.47	A.C.S. & G.C.I.S.	1940	Repair required
Home	Sadar Inspector Qr.near sadar P.S.at Puri	285.80	A.C.S. & G.C.I.S.	1940	Repair required
Home	2Nos.of S.I.Qr.near sadar P.S.at Puri	320.95	A.C.S. & G.C.I.S.	1940	Repair required
Home	3Nos.A.S.I.Qr.near Sadar P.S.at Puri	380.35	A.C.S. & G.C.I.S.	1945	Repair required
Home	4Nos. Ministerial staff Qrs.at Puri	335.00	A.C.S. & G.C.I.S.	1948	Repair required
Home	Havildar Qr.in R.P.Line at Puri	300.43	A.C.S. & G.C.I.S.	1990	Repair required
Home	18Nos. "E" type flat Qrs.near SCS College at Puri	1301.99	R.C.C.	1990	Repair required
Home	24Nos. "F" type flat Qrs.in R.P.Line at Puri	980.9	R.C.C.	1940	Repair required
Home	3Nos.S.I.Qrs.near Railway station at Puri	728.48	A.C.S. & G.C.I.S.	1940	Repair required
Home	Surjent Major No.II Qr.in R.P.line at Puri	230.88	A.C.S. & G.C.I.S.	1940	Repair required

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Home	2Nos.of A.S.I.Qr.near SCS College at Puri	280.98	Tile Terraced	1960	Repair required
Home	1no. A.S.I.Qr.inside fire stationat Puri	150.92	R.C.C.	1960	Repair required
Home	Circle Inspector Quarter at Nimapara	141.95	Tile Terraced	1940	Roof leaking,some doors &windows ,flooring& plastering partly damaged
Home	I.I.C Quarter at Nimapara	195.5	A.C.S. & G.C.I.S.	1940	-do-
Home	Twin A.S.I. Quarter at Nimapara	126.34	A.C.S. & G.C.I.S.	1940	-do-
Home	Twin Conestabal Quarter at Nimapara	70.60	R.C.C.	1978	-do-
Home	D' type Quarter at Konark	109.80	R.C.C.	1984	-do-
Home	E' type Quarter at Konark	64.47	R.C.C.	1984	-do-
Home	F' type Quarter at Konark	40.31	R.C.C.	1984	-do-
Revenue	Collector's residence with subsidiary building at Puri	2798.50	Tile Terraced	1903	Renovation required
Revenue	"D" type Qr.of revenue Deptt.at Puri	232.25	R.C.C.	1980	Repair required
Revenue	"C" type Qr.of revenue Deptt.at Puri	156.06	R.C.C.	1993	Repair required
Revenue	Civil S.D.O.'s residence at Puri	651.18	R.C.C.	1915	Repair required
Revenue	A.D.M.Qr.at Puri	390.04	R.C.C.	1955	Repair required
Revenue	C.Wall of Civil S.D.O.'s residence at Puri		Comp. wall		Repair required

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Revenue	C.Wall of A.D.M.Qr.at Puri		Comp. wall		Repair required
Revenue	Annex of Circuit House at Puri	400.00	R.C.C.	1960	Needs repair
Revenue	"E" type Qr.of Circuit House at Puri	242.70	R.C.C.	1970	Needs repair
Revenue	Peon & Mali Qr.of Circuit House at Puri	400.00	R.C.C.	1970	Needs repair
Revenue	"F" type 34Nos.Qrs.in RHS Colony at Puri	2068.00	R.C.C.	1980	Renovation required
Revenue	"D" type 2Nos.Qrs.in RHS Colony at Puri	364.46	R.C.C.	1980	Renovation required
Revenue	"3R" Qr. 5Nos.in LIC Colony at Puri	918.12	R.C.C.	1964	Needs repair
Revenue	"2RB" Qr. 5Nos.in LIC Colony at Puri	395.88	R.C.C.	1964	Needs repair
Revenue	Temple A.D.M.Qr. at Puri	200.00	Tile Terraced	1978	Needs repair
Revenue	Tahasidar Quarter at Nimapara	148.64	R.C.C.	1940	Roof leaking,some doors &windows ,flooring& plastering partly damaged
Revenue	D' type Quarter for Addl. Tahasildar at Nimapara Qr. I	97.54	R.C.C.	1993	-do-
Revenue	D' type Quarter for Addl. Tahasildar at Nimapara Qr. II	97.54	R.C.C.	1993	Roof leaking,some doors &windows ,flooring& plastering partly damaged
Revenue	Twin 'F'Type Quarter at Nimapara	137.49	R.C.C.	1993	-do-
Revenue	Twin staff quarter at Nimapara Block I	120.77	A.C.S. & G.C.I.S.	1970	-do-
Revenue	Twin staff quarter at Nimapara Block II	120.77	A.C.S. & G.C.I.S.	1970	-do-

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Revenue	"E' Type Quarter for Sub Resister at Nimapara	88.25	R.C.C.	1992	-do-
RajBhawan	4Nos.Rajbhaban Mali Qrs.at Puri	285.00	A.C.S. & G.C.I.S.	1944	Needs repair
RajBhawan	2Nos.A.D.C. Qrs.at Puri	297.28	R.C.C.	1950	Needs repair
Works	P.W.D.staff Qr. No.1 at Puri (one block single storied)	189.00	R.C.C.	1980	
Works	C.Wall of P.W.D.staff Qr. No.1 at Puri		Comp. wall		
Works	P.W.D.staff Qr. No.3 at Puri (one block single storied)	97.34	Tile Terraced	1975	
Works	C.Wall of P.W.D.staff Qr. No.3 at Puri		Comp. wall		
Works	P.W.D.staff Qr. No.4 at Puri (one block single storied)	64.00	Tile Terraced	1925	
Works	C.Wall of P.W.D.staff Qr. No.4 at Puri		Comp. wall		
Works	P.W.D.staff Qr. No.5 at Puri (one block single storied)	92.00	Tile Terraced	1924	
Works	C.Wall of P.W.D.staff Qr. No.5 at Puri		Comp. wall		
Works	P.W.D.staff Qr. No.6 at Puri (Four blocks double storied)	212.00	R.C.C.	1978	Qr.No.6/2 is unsafe.
Works	C.Wall of P.W.D.staff Qr. No.6 at Puri		Comp. wall		
Works	P.W.D.staff Qr. No.7 at Puri (One block)	85.00	Tile Terraced	1925	
Works	C.Wall of P.W.D.staff Qr. No.7 at Puri		Comp. wall		

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Works	P.W.D.staff Qr. No.8 at Puri (One block)	110.00	R.C.C.	1984	
Works	C.Wall of P.W.D.staff Qr. No.8 at Puri		Comp. wall		
Works	P.W.D.staff Qr. No.9 at Puri (One block)	135.00	R.C.C.	1953	
Works	C.Wall of P.W.D.staff Qr. No.9 at Puri		Comp. wall		
Works	P.W.D.staff Qr. No.10 at Puri (One block)	65.00	R.C.C.	1980	
Works	C.Wall of P.W.D.staff Qr. No.10 at Puri		Comp. wall		
Works	P.W.D.staff Qr. No.12 at Puri (One block)	26.00	A.C.S. & G.C.I.S.	1975	
Works	P.W.D.staff Qr. No.13 at Puri (One block)	26.00	A.C.S. & G.C.I.S.	1975	
Works	P.W.D.staff Qr. No.14 at Puri (One block)	31.00	A.C.S. & G.C.I.S.	1975	
Works	P.W.D.staff Qr. No.15 at Puri (One block)	33.00	A.C.S. & G.C.I.S.	1975	
Works	P.W.D.staff Qr. No.16 at Puri (One block)	94.00	A.C.S. & G.C.I.S.	1975	
Works	P.W.D.staff Qr. No.17 at Puri (One block)	86.00	Tile Terraced	1925	
Works	C.Wall of P.W.D.staff Qr. No.17 at Puri		Comp. wall		
Works	P.W.D.staff Qr. No.18 at Puri (One block)	110.00	Tile Terraced	1925	
Works	C.Wall of P.W.D.staff Qr. No.18 at Puri		Comp. wall		

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Works	P.W.D.staff Qr. No.19 at Puri (One block)	36.00	Tile Terraced	1960	
Works	P.W.D.staff Qr. No.20 at Puri (One block)	25.00	Tile Terraced	1924	
Works	P.W.D.staff Qr. No.21 at Puri (One block)	25.00	Tile Terraced	1924	
Works	P.W.D.staff Qr. No.22 at Puri (Four block)	172.00	R.C.C.	1980	
Works	P.W.D.staff Qr. No.23 at Puri (One block)	52.00	R.C.C.	1983	
Works	P.W.D.staff Qr. No.24 at Puri (One block)	52.00	R.C.C.	1983	
Works	P.W.D.staff Qr. No.25 at Puri (Four block)	212.00	R.C.C.	1981	
Works	P.W.D.staff Qr. No.26 at Puri (Four block)	222.00	R.C.C.	1981	
Works	C.Wall of P.W.D.staff Qr. No.26 at Puri		Comp. wall		
Works	P.W.D.staff Qr. No.27 at Puri (One block)	70.00	R.C.C.	1989	
Works	P.W.D.staff Qr. No.28 at Puri (One block)	70.00	R.C.C.	1989	
Works	P.W.D.staff Qr. No.29 at Puri	63.00	R.C.C.	1984	
Works	P.W.D.staff Qr. No.30 at Puri	47.00	R.C.C.	1975	
Works	P.W.D.staff Qr. No.31 at Puri	47.00	R.C.C.	1989	
Works	P.W.D.staff Qr. No.32 at Puri	46.00	R.C.C.	1984	



Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Works	P.W.D.staff Qr. No.33 at Puri	42.00	A.C.S. & G.C.I.S.	1975	
Works	P.W.D.staff Qr. No.34 at Puri	42.00	A.C.S. & G.C.I.S.	2006	
Works	P.W.D.staff Qr. No.35 at Puri	42.00	A.C.S. & G.C.I.S.	1975	
Works	P.W.D.staff Qr. No.36 at Puri	27.00	A.C.S. & G.C.I.S.	1975	
Works	P.W.D.staff Qr. No.37 at Puri	22.00	Tile Terraced	1924	
Works	P.W.D.staff Qr. No.38 at Puri	22.00	A.C.S. & G.C.I.S.	1924	
Works	P.W.D.staff Qr. No.39 at Puri	22.00	A.C.S. & G.C.I.S.	1924	
Works	P.W.D.staff Qr. No.40 at Puri	22.00	A.C.S. & G.C.I.S.	1924	
Works	P.W.D.staff Qr. No.41 at Puri	22.00	A.C.S. & G.C.I.S.	1924	
Works	P.W.D.staff Qr. No.42 at Puri	22.00	A.C.S. & G.C.I.S.	1924	
Works	P.W.D.staff Qr. No.43 at Puri	28.00	Tile Terraced	1915	
Works	P.W.D.staff Qr. No.44 at Puri	35.00	A.C.S. & G.C.I.S.	1990	
Works	P.W.D.staff Qr. No.45 at Puri	35.00	A.C.S. & G.C.I.S.	1950	
Works	P.W.D.staff Qr. No.46 at Puri	35.00	A.C.S. & G.C.I.S.	1950	
Works	P.W.D.staff Qr. No.01 ( J.E.Qr.) at Sakhigopal	123.00	A.C.S. & G.C.I.S.		Good & habitable condition.

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Works	P.W.D.staff Qr. No.02 at Sakhigopal	27.90	A.C.S. & G.C.I.S.		Good & habitable condition.
Works	P.W.D.staff Qr. No.03 at Sakhigopal	27.90	A.C.S. & G.C.I.S.		Good & habitable condition.
Works	P.W.D.staff Qr. No.04 at Sakhigopal	36.50	A.C.S. & G.C.I.S.		Good & habitable condition.
Works	P.W.D.staff Qr. No.05 at Sakhigopal	27.90	A.C.S. & G.C.I.S.		Good & habitable condition.
Works	S.O.Rajbhawan Qr.occupied by E.E.Puri (R&B) Division, Puri	207.16	Tile Terraced	1950	Needs repair
Works	4Nos. P.W.D.Staff Qrs.near R.K.Mission at Puri	297.28	R.C.C.	1979	Needs repair
Works	4Nos. P.W.D.Staff Qrs.near R.K.Mission at Puri	230.40	A.C.S. & G.C.I.S.	1982	Needs repair
Works	G.E.D.Staff Qrs.in P.W.D.Colony at Puri	205	R.C.C.	1965	Needs repair
Works	4Nos. G.E.D.Staff Qrs.in L.I.C.Colony at Puri	285.45	R.C.C.	1968	Needs repair
Works	"D' Type Quarter at Nimapara	97.54	R.C.C.	1973	Some doors, windows & AC Sheet damaged, flooring, & plastering partly damaged
Works	"E' Type Quarter at Nimapara	69.67	A.C.S. & G.C.I.S.	1973	-do-
Works	"F' Type Quarter at Nimapara	60.38	A.C.S. & G.C.I.S.	1973	-do-
Works	Twin 'G' Type Quarter at Nimapara	111.48	A.C.S. & G.C.I.S.	1973	-do-
Works	Old type S.O.Quater at Nimapara	69.67	A.C.S. & G.C.I.S.	1973	-do-
Works	5nos single room Quarter at Nimapara	162.57	R.C.C.	1973	-do-

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Works	Staff Quarter at Gop	61.10	Comp. wall		-do-
Works	J.E. Quarter of Gop	102.66	Comp. wall		-do-
Works	J.E.Quater of Konark	78.96	R.C.C.	1986	Roof leaking,some doors &windows ,flooring& plastering partly damaged
Works	Staff Quarter of Konark	427.00	A.C.S. & G.C.I.S.	1940	-do-
Works	Staff Quarter of Konark	47.84	R.C.C.	1994	-do-
Works	J.E. Quarter at Kakatpur	200.00	A.C.S. & G.C.I.S.		-do-
Excise	Office-cum-Residence of Excise Inspector at Puri	75.00	R.C.C.	1950	Repair required
NCC	3Nos.of N.C.C.staff Qrs.at Puri	315.86	R.C.C.	1970	Repair required
Law	Sub-Judge Qr.at Puri	144.08	R.C.C.	1965	Raise of Plinth with renovation to building
Law	Muncif Qr.at Puri	198.34	Tile Terraced	1965	Renovation required
Law	3R Qrs. 2nos. At Puri	287.24	R.C.C.	1988	Good
Law	Covered passage office of Dist.Judge at Puri	11.14	Tile Terraced	1916	Repair required
Law	Court Covered Qr.at Puri	201.59	Tile Terraced	1926	Repair required
Law	Compound wall		Comp. wall	1952	Repair required
Law	District Judge Qr.at Puri	262.44	A.C.S. & G.C.I.S.	1967	Renovation required

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Law	3Nos.of "D" type Qr.for Judicial Deptt.at Puri	250.83	R.C.C.	1993	Renovation required
Law	C.Wall to 3Nos.of "D" type Qr.for Judicial Deptt.at Puri		Comp. wall		
Law	C.J.M.Qr.at Puri	111.48	Tile Terraced	1967	Renovation required
Law	C.Wall of C.J.M.Qr.at Puri		Comp. wall		
Law	1st A.D.J.Qr.at Puri	102.19	R.C.C.	1984	Good
Law	C.Wall of 1st. A.D.J.Qr.at Puri		Comp. wall		
Law	1st. Track court Judge Qr.at Puri	243.84	R.C.C.	1998	Renovation required
Law	Twin "D" type Qr.for Judicial Deptt.at Puri	213.67	A.C.S. & G.C.I.S.	1967	Repair required
Law	"D" type Quarter of J.M.F.C at Nimapara	101.82	R.C.C.	1997	Roof leaking,some doors &windows ,flooring& plastering partly damaged
Law	"D" type Quarter of Civil Judge at Nimapara	101.82	R.C.C.	1997	-do-
A.H & V.S.	V.A.S.Qr.in side veterinary hospital at Puri	307.49	R.C.C.	1970	Renovation required
A.H & V.S.	Sweeper Qr.in side veterinary hospital at Puri	150.49	A.C.S. & G.C.I.S.	1964	Renovation required
A.H & V.S.	Compounder Qr.in side veterinary hospital at Puri	142.30	A.C.S. & G.C.I.S.	1955	Renovation required
A.H & V.S.	C.D.V.O.Qr.in side veterinary hospital at Puri	282.88	R.C.C.	1970	Renovation required
A.H & V.S.	Stock man Qr.in side veterinary hospital at Puri	80.98	A.C.S. & G.C.I.S.	1970	Renovation required

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
A.H & V.S.	V.A.S. Quarter at Nimapara	160.06	R.C.C.	1970	-do-
A.H & V.S.	V.A.S. Quarter(I.C.D) at Nimapara	147.43	A.C.S. & G.C.I.S.	1970	-do-
A.H & V.S.	Twin staff Quarter at Nimapara	123.37	A.C.S. & G.C.I.S.	1970	-do-
Transport	Twine 2RB Qr.near Sunar Gourang at Puri	311.21	R.C.C.	1970	Renovation required
Transport	R.T.O.Qr.in LIC Colony at Puri	178.52	R.C.C.	1964	Needs repair
Agriculture	D' type Quarter for ADAO at Nimapara	91.97	R.C.C.	1983	Some doors & windows ,flooring& plastering partly damaged
Agriculture	Staff Quarter Block I at Nimapara	48.31	A.C.S. & G.C.I.S.	1978	Some doors & windows ,flooring& plastering partly damaged
Agriculture	Staff Quarter Block II at Nimapara	48.31	A.C.S. & G.C.I.S.	1978	-do-
Agriculture	A.E.O. Quarter at Nimapara	57.13	A.C.S. & G.C.I.S.	1978	-do-
Agriculture	P.P.O. Quarter at Nimapara	57.13	A.C.S. & G.C.I.S.	1978	-do-
Agriculture	V.A.W. Quter at Nimapara	25.64	R.C.C.	1978	Roof leaking,some doors & windows ,flooring& plastering partly damaged
Agriculture	V.A.W. Quter atKonark	54.25	R.C.C.	1972	-do-
Agriculture	D.D.A quarter at Puri	185.03	R.C.C.	1979	Habitable
Agriculture	D.A.O Quarter at Puri	232.25	R.C.C.	1961	Habitable
Agriculture	10nos staff quarter near B.N.R at Puri	834.44	A.C.S. & G.C.I.S.	1961	Habitable

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Agriculture	5 nos staff quarter inside agriculture at Puri	339.35	R.C.C.	1970	Habitable
Agriculture	2 nos VAW quarter in agriculture colony at Puri	113.8	R.C.C.	1962	Needs to be renovate
Agriculture	Grain shed used as quarter at Puri	74.32	A.C.S. & G.C.I.S.	1970	Habitable
Fishery	3nos F type quarter	71.72	A.C.S. & G.C.I.S.	1952	Needs to be renovate
Fishery	Driver quarter	31.15	A.C.S. & G.C.I.S.	1952	Needs to be renovate
Fishery	Asst. director quarter	116.13	A.C.S. & G.C.I.S.	1952	Habitable
Fishery	1no F type quarter	32.99	R.C.C.	1999	Habitable
Soil conservation	1 no F type quarter at Puri	62.26	A.C.S. & G.C.I.S.	1978	Needs to be renovate
Cooperative	1no D type quarter for ARCS	102.19	R.C.C.	1972	Habitable
Cooperative	1 no F type quarter for watch man	63.26	R.C.C.	1972	Needs to be renovate
Cooperative	Steno quarter	100.00	R.C.C.	1972	Needs to be renovate
Cooperative	Old ARCS office converted to Qtr.	225.00	R.C.C.	1972	Habitable
Industries	3RB Qtr for pricipal of I.T.I	192.02	R.C.C.	1960	Habitable
Industries	2RB Qtr head clark	148.17	R.C.C.	1970	Habitable
Industries	2RB Qtr for Super visor	101.72	R.C.C.	1960	Habitable

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Industries	2RB Qtr for choukidar	55.28	R.C.C.	1999	Habitable
Industries	3RB Qtr for Foreman	192.02	R.C.C.	1960	Habitable
Industries	2no 2RB staff quarter	417.12	R.C.C.	1960	Needs to be renovate
Industries	2RB Qtr for wire man	76.18	R.C.C.	1960	Habitable
Industries	2RB Qtr for Super visor	104.51	R.C.C.	1960	Habitable
Industries	2nos "E" type qtr	130.06	R.C.C.	1981	Habitable
Industries	2nos 2RB qtr for DIC Staff	101.72	R.C.C.	1970	Habitable
Finance	Twin staff Qr. Of Sub Treasury at Nimapara Block I	100.33	R.C.C.	1979	Roof leaking,some doors &windows ,flooring& plastering partly damaged
Finance	Twin staff Qr. Of Sub Treasury at Nimapara Block II	100.33	R.C.C.	1979	-do-
Finance	Twin 'E' Type Quarter at Nimapara Sub Treasury	130.32	R.C.C.	2009	-do-
Finance	Twin 'F' Type Quarter at Nimapara Sub Treasury	85.8	R.C.C.	2009	-do-
Finance	Treasury Officer's Qr.at Puri	246.54	R.C.C.	1978	Repair required
Finance	Treasury Qr.at Puri	248.54	R.C.C.	1978	Needs repair
Finance	3R Qtr 4 nos at Puri	371.60	R.C.C.	1960	Habitable
Finance	Chukidar quarter of CTO colony at Puri	35.77	R.C.C.	1960	Inhabitable

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Finance	4 no F type qtr of CT Dept. at Puri	121.70	R.C.C.	1980	Habitable
Finance	2 no E type qtr of CT Dept. at Puri	260.85	R.C.C.	1980	Habitable
Finance	4 no E type qtr of CT Dept. at Puri	520.24	R.C.C.	1989	Habitable
Finance	4 no E type qtr of CT Dept. at Puri	520.24	R.C.C.	1990	Habitable
Finance	Twin F type at Puri	75.62	R.C.C.	1990	Inhabitable
General Administrative	2Nos.of "F" type Qrs.inside vigilance office at Puri	98.77	R.C.C.	1981	Repair required
General Administrative	Vigilance Inspector Qr.at Puri	200.00	R.C.C.	1980	Repair required
General Administrative	1No. "C" type Qr.for Vigilance staff at Puri	215.20	R.C.C.	1980	Repair required
General Administrative	1No. "D" type Qr.for Vigilance staff at Puri	150.00	R.C.C.	1980	Repair required
Panchayatraj	D.P.O.Qr.near R.K.Mission at Puri	280.93	R.C.C.	1980	Repair required
Panchayatraj	A.D.P.O.Qr.near R.K.Mission at Puri	220.00	R.C.C.	1980	Repair required
Panchayatraj	S.D.P.O.Qr.near R.K.Mission at Puri	195.00	R.C.C.	1980	Repair required
Education	Principal Qr.of SCS College at Puri	331.88	Tile Terraced	1931	Needs repair
Education	4Nos.Lecturer Qrs.of SCS College at Puri	323.98	Tile Terraced	1958	Needs repair
Education	2Nos.Lecturer Qrs.of SCS College at Puri	274.05	Tile Terraced	1958	Needs repair



Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Education	Assistant Superintendent Qr.of SCS College at Puri	341.03	R.C.C.	1969	Needs repair
Education	Hostel Superintendent Qr.of SCS College at Puri	140.93	R.C.C.	1969	Needs repair
Education	Head Master Qr.of Govt. Girls high school at Puri	374.64	Tile Terraced	1969	Needs repair
Education	D.I. Qr.of Govt. Girls high school at Puri	138.22	R.C.C.	1960	Needs repair
Education	C.I. Qr.of Govt. Girls high school at Puri	142.22	R.C.C.	1959	Needs repair
Education	7Nos. "C" type Qrs.of SCS College at Puri	780.36	R.C.C.	1978	Needs Repair and renovation
Education	Head Master Qr.of Puri Zila School at Puri	204.38	Tile Terraced	1940	Needs Repair and renovation
Education	4Nos.of Peaon Qr.of Puri Zila School at Puri	167.22	R.C.C.	1949	Needs Repair and renovation
Education	School S.I Quarter at Nimapara	163.78	R.C.C.	1974	-do-
Education	Twin Staff Quarter of JBR Girls High School at Nimapara Block I	96	R.C.C.	1970	-do-
Education	Twin Staff Quarter of JBR Girls High School at Nimapara Block II	96	R.C.C.	1970	-do-
Education	"D" type Quarter of Headmaster at Nimapara	89.18	R.C.C.	2000	-do-
Education	S.T. School Headmaster at Nimapara	71.9	A.C.S. & G.C.I.S.	1970	-do-
Education	Staff Quarter of ST School at Nimapara Block I	72.83	A.C.S. & G.C.I.S.	1970	-do-
Education	Staff Quarter of ST School at Nimapara Block II	71.9	A.C.S. & G.C.I.S.	1970	-do-

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Education	Staff Quarter of Govt. Boys High School at Nimapara Block I	74.32	A.C.S. & G.C.I.S.	1970	-do-
Education	Staff Quarter of Govt. Boys High School at Nimapara Block II	74.32	A.C.S. & G.C.I.S.	1970	-do-
Education	Head master Quarter at Konark	69.58	R.C.C.	1996	Roof leaking,some doors &windows ,flooring& plastering partly damaged
Education	Asst. Teacher Quarter at Konark	75.43	R.C.C.	1996	-do-
Education	Asst. Teacher Quarter at Konark	75.43	R.C.C.	1996	-do-
Education	Attendant Quarter at Konark	29.36	R.C.C.	1995	-do-
Education	Superintendent Quarter of Sevasram school at Konark		R.C.C.		
Education	Head master Quarter Sevasram School at Konark		R.C.C.		
Education	Hostel Building of Sevasram School ( Double Storied)		R.C.C.		
Forest	Staff Quarters( Guard)at Konark	480	A.C.S. & G.C.I.S.	1950	-do-
Forest	Range officer Quarter at Konark	106	A.C.S. & G.C.I.S.	1950	-do-
Forest	Forester Quarter at Konark	148.17	A.C.S. & G.C.I.S.	1950	-do-
Health	Medical Officer Quarter at Nimapara	144.92	R.C.C.	1977	-do-
Health	Nurse Quarter at Nimapara	60.38	R.C.C.	1977	-do-
Health	Compounder Quarter at Nimapara	119.28	R.C.C.	1977	-do-

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Health	Sweeper Quarter at Nimapara	38.64	A.C.S. & G.C.I.S.	1977	-do-
Health	Dhai Quarter at Nimapara	36.42	A.C.S. & G.C.I.S.	1977	-do-
Health	L.H.V. Quarter at Nimapara	114	R.C.C.	2002	-do-
Health	Medical Officer Quarter at Konark	92.07	R.C.C.	1987	-do-
Health	L.H.V. Quarter at Konark	71.03	R.C.C.	1972	-do-
Health	Staff Quarter of Medical Dispensary at Konark		R.C.C.	2005	-do-
Health	Sweeper Qr.in K.D.M. Hospital at Puri	118.26	R.C.C.	1955	Repair required
Health	Servant Qr.in K.D.M. Hospital at Puri	118.26	R.C.C.	1955	Repair required
Health	Nurse Qr.in K.D.M. Hospital at Puri	250.90	R.C.C.	1955	Repair required
Health	Minial Block in K.D.M. Hospital at Puri	170.66	R.C.C.	1955	Repair required
Health	Doctor's Qr.in K.D.M. Hospital at Puri	150.8	R.C.C.	1955	Repair required
Health	C.Wall of K.D.M.Hospital at Puri		Comp. wall	1955	Repair required
Health	C.D.M.O.Qr.at Puri	315.86	Tile Terraced	1914	Renovation required
Health	Out house and Kitchen	222.96	A.C.S. & G.C.I.S.	1914	Renovation required
Health	Qr.at Deptt. Campus	297.78	R.C.C.	2006	Good

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Health	Qr.at D.H.H.Campus at Puri	260.12	R.C.C.	2006	Good
Health	C.Wall		Comp. wall		
Health	4R Qr.at Puri	206.42	R.C.C.	1964	Renovation required
Health	Assistant Surgen Qr.at Puri	179.85	Tile Terraced	1928	Renovation required
Health	C.Wall		Comp. wall		
Health	A.D.M.O. Qr.at Puri	195.09	Tile Terraced	1948	Renovation required
Health	Ledy Doctor Qr. At Puri	198.06	Tile Terraced	1948	Renovation required
Health	Twin 2RB Qr.at Puri	127.08	R.C.C.	1928	Renovation required
Health	Twin Compounder Qr.at Puri	175.49	Tile Terraced	1971	Renovation required
Health	C.Wall		Comp. wall		
Health	Nursing Sister Qr.at Puri	97.54	Tile Terraced	1950	Renovation required
Health	3sets of Nursing Qr.at Puri	254.17	Tile Terraced	1928	Renovation required
Health	C.Wall		Comp. wall		
Health	Sweeper Qr.at Puri	59.45	Tile Terraced	1928	Renovation required
Health	Minial ward at Puri	39.48	Tile Terraced	1928	Renovation required

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Health	Servant block latrine	118.72	Tile Terraced	1928	Renovation required
Health	Principal Qr.of G.A.M.at Puri	246.92	R.C.C.	1952	Good
Health	C.Wall		Comp. wall	1952	
Health	Deputy Sperintendent Qr.of G.A.M.at Puri	88.81	R.C.C.	1965	Repair required
Health	C.wall		Comp. wall	1965	
Health	6Nos.Nurse Qr.of G.A.M.at Puri	147.43	R.C.C.	1965	Renovation required
Health	C.Wall		Comp. wall	1965	
Health	Dhobi shed of G.A.M.at Puri	23.78	A.C.S. & G.C.I.S.	1965	Renovation required
Health	Asst.Surgen Qr.of I.D.H.at Puri	194.62	Tile Terraced	1955	Renovation required
Health	C.Wall		Comp. wall	1955	
Health	3Nos.of Compounder Qrs.of I.D.H.at Puri	334.53	Tile Terraced	1955	Renovation required
Health	C.Wall		Comp. wall	1955	
Health	5Nos.of Nurse Qrs.of I.D.H.at Puri	208.37	Tile Terraced	1955	Renovation required
Health	C.Wall		Comp. wall	1955	
Health	2Nos.of "C" type Qrs.of I.D.H.at Puri	102.65	R.C.C.	1953	Renovation required

Deptt. Name	Name of building	Plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Health	Dhai Qr., Kitchen and Latrine	180.41	R.C.C.	1953	Renovation required
Health	C.Wall		Comp. wall	1955	

Non Residential building of Puri (R&B) Division, Puri							
Deptt. Name	Name of building	Plinth area in Sqm.	Addition/ alteration plinth area in Sqm.	Total plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Revenue	Record Room Cum Library of puri Colletoreate	340.15		340.15	R.C.C.	1995	Needs to be renovate
Revenue	Old kasim Bazar building usedd as Tahasil	252.50		252.50	R.C.C.	1999	
Revenue	Old Circuit House at Puri	856.00		856.00	R.C.C.	1942	Renovation required
Revenue	New Circuit House at Puri	963.12		963.12	R.C.C.	1948	Needs repair
Revenue	6Nos. Garage of Circuit House at Puri	1000.12		1000.12	R.C.C.	1942	Needs repair and renovation
Revenue	Old Collectorate with subsidiary building at Puri	3645.00		3645.00	R.C.C.	1903	Renovation required
Revenue	New Collectorate at Puri	300.65		300.65	R.C.C.	1985	Repair required
Revenue	Compound wall of collectorate at Puri				Comp. wall		
Revenue	D.D.B.Office at Puri	365.58		365.58	R.C.C.	1945	Good
Revenue	Guest House of D.D.B.office at Puri	85.00		85.00	R.C.C.	1945	Good
Revenue	Motor garage and rest shed of collectorate at	120.00		120.00	A.C.S. & G.C.I.S.	1950	Repair required
Revenue	Record room of collectorate at Puri	874.18		874.18	R.C.C.	1950	Repair required
Revenue	Cycle shed and Latrine block of new	176.22		176.22	R.C.C.	1985	Repair required
Revenue	S.D.O. Office at Puri	345.86		345.86	R.C.C.	1988	Repair required
Revenue	Tahasil Office at Puri	325.15		325.15	R.C.C.	1985	Repair required
Revenue	Waiting hall to R.I.Office at Puri	297.50		297.50	R.C.C.	1990	Good
Revenue	Conference Hall of collectorate at Puri	305.00		305.00	R.C.C.	1985	Repair required
Revenue	District Election Office at Puri	70.00		70.00	R.C.C.	1986	Good
Revenue	Election Godown of election office at Puri	45.00		45.00	A.C.S. & G.C.I.S.	1985	Renovation required
Revenue	Library cum adl. Record room of collectorate at	230.20		230.20	R.C.C.	2000	Renovation required
Revenue	Sub-Collector's Record room at Puri	116.12		116.12	R.C.C.	2006	Repair required
Revenue	Tahasil Office at Nimapara	450.00		450.00	R.C.C.	1940	- do-
Revenue	-do-	147.55		147.55	A.C.S. & G.C.I.S.	1940	
Revenue	Revenue Rest shed at Nimapara	69.67		69.67	R.C.C.	1940	- do-
Revenue	R.I.Office Building at Andhia	57.60		57.60	R.C.C.	1978	- do-
Revenue	R.I.Office Building at Patapur	57.60		57.60	A.C.S. & G.C.I.S.	1978	- do-
Revenue	Sub-Register Office at Nimapara	148.64		148.64	R.C.C.	1992	- do-
Revenue	R.I. Office at Konark	57.60		57.60	A.C.S. & G.C.I.S.	1978	- do-
Edication	Womens college at Puri. (Main Building)	1550.00		1550.00	R.C.C.	2002	
Edication	1st floor over existing Womens college at Puri.		122.24	122.24	R.C.C.	2009	
Edication	S.C.S.College at Puri	3432.58		3432.58	R.C.C.	1926	Needs repair and renovation
Edication	Patharpuri Hostel of S.C.S.College at Puri	997.99		997.99	R.C.C.	1918	Needs repair
Edication	Hostel No.1 of S.C.S.College at Puri	599.10		599.10	R.C.C.	1926	Needs repair
Edication	Sukanya Ladies Hostel of S.C.S.College at	3288.66		3288.66	R.C.C.	1983	Needs repair
Edication	Govt. Girls High School at Puri	1761.73		1761.73	R.C.C.	1917	Needs repair
Edication	Puri Zila School at Puri	1911.42		1911.42	R.C.C.	1915	Needs repair
Edication	Biswamber Vidyapitha at Puri	1487.74		1487.74	R.C.C.	1915	Needs repair

Non Residential building of Puri (R&B) Division, Puri							
Deptt. Name	Name of building	Plinth area in Sqm.	Addition/ alteration plinth area in Sqm.	Total plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Education	Gangadhar Vidyapith at Puri	1393.5		1393.50	A.C.S. & G.C.I.S.	1994	Needs repair
Education	Gadadhar High School at Puri	1146		1146.00	R.C.C.	1915	Needs repair
Education	Bholanath Vidyapith at Puri	696.75		696.75	R.C.C.	1975	Needs repair
Education	L.I.C.Colony M.E.School at Puri	334.24		334.24	R.C.C.	1973	Needs repair
Education	M.V.Girls High School at Puri	430.94		430.94	R.C.C.	1931	Needs repair
Education	Sukhalata Girls High School at Puri	418.04		418.04	R.C.C.	1965	Needs repair
Education	D.I.of School at Puri	249.24		249.24	R.C.C.	1935	Needs repair
Education	C.I.of School at Puri	748.48		748.48	R.C.C.	1967	Needs repair and renovation
Education	J.B.R. Govt. High School at Nimapara	1234.36		1234.36	A.C.S. & G.C.I.S.	1928	Flooring & plastering some doors
Education	J.B.R. Govt. High School at Nimapara	61.50	55.74	117.24	R.C.C.	1998	- do-
Education	Govt Boys High School at Nimapara	1322.90		1322.90	A.C.S. & G.C.I.S.	1928	- do-
Education	Govt Boys High School at Nimapara	566.62	127.83	694.45	R.C.C.	1928	- do-
Education	S.T. School Building at Nimapara	615.46		615.46	A.C.S. & G.C.I.S.	1930	- do-
Education	Kitchen & Dining Hall of S.T. School at	69.67		69.67	R.C.C.	2005	- do-
Education	Govt High School at Konark	561.56		561.56	R.C.C.	1988	- do-
Education	Govt High School at Konark ( Double Storied)		126.8	126.80	R.C.C.		- do-
Education	Hostel Building at Konark			0.00	R.C.C.		- do-
Education	Sanitry Complex of Govt. High Schoolat		68.74	68.74	R.C.C.	2009	
Education	Extension of class room cum hostel building		185.8	185.80	R.C.C.	2009	
Education	Sevasram School at Konark	277.49		277.49	R.C.C.	1967	Flooring & plastering some doors
Education	Extension of class room	76.27		76.27	R.C.C.	1992	
Education	Hostel & Two nos Addl. Class room	222.5884		222.59	A.C.S. & G.C.I.S.		
Education	Sevasram School at Konark ( Sarbasikhya		119.37	119.37	R.C.C.	2009	
Education	Hostel Building of Sevasram School ( Double		234.66	234.66	R.C.C.		
Rajbhawan	Rajbhawan at Puri	2859.02		2859.02	R.C.C.	1913	Needs repair
Tourism	Youth Hostel at Puri	1506.72		1506.72	R.C.C.	1977	Needs repair
Agriculture	Office Cum go-down of Project Demonstration Office at Nimapara	110.36		110.36	A.C.S. & G.C.I.S.	1940	Flooring & plastering some doors & window damaged & Copound wall partly damaged
Agriculture	Storage go down at Nimapara	155.24		155.24	A.C.S. & G.C.I.S.	1940	- do-
Agriculture	D.D.A office building	1029.00		1029.00	R.C.C.	1979	
Agriculture	Compound wall of DDA				Comp. wall	1982	
Agriculture	D.A.O office at Puri.	2043.80		2043.80	R.C.C.	1955	
Agriculture	D.A.O Rest shed	82.68		82.68	R.C.C.	1955	
Agriculture	Compound wall of D.A.O				Comp. wall	1955	
Agriculture	Driver of D.A.O jeep garrage of D.A.O	41.80		41.80	R.C.C.	1955	
Agriculture	1st floor over existing D.A.O office at Puri.	346.33		346.33	R.C.C.	2009	
Industries	D.I.C office at Puri	562.04		562.04	R.C.C.	1960	G.F to be renovate
Industries	I..T.I office building with subsideary building at Puri	3089.02		3089.02	R.C.C.	1950	



Non Residential building of Puri (R&B) Division, Puri							
Deptt. Name	Name of building	Plinth area in Sqm.	Addition/ alteration plinth area in Sqm.	Total plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Industries	Hostel and guest room of I.T.I at Puri	624.38		624.38	R.C.C.	1960	
Industries	Work shop building at Puri	129.74		129.74	R.C.C.	1960	
Industries	One class room at Puri	61.18		61.18	R.C.C.	1990	
Industries	Work shop building for T.V and Radio at Puri	99.50		99.5	R.C.C.	1992	
Industries	Extension to D.I.C 1st floor building at Puri	123.13		123.13	R.C.C.	1992	
Industries	Work shop building of I.T.I at Puri.(1st floor) at Puri		201.46	201.46	R.C.C.	2009	
Industries	Cycle shed for I.T.I at Puri		111.48	111.48	R.C.C.	2008	
Cooperative	A.R.C.S office building at Puri	734.09		734.09	R.C.C.	1960	
Cooperative	C.C.B unit at Puri	199.83		199.83	R.C.C.	1981	
Cooperative	Composite office building to coporative Dept.( Three storied) at Puri	1210.39		1210.39	R.C.C.	1992	
Soil conservation	Soil conservation office building at Puri	272.20		272.20	R.C.C.	1960	Needs to be renovate
Soil conservation	Range office at Puri	63.75		63.75	A.C.S. & G.C.I.S.	1970	
Letislative	O.L.A.Guest house at Puri	316.57		316.57	R.C.C.	2009	
Letislative	O.L.A.Out house at Puri	103.30		103.30	R.C.C.	2007	
Letislative	Compound wall				Comp. wall	2006	
Works	Nirman Nivas at Puri (One block 3 storied)	1701.46		1701.46	R.C.C.	1984	
Works	C.Wall of Nirman Nivas at Puri (One block 3				Comp. wall		
Works	Old I.B.at Puri (one block single storied)	201.00		201.00	R.C.C.	1904	
Works	C.Wall of Old I.B.at Puri (one block single storied)				Comp. wall		
Works	Annex at Puri (one block single storied)	108.00		108.00	R.C.C.	1904	
Works	Out house inside old I.B.at Puri	86.00		86.00	R.C.C.	1950	
Works	C.Wall of Out house inside old I.B.at Puri				Comp. wall		
Works	Puri (R&B) Sub-division Office at Puri (one	186.00		186.00	R.C.C.	1981	
Works	C.Wall of Puri (R&B) Sub-division Office at Puri				Comp. wall		
Works	P.W.D.Storage godown No.III at Puri	81.00		81.00	R.C.C.	1981	
Works	C.Wall of P.W.D.Storage godown No.III at Puri				Comp. wall		
Works	P.W.D.Storage godown No.II at Puri	88.00		88.00	A.C.S. & G.C.I.S.	1980	
Works	P.W.D.Storage godown No.I at Puri	124.00		124.00	A.C.S. & G.C.I.S.	1984	
Works	C.Wall of P.W.D.Storage godown No.I at Puri				Comp. wall		
Works	Section Office at Sakhigopal	93.60		93.60	A.C.S. & G.C.I.S.		Good
Works	P.W.D. I.B.at Sakhigopal	142.30		142.30	A.C.S. & G.C.I.S.		Good
Works	P.W.D.Storage godown at Sakhigopal	93.60		93.60	R.C.C.		Good
Works	P.W.D. I.B.at Satapada	98.70		98.70	R.C.C.	1974	Unusable condition
Works	Choukidarshed of P.W.D.I.B.at Satapada	25.10		25.10	R.C.C.	1974	Unusable condition
Works	Kitchen of Choukidarshed & Pump house of	15.20		15.20	A.C.S. & G.C.I.S.	1974	Unusable condition
Works	Kitchen cum store of P.W.D.I.B.at Satapada	36.14		36.14	A.C.S. & G.C.I.S.	1974	Unusable condition
Works	C.Wall of P.W.D.I.B.at Satapada				Comp. wall		
Works	P.W.D.I.B.at Brahmagiri	126.64		126.64	R.C.C.	1974	Unusable condition
Works	Section Office at Brahmagiri	45.54		45.54	R.C.C.	1974	Unusable condition

Non Residential building of Puri (R&B) Division, Puri							
Deptt. Name	Name of building	Plinth area in Sqm.	Addition/ alteration plinth area in Sqm.	Total plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Works	Sectional store adjacent to Office at	77.96		77.96	A.C.S. & G.C.I.S.	1974	Unusable condition
Works	Sectional store (Medical side) at Brahmagiri	77.96		77.96	R.C.C.	1974	Unusable condition
Works	Sectional store (East side) at Brahmagiri	166.30		166.30	A.C.S. & G.C.I.S.	1974	Unusable condition
Works	Extension room of section Office at Brahmagiri	4.50		4.50	R.C.C.	2008	Good
Works	C.Wall of P.W.D.I.B.at Brahmagiri				Comp. wall		
Works	Gangshed at Panaspada	72.34		72.34	A.C.S. & G.C.I.S.	1974	Unusable condition
Works	Gangshed at Barakudi	72.34		72.34	R.C.C.	1974	Damaged condition
Works	Gangshed at Dahikhia	72.34		72.34	R.C.C.	1974	Damaged condition
Works	G.E.D.Office at Puri	265.12		265.12	R.C.C.	1950	Needs repair and renovation
Works	Store no 3 converted to division office	269.19		269.19	R.C.C.	1972	
Works	Latrine block	18.58		18.58	A.C.S. & G.C.I.S.	1972	
Works	M.D.B subdivision, Puri.	310.10		310.10	A.C.S. & G.C.I.S.	1906	
Works	Compound wall of sub division office				Comp. wall	1906	
Works	Motor garage no 3	46.45		46.45	A.C.S. & G.C.I.S.	1970	
Works	PWD store no 5	84.35		84.35	A.C.S. & G.C.I.S.		
Works	Compound wall of Division office				Comp. wall	1972	
Works	PWD store no 2	63.26		63.26	A.C.S. & G.C.I.S.	1968	
Works	Garage and work shop	93.83		93.83	A.C.S. & G.C.I.S.	1971	
Works	Record room and computer room of Division office (1st floor)		350.00	350.00	R.C.C.	2008	
Works	PWD Sub division Office at Nimapara	149.57		149.57	R.C.C.	1973	Roof leaking some doors & window damaged & Compound wall partly damaged
Works	PWD IB at Nimapara	202.02		202.02	A.C.S. & G.C.I.S.	1940	- do-
Works	Storage godown at Nimapara	395.00		395.00	A.C.S. & G.C.I.S.	1979	- do-
Works	P.W.D. IB at Konark ( Old)	666.00		666.00	R.C.C.	1940	- do-
Works	Extension of PWD IB at Konark	1142.67		1142.67	R.C.C.	1982	- do-
Works	PWD Section office at Konark	68.20		68.20	R.C.C.	1982	- do-
Works	PWD IB at Gop	122.01		122.01	A.C.S. & G.C.I.S.	1960	- do-
Works	PWD Section office at Gop	74.60		74.60	R.C.C.	1982	- do-
Works	Storage godown at Gop	184.35		184.35	A.C.S. & G.C.I.S.	1981	AC Sheet Completely blown awy in Super Cyclone during 1999. All Wooden items with Masonry work damaged

Non Residential building of Puri (R&B) Division, Puri							
Deptt. Name	Name of building	Plinth area in Sqm.	Addition/ alteration plinth area in Sqm.	Total plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Works	PWD Section Office at Kakatpur	280.00		280.00	A.C.S. & G.C.I.S.		- do-
Works	P.W.D.IB at Astaranga	250.00		250.00	A.C.S. & G.C.I.S.		- do-
Works	Extension PWD IB at Astaranga		147.00	147.00	R.C.C.		
Excise	District Excise Office at Puri	360.01		360.01	R.C.C.	1986	Repair required
Excise	Ganja Gola at Puri	172.00		172.00	R.C.C.	1987	Repair required
Excise	Excise Barrack at Puri	260.00		260.00	A.C.S. & G.C.I.S.	1951	Repair required
Law	New Civil Court building at Puri ( Double storied)	1972.54		1972.54	R.C.C.	1971	Repair required
Law	Old Civil Court building at Puri	216.73		216.73	R.C.C.	1923	Roof to be changed
Law	Old Civil witness building at Puri	85.83		85.83	R.C.C.	1927	Damaged
Law	Sessions Court at Puri	25.64		25.64	A.C.S. & G.C.I.S.	1920	Renovation required
Law	Sessions Judge Court at Puri	215.43		215.43	R.C.C.	1927	Roof to be changed
Law	New Civil Court compound wall at Puri				Comp. wall	1920	
Law	Separate building of court Malkhana at Puri	118.26		118.26	R.C.C.	1984	Renovation required
Law	First Track Court building at Puri	232.25		232.25	R.C.C.	2004	Good
Law	Civil court Guest House at Puri ( Double storied)	459.92		459.92	R.C.C.	1984	Good
Law	Court Building at Nimapara	446.00		446.00	R.C.C.	1943	- do-
Static	Statistical office at Puri ( Double storied)	464.50		464.50	R.C.C.	1976	Good
NCC	N.C.C.Office at Puri ( Double storied)	1114.80		1114.80	R.C.C.	1976	Repair required
Public relation	Information Centre at Lions Gate, Puri	44.59		44.59	R.C.C.	1984	Repair required
Public relation	Town Hall at Puri	368.06		368.06	Tile Terraced	1930	Renovation required
Public relation	D.P.R.Office at Puri	120		120.00	R.C.C.	1960	Raise of plinth & sand filling required
Health	2Nos. P.G.Hostel of G.A.M.at Puri	102.00		102.00	R.C.C.	1982	Repair required
Health	Pharmasist shed of G.A.M.at Puri	79.24		79.24	R.C.C.	1982	Repair required
Health	Outdoor block of G.A.M.at Puri	2962.20	267.07	3229.27	Tile Terraced	1955	Repair required
Health	Indoor block of G.A.M.at Puri	322.08		322.08	Tile Terraced	1955	Repair required
Health	Anatomy block of G.A.M.at Puri	174		174	Tile Terraced	1956	Repair required
Health	Pathology block of G.A.M.at Puri	120.77		120.77	Tile Terraced	1956	Repair required
Health	Lecturer theater room of G.A.M.at Puri	353.02		353.02	Tile Terraced	1956	Repair required
Health	Lecturer Hall of G.A.M.at Puri	148.64		148.64	R.C.C.	2007	Repair required
Health	Physiology Hall of G.A.M.at Puri	297.28		297.28	R.C.C.	2007	Repair required
Health	Rasashastra & Drabyaguna lab. of G.A.M.at	120.39		120.39	R.C.C.	2007	Repair required
Health	Pharmasist block of G.A.M.at Puri	120.39		120.39	A.C.S. & G.C.I.S.	1956	Renovation required
Health	Lecturers theatre building of G.A.M.at Puri	171.86		171.86	A.C.S. & G.C.I.S.	1956	Renovation required
Health	Library Block of G.A.M.at Puri	108.97		108.97	R.C.C.	1956	Renovation required

Non Residential building of Puri (R&B) Division, Puri							
Deptt. Name	Name of building	Plinth area in Sqm.	Addition/ alteration plinth area in Sqm.	Total plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Health	C.Wall				Comp. wall	1956	
Health	Gents Hostel No.1 of G.A.M.at Puri ( Double	456.04		456.04	R.C.C.	1960	Repair required
Health	Clinical building & departmental building 3	1373.70		1373.70	R.C.C.	2008	Good
Health	Gents Hostel No.2 of G.A.M.at Puri	372.99		372.99	R.C.C.	1960	Repair required
Health	Ladies Hostel No.3 of G.A.M.at Puri	311.49		311.49	R.C.C.	1960	Repair required
Health	Ladies Hostel of G.A.M.at Puri	287.99		287.99	R.C.C.	1955	Repair required
Health	Laboratory of G.A.M.at Puri	57.5		57.50	R.C.C.	1955	Repair required
Health	Indoorword 4 block of I.D.H.at Puri	1694.49		1694.49	R.C.C.	1945	Repair required
Health	X-ray building of I.D.H.at Puri	187.28		187.28	R.C.C.	2009	Good
Health	Superintendent office of I.D.H.at Puri	189.51		189.51	Tile Terraced	1958	Repair required
Health	T.B.Clinic of I.D.H.at Puri	187.28		187.28	R.C.C.	2006	Good
Health	Cottage of X-ray block of I.D.H.at Puri	125.41		125.41	Tile Terraced	1945	Repair required
Health	Ambulance garage of I.D.H.at Puri	45.98		45.98	A.C.S. & G.C.I.S.	1956	Required renovation
Health	Kitchen Block of I.D.H.at Puri	86.21		86.21	A.C.S. & G.C.I.S.	1955	Renovation required
Health	Duty room of I.D.H.at Puri	24.06		24.06	Tile Terraced	1955	Renovation required
Health	Watchman shed of I.D.H.at Puri	57.96		57.96	Tile Terraced	1956	Renovation required
Health	Semi pharماسist out door of I.D.H.at Puri	215.52		215.52	Tile Terraced	1956	Renovation required
Health	Dhobi Shed of I.D.H.at Puri	13.93		13.93	Tile Terraced	1967	Renovation required
Health	Generator room of I.D.H.at Puri	7.43		7.43	A.C.S. & G.C.I.S.	1972	Renovation required
Health	Sangha Hall of I.D.H.at Puri	408.76		408.76	A.C.S. & G.C.I.S.	1956	Renovation required
Health	Labour ward of I.D.H.at Puri	178.11		178.11	R.C.C.	1955	Renovation required
Health	C.Wall				Comp. wall		
Health	3Seats of Specialist Chamber in District	99.86		99.86	R.C.C.	1984	Good
Health	Store room in District H.Q.Hospital at Puri	159.28		159.28	R.C.C.	1984	Repair required
Health	Fileria word in District H.Q.Hospital at Puri	180.31		180.31	R.C.C.	1968	Good
Health	Main building of District H.Q.Hospital at Puri	1790.46		1790.46	R.C.C.	1967	Good
Health	X-ray block of District H.Q.Hospital at Puri	243.67		243.67	Tile Terraced	1930	Renovation required
Health	Gynic word of District H.Q.Hospital at Puri	142.97		142.97	Tile Terraced	1930	Good
Health	Female labour word (Double storied) of	589.72		589.72	Tile Terraced	1958	Good
Health	Cottage of District H.Q.Hospital at Puri	147.98		147.98	R.C.C.	1958	Good
Health	C.Wall of District H.Q.Hospital at Puri				Comp. wall	1955	
Health	Kitchen Block of District H.Q.Hospital at Puri	19.13		19.13	Tile Terraced	1958	Repair required
Health	Out door of District H.Q.Hospital at Puri	253.43		253.43	R.C.C.	2000	Good
Health	Latrine block of District H.Q.Hospital at Puri	61.31		61.31	Tile Terraced	1906	Good
Health	Ambulance garage of District H.Q.Hospital at	56.82		56.82	Tile Terraced	1957	Good
Health	Kitchen Block of District H.Q.Hospital at Puri	106.27		106.27	R.C.C.	2007	Good
Health	Sterilization word of District H.Q.Hospital at	131.67		131.67	Tile Terraced	1965	Renovation required
Health	Common C.Wall of District H.Q.Hospital at Puri				Comp. wall	1925	
Health	Fileria Reserch centre of District H.Q.Hospital	209.02		209.02	R.C.C.	1965	Good

Non Residential building of Puri (R&B) Division, Puri							
Deptt. Name	Name of building	Plinth area in Sqm.	Addition/ alteration plinth area in Sqm.	Total plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Health	C.D.M.O. of District H.Q.Hospital at Puri	270.06		270.06	R.C.C.	1928	Good
Health	Family Planning office of District H.Q.Hospital	93.17		93.17	A.C.S. & G.C.I.S.	1965	Repair required
Health	Garage of District H.Q.Hospital at Puri	24.89		24.89	R.C.C.	1965	Repair required
Health	A.N.M.Hostel of District H.Q.Hospital at Puri	924.44		924.44	A.C.S. & G.C.I.S.	1962	Repair required
Health	A.N.M.Hostel ( Double Storied) of District	126.34		126.34	R.C.C.	2008	Good
Health	C.Wall of District H.Q.Hospital at Puri				Comp. wall	1962	
Health	A.N.M.training school of District H.Q.Hospital	100.00		100.00	R.C.C.	1994	Repair required
Health	Rest Shed and auto ward of District	100.00		100.00	R.C.C.	1994	Repair required
Health	Postmortum centre and corridor of District	85.31		85.31	R.C.C.	2006	Repair required
Health	Administrative block & subsidiary building of	1789.21		1789.21	R.C.C.	2006	Repair required
Health	Kamaladevi Maternity hospital at Puri	545.78		545.78	R.C.C.	1955	Good
Health	C.Wall of Kamaladevi Maternity hospital at Puri				Comp. wall		
Health	Area Hospital Building at Nimapara ( Old)	250.04	99.35	349.39	R.C.C.	1979	- do-
Health	- do- -do-	217.60		217.60	A.C.S. & G.C.I.S.	1940	- do-
Health	Area Hospital Building at Nimapara (New)	1002.50		1002.50	R.C.C.	2002	- do-
Health	- do- (Kit & Store)	47.85		47.85	R.C.C.	2002	- do-
Health	Govt. Dispensary at Konark	119.56		119.56	R.C.C.	1975	- do-
Health	Six Beded ward at Konark	109.62		109.62	R.C.C.	1983	- do-
Health	Cholera ward at Konark	34.09		34.09	R.C.C.	1980	Flooring & plastering some doors & window damaged & Copound wall partly damaged
Health	M.C.W.C Building at Konark	97.75		97.75	R.C.C.	1976	- do-
Health	2 nos Special Cabin at Konark		60.385	60.385	R.C.C.	2009	
Finance	District Treasury office at Puri	1002.57	133.77	1136.34	R.C.C.	1983	Good
Finance	Pensioner's room in treasury office at Puri	46.00		46.00	A.C.S. & G.C.I.S.	2004	Good
Finance	1st floor(Left wing) of C.T.O office at Puri.		176.35	176.35	R.C.C.	2009	
Finance	Lavatory block of C.T.O office at Puri	6.00		6.00	R.C.C.	1997	
Finance	Guest house of C.T.O office at Puri	204.38		204.38	R.C.C.	2008	
Finance	Commercial Tax office building at Puri	678.17		678.17	R.C.C.	1955	
Finance	Garage of C.T Dept. at Puri	55.74		55.74	R.C.C.	1955	
Finance	Extension of C.T .O office at Puri	70.00		70.00	R.C.C.	1998	
Finance	Compound wall of C.T.O at Puri				Comp. wall	1982	
Finance	Inspection room at Puri	80.82		80.82	R.C.C.	1998	
Finance	Sub Tresury Office & Barrak at Nimapara	315.86		315.86	R.C.C.	1996	Roof leaking some doors & window damaged & Copound wall partly damaged
Fishery	Asst. Director fishery office building	115.20		115.20	R.C.C.	1952	
Fishery	Store Room	70.60		70.60	R.C.C.	1952	

Non Residential building of Puri (R&B) Division, Puri							
Deptt. Name	Name of building	Plinth area in Sqm.	Addition/ alteration plinth area in Sqm.	Total plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
General Administrative	Vigilance Squared Office at Puri	150.07		150.07	R.C.C.	1985	Repair required
Tranport	R.T.A.Office at Puri	468.40		468.40	R.C.C.	1990	Good
S & Y.S.	District Sports complex at Puri	747.84		747.84	A.C.S. & G.C.I.S.	1995	
S & Y.S.	Multisim of sports complex	125.41		125.41	A.C.S. & G.C.I.S.	1995	
S & Y.S.	Compound Wall of Jagannth stadium				Comp. wall	1999	
A.H & V.S.	Veterinary Hospital with subsidiary buildings at Puri	1500.95		1500.95	R.C.C.	1960	Renovation required
A.H & V.S.	C.D.V.O.Office at Puri	975.45		975.45	R.C.C.	1965	Good
A.H & V.S.	Veterenary Despensary Building at Nimapara	163.26		163.26	R.C.C.	1978	- do-
A.H & V.S.	Veterenary Despensary Building ( I.C.D.) General at Nimapara	80.00		80.00	A.C.S. & G.C.I.S.	1978	
Home	Police Station Building at Nimapara	430.12		430.12	A.C.S. & G.C.I.S.	1940	- do-
Home	Police Circle Inspector Office at Nimapara	107.76		107.76	R.C.C.	1940	Flooring & plastering some doors & window damaged & Copound wall partly damaged
Home	One Piegon Hall at Nimapara	22.76		22.76	A.C.S. & G.C.I.S.	1940	- do-
Home	Police Station Building at Konark	116.40		116.40	R.C.C.	1983	- do-
Home	Out post Building at Konark	34.37		34.37	A.C.S. & G.C.I.S.	1966	- do-
Home	District Police Office at Puri	1660.00		1660.00	R.C.C.	1945	Renovation required
Home	Kumbharpara P.S.Building at Puri	627.07		627.07	R.C.C.	2002	Good
Home	Town P.S.Building at Puri	1780.65		1780.65	R.C.C.	1967	Repair required
Home	Baselisahi Outpost building at Puri	968.36		968.36	Tile Terraced	1907	Repair required
Home	Workshop store (No.1) in R.P.Line at Puri	166.38		166.38	A.C.S. & G.C.I.S.	1923	Repair required
Home	5Nos. Motor garage in R.P.Line at Puri	303.87		303.87	A.C.S. & G.C.I.S.	1956	Repair required
Home	Flag stand outpost used as Police ministerial	165		165.00	R.C.C.	1950	Repair required
Home	Pegon left in R.P.Line at Puri	250.08		250.08	A.C.S. & G.C.I.S.	1945	Repair required
Home	One constable Dinning Hall in R.P.Line at Puri	125.41		125.41	A.C.S. & G.C.I.S.	1945	Repair required
Home	Two Kitchens for constable in R.P.Line at Puri	58.74		58.74	A.C.S. & G.C.I.S.	1965	Repair required
Home	Wireless Office (used as reader office) in	50.16		50.16	Tile Terraced	1960	Repair required
Home	Police Hospital inside R.P.Line at Puri	588.98		588.98	A.C.S. & G.C.I.S.	1965	Repair required
Home	Ration store inside R.P.Line at Puri	132.35		132.35	R.C.C.	1960	Repair required
Home	6Nos. Motor garage in R.P.Line at Puri.	278.70		278.70	R.C.C.	1970	Repair required
Home	One shed for Fire station used as Motor	40.34		40.34	A.C.S. & G.C.I.S.	1970	Repair required
Home	Workshop store (No.2) in R.P.Line at Puri	165.56		165.56	A.C.S. & G.C.I.S.	1945	Repair required

Non Residential building of Puri (R&B) Division, Puri							
Deptt. Name	Name of building	Plinth area in Sqm.	Addition/ alteration plinth area in Sqm.	Total plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Home	Latrine Block in R.P.Line at Puri	95.88		95.88	R.C.C.	2002	Repair required
Home	2Nos. Garage in R.P.line at Puri	118.44		118.44	A.C.S. & G.C.I.S.	1965	Repair required
Home	Reserve Police Office with subsidiary building	286.65		286.65	R.C.C.	1952	Repair required
Home	4Nos. Police barrake in R.P.line at Puri	308.87		308.87	A.C.S. & G.C.I.S.	1966	Repair required
Home	4Nos. Police barrake in R.P.line at Puri	1761.38		1761.38	A.C.S. & G.C.I.S.	1929	Repair required
Home	Distiliary barrake in R.P.line at Puri	286.15		286.15	R.C.C.	1936	Repair required
Home	A.P.R. barrake in R.P.line at Puri	285		285.00	R.C.C.	1952	Repair required
Home	Govt. property store in R.P.line at Puri	65.78		65.78	A.C.S. & G.C.I.S.	1954	Repair required
Home	Police canleen hall at Puri	130.06		130.06	A.C.S. & G.C.I.S.	1954	Repair required
Home	Petrol godaw store in R.P.line at Puri	13.93		13.93	Tile Terraced	1950	Repair required
Home	Building material store converted to O/O the	255.83		255.83	R.C.C.	1950	Repair required
Home	Constable barrack usede as drama pendal	139.35		139.35	A.C.S. & G.C.I.S.	1953	Repair required
Home	Nabakalebar barrack No.5 used as reserve	139.35		139.35	R.C.C.	1999	Good
Home	A.P.R.Barrack used as Police High School in	453.92		453.92	R.C.C.	1952	Repair required
Home	Dog Squard in R.P.line at Puri	47.78		47.78	R.C.C.	1953	Repair required
Home	Dog Squard Office in R.P.line at Puri	74.32		74.32	R.C.C.	1960	Repair required
Home	Family welfare centre in R.P.line at Puri	130.06		130.06	R.C.C.	1990	Repair required
Home	Abakash Barrack near Police Abakash at Puri	53.97		53.97	R.C.C.	1990	Repair required
Home	One Police Counter ( Magazine) in R.P.line at	320.00		320.00	Tile Terraced	1970	Repair required
Home	C.Wall of R.P.Line at Puri				Comp. wall		
Home	Fire station building with Guest garage &	796.95		796.95	R.C.C.	1941	Repair required
Home	Sadar Police station building at Puri	139.35		139.35	R.C.C.	1970	Repair required
Home	Kumbharpara Out Post at Puri	162.38		162.38	R.C.C.	2006	Repair required
Home	Harchandi sahi Out Post at Puri	162.38		162.38	R.C.C.	2006	Renovation required
Home	Sea Beach Police Station at Puri	288.73		288.73	R.C.C.	2006	Good
Home	D.F.S.L.Building at Puri	221.00		221.00	R.C.C.	1995	Good
Home	Sagregation wall of district Jail at Puri	97.17		97.17	Comp. wall	1982	Repair required
Home	Hospital (New +Old)of district Jail at Puri	172.32		172.32	R.C.C.	1982	Repair required
Home	Word No.3 of district Jail at Puri	120.77		120.77	Tile Terraced	1931	Repair required
Home	New word of district Jail at Puri	106.83		106.83	Tile Terraced	1971	Repair required
Home	Hospital (raw materials) of district Jail at Puri	37.16		37.16	A.C.S. & G.C.I.S.	1931	Repair required
Home	Leprosy word of district Jail at Puri	18.11		18.11	A.C.S. & G.C.I.S.	1920	Repair required
Home	Office Room of district Jail at Puri	438.85		438.85	R.C.C.	1923	Repair required
Home	Word No.6 of district Jail at Puri	202.89		202.89	A.C.S. & G.C.I.S.	1923	Repair required
Home	Word No.7 of district Jail at Puri	148.17		148.17	Tile Terraced	1920	Repair required
Home	Word No.8 of district Jail at Puri	114.45		114.45	A.C.S. & G.C.I.S.	1920	Repair required
Home	Cell of district Jail at Puri	46.07		46.07	R.C.C.	1906	Repair required
Home	General Kitchen of district Jail at Puri	88.53		88.53	Tile Terraced	1906	Repair required
Home	Division Kitchen of district Jail at Puri	16.15		16.15	Tile Terraced	1906	Repair required

Non Residential building of Puri (R&B) Division, Puri							
Deptt. Name	Name of building	Plinth area in Sqm.	Addition/ alteration plinth area in Sqm.	Total plinth area in Sqm.	Type of Roof	Year of construction	Present condition of the building
Home	Word No.3 & 4of district Jail at Puri	172.32		172.32	Tile Terraced	1927	Repair required
Home	Ration Godown of district Jail at Puri	33.53		33.53	Tile Terraced	1927	Repair required
Home	Word No.2 of district Jail at Puri	344.65		344.65	Tile Terraced	1927	Repair required
Home	Hospital Kitchen of district Jail at Puri	13.47		13.47	R.C.C.	1906	Repair required
Home	Dhai shed of district Jail at Puri	71.34		71.34	R.C.C.	1923	Repair required
Home	Work shop No.I & II of district Jail at Puri	148.82		148.82	A.C.S. & G.C.I.S.	1923	Repair required
Home	C.Wall of word No.6,7& 8 of district Jail at Puri				Comp. wall		
Home	C.Wall (Latrine) of district Jail at Puri				Comp. wall		
Home	Common Latrine of district Jail at Puri	5.57		5.57	Tile Terraced	1980	Renovation required
Home	C.Wall of Leprosy word district Jail at Puri				Comp. wall		
Home	Cowshed of district Jail at Puri	98.10		98.10	A.C.S. & G.C.I.S.	1918	Renovation required
Home	Kitchen block of worder in district Jail at Puri	88.44		88.44	Tile Terraced	1918	Good